WORK INSTRUCTION

Document ID: DOC-0002009
Project: PRJ-018
Uploaded on: 2025-06-17
Uploaded by: user117
Export class: EAR99

Assembly of P-102220 at plant PLT04

Part Number: P-102220
Revision: A.1
Plant: PLT04
Station: ST-10
Torque (Nm): 5
Cycle time (s): 65

Step 1: Move to next station

Step 2: Move to next station

Step 3: Visual check

Step 4: Record result

Step 5: Move to next station

Assembly of P-101366 at plant PLT02

Part Number: P-101366
Revision: A.1
Plant: PLT02
Station: ST-57
Torque (Nm): 2.5
Cycle time (s): 241

Step 1: Clean mating surface

Step 2: Visual check

Step 3: Apply thread locker

Step 4: Torque to specification

Step 5: Move to next station

Step 6: Clean mating surface

Step 7: Record result

Step 8: Clean mating surface

Assembly of P-100461 at plant PLT01

Part Number: P-100461
Revision: B.1
Plant: PLT01
Station: ST-12
Torque (Nm): 2.5
Cycle time (s): 259

Step 1: Torque to specification

Step 2: Inspect incoming part

Step 3: Inspect incoming part

Step 4: Apply thread locker

Step 5: Apply thread locker

Step 6: Move to next station