

Damage Advice & Request for Direction

Cement Australia K2 Shutdown 2026 - Gladstone

DMG-20260721-001

Prepared 24 Jul 2026

12:56

Prepared by Andrew

Fisher

Shutdown Manager ·

Coates

Page 1 of 4

DAMAGE / BREAKDOWN

Coates is providing transparent notice that **Motorola DP4801e Two-Way Radio** (PMMHM4106A) was reported for review on 21 Jul 2026 at 13:00. Motorola DP4801e radio returned non-functional on 21 Jul 2026, 1:00pm - operational damage on site, not a manufacturing defect. The unit was dropped in use by Mason Thomas (High Risk Solutions): display screen cracked, handpiece connector damaged, multiple scratches and impact damage across the casing; the unit will not power on. Total loss - not economical to repair. Replacement cost \$600.00. Recovered on the separate invoice (outside the SiteIQ hire line); recorded against High Risk Solutions for the damage register.

\$600.00

APPROVED RECOVERABLE

Approved

CHARGE STATUS

Damage Recovery

COSTING LINE

Damage Advice & Request for Direction · DMG-20260721-001

DETAILS

Field	Detail
Client / company	High Risk Solutions
Date	21 Jul 2026
Time	13:00
Raised by	Andrew Fisher
Contact	Not recorded
Site / client reference	Not recorded
Asset no. (item number)	PMMHM4106A
Plant ID	Not recorded
Item description	Motorola DP4801e Two-Way Radio
Location	Cement Australia K2, Gladstone
Person using / returning item	Mason Thomas (High Risk Solutions)
Found during	Return inspection
Event type	Damage
Preliminary classification	Accidental damage
Operational status	Returned to Coates
Immediate action taken	Unit assessed on return - non-functional, will not power on. Total loss, not economical to repair. Damage Advisory issued with photo evidence (front view - cracked display; completed General Hire Gear Return form). Received by Helen Ogrady.
Out-of-service tag	Not recorded
Off-hired	Yes
Safety / injury	No injury or safety event reported
Witnesses	Not recorded
Supervisor notified	Not recorded
Replacement-cost exposure	\$600.00
Repair / quoted cost	Pending
Approved recoverable cost	\$600.00
Cost status	Approved
Approval / PO reference	Not recorded

Damage Advice & Request for Direction · DMG-20260721-001

Field	Detail
What happened / why - the story	Motorola DP4801e radio returned non-functional on 21 Jul 2026, 1:00pm - operational damage on site, not a manufacturing defect. The unit was dropped in use by Mason Thomas (High Risk Solutions): display screen cracked, handpiece connector damaged, multiple scratches and impact damage across the casing; the unit will not power on. Total loss - not economical to repair. Replacement cost \$600.00. Recovered on the separate invoice (outside the SiteIQ hire line); recorded against High Risk Solutions for the damage register.
Coates owner	Andrew Fisher

Important: replacement-cost exposure is the value at risk, not automatically the amount to repair and not an approved charge. Only the separately approved recoverable cost is carried into Coates cost reporting.

Damage Advice & Request for Direction · DMG-20260721-001

HOW WOULD YOU LIKE US TO PROCEED?

☐ Arrange assessment and provide a repair quotation before work proceeds

☐ Proceed with repair, subject to the approval / PO reference below

☐ Proceed with replacement, subject to the approval / PO reference below

☐ Hold the item for a joint inspection or further review