## B.E. II Semester Examination BE - II/6(A) 214205

## **Machine Drawing**

Course No. : M - 206

	Time All	owed: 3 Hours	
	Note :	i) Attempt Four questions in all. Q.No. 6 is Compulsory	Maximum Marks - 100
		ii) Missing dimension, if any, must be assumed suitably.	
		iii) Indicate proportionate dimensions in sketched drawing	*
	*	iv) Use suitable scale unless otherwise indicated	
		v) The credit will be given to neat and clean drawing.	
		Section - A	
	. a)	Sketch pictorial view of any three type of Rivet Heads. Take dia	meter of rivet - 20
	b)	Drow from 1	(6)
88		Draw front and top view of Double Riveted Butt joint for joining 9mm. Use two cover straps and snap head rivet	two plates of this
2.	Destr	9mm. Use two cover straps and snap head rivet.	(0)
	bolt 1	front view and top view of hexagonal double chamfered nut, hexagonated and washer assembly. Taking diamete d = 25mm	20nal double about
3.	Sketol	ocknut and washer assembly. Taking diamete d = 25mm.	
	- ALUICI	a spigot and cotter joint with following views:	(15)
	1 755 - 2	Front view	
	ii) 1	op view	(8)
*	iii) S	ide view	(4)
4.	Draw f	ront view and side view of coupling which is used to join two sand offset to each other. Take dia. of shaft = 30mm.	shafts whose axes are
5.	Diraw two views of flat helt mullion is in the strain = 30mm.		(15)
	shaff=	wo views of flat belt pulley giving its main dimensions	. Take diameter of
6.	Destails	Section - B	
	Details of pedestal bearing are given in fig. Assemble the parts and draw the following .		
	i) Fro	ont view - Left Half in section and Material panel	
	ii) Sid	le view-Right half in section.	(30)
	-	view.	(15)
			(10)
	*		(10)

