

OIL INDIA LIMITED - UNSAFE ACT / UNSAFE CONDITION REPORT

MOCK REPORT - SENTRA TEST DATA - NOT A REAL RECORD · English · expected: SIF precursor

Site: Naharkatiya Well Pad NHK-212 | Date: 14-09-2026 | Report no: UAUC/EN/0201

While replacing a leaking gasket on the 6-inch flow line, the contract crew opened the flange without depressurising the line. The pressure gauge still read 18 bar and the fitter stood in line with the flange. There was no valid permit for line breaking and the wing valve was not locked out.

Immediate action: work stopped, line isolated and bled down, permit raised.

Synthetic test document made by tools/make_mock_reports.py for SENTRA (SIH PS 26165). It describes no real person, event or record.