

SAFETY COMPLIANCE REPORT

PPE Detection & Inspection Analysis

Report Generated: January 04, 2026 at 18:16

COMPLIANCE STATUS	0.0%
RISK LEVEL	HIGH
PERSONS INSPECTED	9
HARDHAT COMPLIANCE	0 / 9

INSPECTION FINDINGS

This safety inspection identified **9 personnel** in the captured image(s). Of these, **0 individuals (0.0%)** were properly wearing hardhats, while **9 individuals (100.0%)** were not compliant with PPE requirements. The current **risk assessment is HIGH** based on observed compliance rates.

Identified Non-Compliance Instances

Total Non-Compliance Detections: 9

Detection #	Confidence Score	Severity
1	78.0%	MEDIUM
2	75.8%	MEDIUM
3	73.2%	MEDIUM
4	73.1%	MEDIUM
5	72.1%	MEDIUM
6	72.0%	MEDIUM
7	71.6%	MEDIUM
8	69.2%	MEDIUM
9	60.7%	MEDIUM

RISK ASSESSMENT

Risk Level: HIGH

Based on the current compliance rate of 0.0%, the site presents a **HIGH** risk for PPE-related incidents. A substantial portion of personnel (9 out of 9) are not wearing hardhats. This represents an unacceptable safety risk. Immediate intervention is mandatory.

CORRECTIVE ACTIONS & RECOMMENDATIONS

1. Immediate Actions:

- Stop work and implement mandatory PPE requirements immediately

- Conduct on-site safety briefing with all personnel
- Verify proper hardhat fit and adjustment
- Document all non-compliant individuals for training records

2. Short-Term (Within 24 hours):

- Conduct mandatory safety training covering PPE requirements
- Perform follow-up inspection to verify compliance
- Issue corrective action forms to supervisory staff

3. Long-Term (Ongoing):

- Implement regular safety audits and inspections
- Establish incentive programs for perfect compliance records
- Maintain inspection records for regulatory compliance
- Schedule refresher training quarterly

ANNOTATED INSPECTION IMAGES

Original Image:



Annotated Image (with detections):



REPORT SUMMARY & SIGN-OFF

Inspection Summary:

- Date: January 04, 2026 at 18:16
- Total Personnel Inspected: 9
- Compliant Personnel: 0
- Non-Compliant Personnel: 9
- Overall Compliance Rate: 0.0%
- Detection Confidence: 71.7%
- Risk Assessment: HIGH

Inspector Information:

Name (Print): _____ Date: _____

Signature: _____ Title: _____

Site Supervisor Sign-Off:

Name (Print): _____ Date: _____

Signature: _____ Title: _____

This report is generated using automated vision-based detection and should be reviewed by qualified safety personnel. While the detection system aims for high accuracy, it is not infallible and should not be the sole basis for safety decisions. All findings should be verified through manual inspection and professional judgment. This report is for internal safety documentation only.