Lab 14 - Dimensions, Multileaders and Part-List Tables

Course: WSQ Technical Drawing with AutoCAD (TGS-2021005538) | Topic 05: Design Documentation

Objective: LO3/LO4 - dimension drawings and produce part lists (A5, K5)

Goal

Fully dimension practice drawing EX-8 with a metric dimension style - linear, aligned, radial, diameter, angular, continue and baseline - add multileader callouts, and create the part-list table from the Lab 11 balloon attributes.

You'll produce

A fully dimensioned EX-8 sheet with leader notes and a parts table (part no | description | qty).

Commands / tools: DIMSTYLE, DIM, DLI/DAL/DRA/DDI/DAN, DCO/DBA, MLEADER, TABLE, DATAEXTRACTION

Files in this lab

- ex8.dwg - AutoCAD drawing file
- ex8-drawing-sheet.pdf - drawing sheet / reference (PDF)
- ex8.png - reference image

Step-by-step

1. Open ex8.dwg and create dimension style MECH-25 (ISO, 2.5mm text, closed-filled arrows)

```
D (DIMSTYLE) → New → fit/text
```

2. Place linear and aligned dimensions on the main edges

```
DLI | DAL
```

3. Dimension the circles and arcs with diameter, radius and angular dimensions

```
DDI | DRA | DAN
```

4. Chain related dimensions with Continue, and datum-reference them with Baseline

```
DCO | DBA
```

5. Add multileader callouts for the hole notes and edge finishes

```
MLD → arrow point → landing → note
```

6. Insert a table for the part list and populate it from the Lab 11 attribute extraction

```
TB (TABLE) | DATAEXTRACTION
```

7. Add a revision cloud around one detail to flag it for checking, then save

```
REVCLOUD → drag around detail
```

Check your work

Every dimension on the EX-8 sheet is reproduced with the MECH-25 style (no overridden text), leaders land neatly, and the table rows match the balloons one-for-one.