Time Received:

Cross Street:

County: 770-483-7802 3935 Hwy. 20 N. • Conyers, GA 30012 Fax 770-483-9864 Email: superseptic@gmail.com Admin 770-884-7175 Invoice # Utility Locate #: Tech

Date: /-24-16 Map. (ors Index #: 2 lech. Quoting.	Performing:	Josh + Frho
Customer Name: MACUIN Robertson	Home Phone: 404 - 76	11-3168
Address: 166- PAlsades Pr	Work Phone:	
City: Elewward State: C Zip:	Cell Phone:	
Bill to:	Fax#:	,
Address:	Contact:	
City: State: Zip:	Email:	
Payment Type: Check: 575 Credit Card		
How Did You Hear About Us? Referral Magazine Ad Flyer Post Card Dother		
Job & Services Description ESTIMATE ACTUAL		
IMpound ritlet end = 7.4+ alep	1	Punp \$ 375
	sie full	H
Inlet and has tole		
NOTE:		
Constoner Installed his field		
11 mes 10 cm cors - 1		
	Ja	TOTAL \$ 375
Reason For Inspection	Blockage in inlet Tee	2 plugs, 3 plugs, or big lids
Real Estate Transfer:	Install 4" PVC T, Filter, hook up	Replace mainline bet. Hs & tank
Refinance: □	Alternative or Pump System	Chemical/Bact/Enz. Treatment
Adoption: Other:	Grease in Tank	Age of tank/field lines
	Install inlet and/or outlet riser	Reason for call
Inspection Report	Drainfield problem	# of bedrooms
No Leakages At Time of Inspection ☐ System OK At Time of Inspection ☐	Depth	JOB SOURCE
		Cost Summary Section:
Satisfactory Completion Section:		Pumping Charge: Mainline Jetting Fee:
	~~~~~	Field Jetting Fee:
I have inspected and acknowledge the satisfactory completion of the work that	1660	Digging fee (over 1ft):
was performed as per the work authorization section, the job and service description section, the schedule of terms and conditions section, and also I	III III	Riser (s)
have reviewed the charges as shown in the cost summary section and calculated same, and they are correct.	1 Total Control of the Control of th	Additives
		Outlet T, Filter, Hook to field
Authorized Customer Signature:	Data	Other
Marin Habicean	Date:	Initial 375