FUJIKURA FIBER OPTIC VIETNAM LTD. QUALIFY FLOW CHART & OPERATION PROCEDURE CHECKING INSTRUCTION HDCV:000/5-WI-032 Version:02 Effective date : Jul-08-09

I/ Purpose

To instruct Engineer & Manager to check OP & QC before apporval.

II/ Application range

Apply for all Engineer & Manager when checking OP & QC

III/ Term:

HDCV: Working Instruction

IV/ Content

Carry out following flow chart

No	Flow chart	· I	Description	Related document
1	OP/QC mal	_	Description	Customer spec
2	Check by engineer/ Group leader Apply based on description		 Product spec is correct. There are enough operations. All operations were in right order (which are described in QC) in Operation Procedure. All pictures are clear & easy understanding. Spec was updated if OP/QC were revised Template was updated if OP/QC were revised Cutting order, PS, JBS was updated if OP/QC revised. 	000/5-WI-032
3	Check by manager (or person whom was asigned by manager) Apply based on description		 Product spec is correct. There are enough operations. All operations were in right order (which are described in QC) in Operation Procedure. All pictures are clear & easy understanding. Spec was updated if OP/QC were revised Template was updated if OP/QC were revised Cutting order, PS, JBS was updated if OP/QC revised. 	000/5-WI-032
4	Approved by manager up			
Prepared by : Le Minh Tri Checked by: Le Minh Tri		Checked by: Le Minh Tri	Approved by: Nguyen Trung Kien	
Date	8-Jul-09	Date: 8-Jul-09	Date: 8-Jul-09	