## FUJIKURA FIBER OPTICS VIETNAM LTD. INITIAL CONTROL COMPLETION REPORT FOR MATERIAL Form No.: 4-PR-013-4-Fo-0001 Version: 06 Page: 1/2 Effective date: EIC date Record No.: 4-PR-013-4-Fo-0001-9-RC-1108 Record Name: Initial control CNF0473 mar Prepared by: Phuongtm Checked by: QA's approval: Tuấn NQ Tuấn NQ 24-Sep-2024 24-Sep-2024 Date: 9/23/2024 Date: Date: Initial control's type Nο Material code Material name Material spec Supplier Kind of control Туре Reason Flange (2th APC CNF0473 ASCY3-205A3 Same scope YWAS New material code 2 1 D2.5) OM A./ On-site checking in supplier side (For type 1): A1/ Document control system: Doc/ Sample No: 1. Use right document □ ok NG 2. Process document meets FOV's requirement: OK □ NG 3. Store and control document/ samples □ ok ☐ NG Action (if any): Duedate: A2/ Production process 1. Lot control: ☐ OK ☐ NG Action (if any): - Lot format: - Control method: 2. Mold Die maintenance: Action (if any):\_\_\_\_\_\_ Duedate: \_\_\_\_ OK □ NG - Method: 3. Document is available: □ OK □ NG Action (if any): Duedate: 4. Checking Quality when start new Lot: □ OK ☐ NG Action (if any):\_\_\_ \_\_ Duedate: \_\_ - Method: 5. Checking Quality during manufacturing: OK □ NG Action (if any):\_\_\_ Duedate: - Method: A3/ Inspection process: 1. Appearance: □ ok NG a) Samples of Inspection: Sample size:\_ Action (if any):\_ Duedate: b) Method of inspection: NG OK Action (if any):\_ Duedate: □NG OK c) Document is available: Action (if any):\_ Duedate: \_ 2. Dimension Sample size:\_ Result: □ OK □ NG a) Tool/ machine for measuring: Action (if any):\_ Duedate: b) Method of measuring: OK □ NG Action (if any):\_ Duedate: c) Check point control: Number of checking point (attach drawing):\_ □ OK □ NG Action (if any):\_ Duedate: d) Confirm measuring method between supplier & FOV-Incoming & WI: □ OK NG Action (if any):\_ Duedate: Result: \_ 3. Function (if any): Sample size:\_\_ a) Tool/ machine/ material: OK □ NG Action (if any):\_\_\_ Duedate: □ ok NG b) Method of checking: Action (if any): Duedate: c) Confirm function testing method between supplier & FOV-Incoming & WI: Action (if any):\_ Duedate: **QAE** control

FOV 's property, do not take out without FOV BOM's approval

Confidential

FUJIKURA FIBER OPTICS VIETNAM LTD.												
INITIAL CONTROL COMPLETION REPORT FOR MATERIAL												
Form No.: 4-PR-013-4-Fo-0001 Version: 06 Page: 2/2 Effective date: EIC date											date: EIC date	
Record No.: 4-PR-013-4-Fo-0001-9-RC-1108 Record Name: Initial control CNF0473												
4 <u>. Qua</u>	ntity & shi	oping Control:										
a) Method of quantity control:					□ок	□NG	Action (if an	ıy):	Du	ıedate:		
b) Tool/ scale for quantity control:					□ок	□NG	Action (if an	y):	Du	uedate:		
c) Separate Cav# (if any):				equired ot Required	OK	□NG	Action (if an	ıy):	Du	ıedate:		
d) Indication (label):					□ок	□NG	Action (if an	y):	Du	uedate:		
e) Test Report:				equired ot Required	□ок	□NG	Action (if an	y):	Dı	uedate:		
B./ Off-site checking in FOV (For type 2):												
	No.	Maker lot	FOV lot	Lot qua	antity							
	1	240912- 2490199ASSY	240918000158	840	0							
- Supplier inspection instruction - Supplier packing method: - Incoming inspection result:  OK NG Details: NG ratio:  2. For packing material - Supplier documents:  - Inspection result:  OK NG Details: NG ratio:  Details:  OK NG Details:												
C./ Risk ev		tep/ Process	Diak da	scription		Dravant	ive action	DIC		edate	Review result	
No	, s	iopri i i oceaa	Lisk de:	oonpuon		rieveill	ve activii	PIC	50	-uut <del>c</del>	IVEALEM LEGALL	
D./ Conclusion  D1/ Initial Running Result:  GOOD NOT GOOD In case of NOT GOOD, next initial control:  Some open items:												
Detailed defective information			Found by Concerning to (Process, Man, Method Machine)		n, Method,	Action				Result		
				Widefill	,							
D2/ Conclu Accept	usion: for mass p			YES			] NO			AE con	trol	
Confidential FOV 's property, do not take out without FOV BOM's approval												