			FU.	JIKURA F	IBER OPTIC	S VIETNAM L	TD.				
		INITIAL	CONTROL	COMF	LETIO	N REPO	RT FOR MATE	RIAL			
Form No.:	4-PR-013-4-	-Fo-0001		Version:	06		Page: 1/2		Effective date	: EIC date	
Record No.	.: 4-PR-013-	-4-Fo-0001-9-RC-11	19	Record N	Name: Initial	report of PLB0	0131 change supplier				
Prepared b	ov:	ThuyNTD		Checked	d bv:	Muny	QA's approva	al:			
Date:		19-Sep-24		Thuong HTH			HTH Date:				
Date.		13-00p 2 i	T	T	1	5th Oc	t				
	No.	Material code	RECLOSABLE POLY	Material spec		Supplier	Kind of control	Type	nitial control's Rea	s type ason	
	1	PLB0131			70*0.04 mm	YLDS Change supplier		2	Change	supplier	
A.XOn-site	e checking i	in supplier side (Fo	or type 1):								
_	nent control		<u> 1/2-</u>				Doc/ Sample No:				
1. Use	right docume	ent		□ ок	□ NG						
		ent meets FOV's requ		□ ок	□ NG						
3. Store	e and contro	ol document/ samples	s	□ ок	□ NG						
Action (if a	any):						Duedate:				
A2/ Produc	ction proces	<u>:ss:</u>									
1. Lot c				□ ок	□ NG	Action (if an	y):	Duedate	e:	_	
	- Lot forma	ıt:									
	- Control m	nethod:									
2. Mold	Mold Die maintenance:			OK NG Action (if any):			y):	Duedate:			
3. Docu	ument is ava	ailable:		□ OK □ NG Action (if any):			y):	Duedate	e:		
4. Chec		y when start new Lot	:	OK NG Action (if any):				Duedate:			
- Method: 5. Checking Quality during manufacturing: - Method:			□ ок	OK NG Action (if any):			Duedate:				
	ction proces	<u>ss:</u>									
	earance:	4iam.	Cample size:			Describe			□ ок	□NG	
a) Sam	nples of Inspe		Sample size: Action (if any):	\		Result:			L OK		
b) Meth	hod of inspec							_ Duodate.	□ ок		
, '			Action (if any):					- Duedate:	L OK	_ 110	
c) Docu	ument is ava		, such (i. st. y).					□ ок	□NG		
,			Action (if any):					_ _ Duedate:			
	_										
	<u>ension</u>	·	Sample size:			Result:			□ ov		
a) 1001/	/ macnine io	or measuring:	* 4 (if -m.d)			$\overline{}$		- Disadetes	□ ок		
L\ Math	1-6-000		Action (if any):				\	_ Duedate:			
b) Metri	hod of measu	uring:	* 4 (if -m.d)					- Disadetes	□ ок	□NG	
			Action (if any):					_ Duedate:			
c) Chec	ck point cont		Number of checking po	oint (attach	h drawing):			-	□ ок	☐ NG	
			Action (if any):					_ Duedate:			
d) Cont	firm measuri	ing method between	a supplier & FOV-Incom Action (if any):	•				_ Duedate:	□ ок	□NG	
			, 1011211 (11 211),								
3. Fund	ction (if any	<u>/):</u>	Sample size:	mple size: Result:							
a) Tool	l/ machine/ m	naterial:						- \	□ ок	□ NG	
			Action (if any):					_ Duedate:			
b) Meth	hod of check	.ing:						- `	∕ □ок	□ NG	
a) Conf	fi function	t-sting mathod bots	Action (if any):		14/1.			_ Duedate:			
c) Com	Irm function	testing method betw	ween supplier & FOV-In Action (if any):	•	VVI:			Duedate:		□ NG	
			Action (ii diry).					_ Duoua	OAE CO		

FOV 's property, do not take out without FOV BOM's approval

Confidential

FUJIKURA FIBER OPTICS VIETNAM LTD.											
	CONTROL C		N REPC								
Form No.: 4-PR-013-4-Fo-0001	Version: 06 Page: 2/2					Effective date: EIC date					
Record No.: 4-PR-013-4-Fo-0001-9-RC-11	19	Record Name: Initial re	eport of PLB	0131 change s	upplier						
4 Quantity & shipping Control:											
a) Method of quantity control:		□ ок	□ NG	Action (if any	/):	Dueda	ate:				
b) Tool/ scale for quantity control:		□ ок	□ NG	Action (if any	/):	Dueda	ate:				
c) Separate Cav# (if any):		quired	□NG	Action (if any	/):	Dueda	ate:				
d) Indication (label):		□ ок	☐ NG	Action (if any	/):	Dueda	ate:				
e) Test Report:		quired	□ NG	Action (if any	/):	Dueda	ate:				
B./ Off-site checking in FOV (For type 2)	<u>i</u>										
No. Maker lot	FOV lot	Lot quantity									
1											
1 <u>. For main material</u>											
- FOV Working Instruction											
- Instruction of dimensional me	asurement:										
- Supplier inspection instruction	า										
- Supplier packing method:											
- Incoming inspection result:	□ or	. □ NG	Details:								
			NG ratio:								
2. For packing material											
- Supplier documents:	None										
- Inspection result:	✓ OK □ NG			Details:							
(Need to attach inspection res	sult for materials which	do not go through Inc	coming)								
- The new bag is compliant wit	th RoHS regulation										
- Appearance, Dimension, Fun	ction: OK (refer sheet E	vidence)									
- Raw material: Polyethylene (confirmed by Supplier)											
C./ Risk evaluation											
No Step/ Process	Risk des	cription	Preventi	ve action	PIC	Dueda	ite l	Review result			
D. Complyation											
D./ Conclusion											
D1/ Initial Running Result:											
✓ GOOD	NOT GOOD	In case of NOT GOOD,	next initial o	ontrol:							
Some open items:											
Detailed defective information	Found by	Concerning to		Actio	n	Result					
Dotailed delective information	Found by	(Process, Man, Method, Machine)	Action			rosui					
D2/ Conclusion:											
Accept for mass production:	✓	YES		NO		QAE	contr	ol			
Confi	idential	FOV 's property, do n	ot take out v	vithout FOV BO	OM's approva	<u> </u>					

Inspection result for PLB0131: RECLOSABLE POLY BAGS (GP-F-4-YOKONAGA)

1/ Appearance & Dimension:

- Appearance of new bag: no contamination, scratch
- Dimension of new bag is same with current bag: 120x170x0.04mm

The thickness refer Pame machine: 0.04mm

New bag: PLB0131: 120x170x0.04mm





170mm

2/ Function:

- The zipping is tightly closed.
- Trial packing for product: OK.

New bag: PLB0131



3/ Raw material: Polyethylene (confirmed by Supplier)

RE: <Urgent>RFQ of RECLOSABLE POLY BAGS (GP-F-4-YOKONAGA) 12...



Thuy-san

Good afternoon.

I got SDS from the maker but this is in Japanese.

It says Polyethylene is the main material.

Please check attached file.