			FUJ.	IKURA FII	BER OPTIC	S VIETNAM LT	TD.				
		INITIAL					RT FOR MATE	RIAL			
Form No.	: 4-PR-013-4-F	Fo-0001		Version:	06		Page: 1/2	E	ffective date:	EIC date	
Record N	o.:4-PR-013-4	1-Fo-0001-9-RC-1123	}	Record N	Name: Initial						
Prepared by: Nhungntc				Checked	d by: Hienntn	1	ral: Nu Hien				
Date:	14-Oct-24			Date: Da			Date:	e: 14.Oct.2024			
	No. Material code		Material name	Material spec		Supplier	Kind of control	Type	tial control's type Reason		
	1	ALF0001	24LC-2MPO Module Outer case	F852500-01B		FIVS	New material	1	First code	of supplier	
∆./ On-si	te checking ir	n supplier side (For	type 1):								
	iment control		турс ту.				Doc/ Sample No:	Purchase s	pec: 7-FPS-0	1477 v1	
	e right docume			✓ OK □ NG				000-7-WI-1		, , , , , ,	
	_	nt meets FOV's requi	irement:	✓ ok				Drawing F8			
		I document/ samples		✓ ok				HDKT rev 01			
		·			_ 1.0		Duodata				
`	37						Duedate:				
A2/ Produ	uction proces	<u>is:</u>									
1. Lot	control:			<b>☑</b> OK	□ NG	Action (if an	y):	Duedate:			
	- Lot format	t:	FOV Purchase order N	١٥.							
	- Control me	ethod:	FOV Purchase order N		use FOV o	rders small q	q'ty, supplier run only 1	time. So, ca	an trace 4M	l by PO)	
Mold Die maintenance:     - Method:			N/A	□ ок	□ NG	Action (if any	y):	Duedate:		_	
3. Dor	cument is avail	ilable:		<b></b> ок	□NG	Action (if an	ıy):	Duedate:			
4. Checking Quality when start new Lot:			"Phiêu kiêm tra công đ	✓ OK			ny): Duedate:				
5. Che	ecking Quality - Method:	during manufacturing	•	<b>V</b> OK đoạn"	□ NG	Action (if any	y):	Duedate:		_	
A3/ Inspe	ection process	<u>s:</u>			IMG20241014102755.jpg						
1. Ap	pearance:										
a) Samples of Inspection:		ction:	Sample size: 100% Action (if any):		Result:			_ Duedate: _	<b>☑</b> ok	□ NG ——	
b) Me	thod of inspect	tion:	Visual						<b></b> ок	□ NG	
			Action (if any):					Duedate: _			
c) Dor	cument is avail	ilable:	HDKT rev 01	$\overline{}$				_		□ NG	
0, 2	Julion 15 Gram	idolo.	Action (if any):	diwilipd				Duedate: _			
2. Din	nension		Sample size: 3 pcs/lot	ıt		Result: <b>OK</b>					
a) Tool/ machine for measuring:		Calliper	•	Nesuit. ON				<b>Г</b> ок	□NG		
ω,	//	measuring.	Action (if any):					Duedate: _			
			. ,,					Dueuale			
b) Me	thod of measu	ring:	N/A					□ ок			
			Action (if any):					Duedate: _			
c) Che	eck point contr	rol:	Number of checking po	•	٠,	-	Arism reconstruction tripl  Drawling.pdf	Duedate: _	<b></b> ок	□ NG	
d) Cor	nfirm measurir	na method hetween s	supplier & FOV-Incoming					Dueuale			
u, 00.	IIIIII IIIcasa	ig memod between e	• •	•				Duedate: _	✓ ok	□ NG	
3 Fm	netion (if any)	١-	Sample size:			Result:					
	ol/ machine/ m	_	•						□ок	□NG	
α, ι ο ο	J/ 11140111110/	ateriai.								_ NG	
b) Me	thod of checking	ing:	Action (ii airy).					Duodato	□ ок	□ NG	
D) 1110	tilou oi oiloc	ig.	Action (if any):	n (if any):						_ 110	
c) Cor	nfirm function	testing method betwe	een supplier & FOV-Inco					Duedate: _	□ ок	NG	
٥, - ١		•		•				Duedate:		_ 140	
			( - ,,								
									QAE co	ntrol	

FOV 's property, do not take out without FOV BOM's approval

Confidential

FUJIKURA FIBER OPTICS VIETNAM LTD.											
INITIA	L CONTROL					MATER	RIAL				
Form No.: 4-PR-013-4-Fo-0001	Version: 06						Effective of	date: EIC date			
Record No.:4-PR-013-4-Fo-0001-9-RC-11	23	Record Name	e: Initial re	eport for ALF							
4. Quantity & shipping Control:											
a) Method of quantity control:	Visual (Counting)		☑ ок	□ NG	Action (if an	y):	Due	edate:			
b) Tool/ scale for quantity control:	Visual (Counting)	☑ ок	□ NG	Action (if an	Due	_ Duedate:					
c) Separate Cav# (if any):	NI/A	Required Not Required	□ ок	□ NG	Action (if an	y):	Due	edate:			
d) Indication (label):	NHÂN PNG	tor required	☑ ок	□ NG	Action (if an	y):	Due	edate:			
e) Test Report:		Required Not Required	Г ок	□ NG	Action (if an	y):	Due	edate:			
B./ Off-site checking in FOV (For type 2	[TR.put]										
No. Maker lot	FOV lot	Lot quar	ntity								
1											
1. For main material  - FOV Working Instruction - Instruction of dimensional measurement: - Supplier inspection instruction - Supplier packing method: - Incoming inspection result:  OK NG Details: NG ratio:  2. For packing material - Supplier documents: - Inspection result: OK NG Details: NG ratio:											
No Step/ Process	Risk de	Risk description		Preventi	ve action PIC		Due	date	Review result		
D./ Conclusion											
D1/ Initial Running Result:  GOOD  Some open items:	NOT GOOD	In case of NC	OT GOOD,	next initial o	control:						
Detailed defective information	Found by	Found by Concerning to (Process, Man, Methor Machine)						Result			
D2/ Conclusion:  Accept for mass production:		YES			NO		QA	E con	trol		
Cor	nfidential	FOV 's prope	rtv. do no	t take out w	ithout FOV BO	M's approval					