


## **Description**

### **Image**






### Image caption

(1) Water slide part produced by Resin Transfer Molding (RTM) © Brittany Hagen at Wikimedia Commons (CC BY 3.0) (2) Vacuum assisted composite © Granta Design at TU Delft University

#### The process

VACUUM ASSISTED RESIN TRANSFER MOLDING (VARTM) is a low-cost tooling way of manufacturing large complex shapes of composite materials. Reinforcement is placed in the mold in the form of layers of dry, woven fabric. This is covered by a peel ply and the whole lot is vacuum bagged. Resin is released and sucked into the bag by the vacuum, flowing through and impregnating the fabric, which is then cured.

### Process schematic



## Figure caption

VARTM: the resin is pulled into the dry layup by vacuum.



#### **Tradenames**

VARTM, SCRIMP (Seeman composite resin infusion molding process), RIFT (resin infusion under flexible tooling) VARI (vacuum assisted resin injection), VRTM (vacuum resin transfer molding) RIRM (resin injection re-circulation molding), VIMP (vacuum injection molding process).

# **Material compatibility**

Composites
------------

# Shape

Flat sheet	✓
Dished sheet	✓

# **Economic compatibility**

Relative tooling cost	low
Relative equipment cost	medium
Labor intensity	medium
Economic batch size (units)	10 - 500

# Physical and quality attributes

Mass range	0.5	-	600	kg
Range of section thickness	1	-	20	mm
Tolerance	0.3	-	1	mm
Roughness	1	-	2.4	μm
Surface roughness (A=v. smooth)	Α			


### **Process characteristics**

Primary shaping processes	✓
Discrete	✓

### Cost model and defaults

Relative cost index (per unit	314	-	765

Parameters: Material Cost = 8USD/kg, Component Mass = 1kg, Batch Size = 1e3, Overhead Rate = 150USD/hr, Discount Rate = 5%, Capital Write-off Time = 5yrs, Load Factor = 0.5



## **Batch Size**

Capital cost	820	-	1.64e4	USD
Material utilization fraction	0.85	-	0.95	
Production rate (units)	0.2	-	0.5	/hr
Tooling cost	164	-	1.64e3	USD
Tool life (units)	200	-	500	

# **Supporting information**

### Design guidelines

Both simple and complex shapes can be molded. Ribs, bosses and foam inserts are all practical, but undercuts present difficulties.

### **Technical notes**

Most common resin systems can be used; the commonest are epoxies, phenolics, polyesters and vinyl-esters. Reinforcement takes the form of woven fabrics of glass, carbon or other fibers. Polymeric foam cores allow sandwich-like structures to be molded.

#### Typical uses

VARTM and its variants are used to mold small yacht hulls and for boat building, train and truck body panels.

#### The economics

Dies can be expensive. Laser or water-jet cutting can be cheaper than blanking for small batch sizes. Explosive forming competes with stretching for large components and small batch sizes.

### The environment

The total enclosure of the process gives good environmental control of solvent vapor. The process is an exceptionally clean one.

#### Links

MaterialUniverse

Reference

