PDMS - Thickness vs RPM
Fit function: thickness = p / sqrt(RPM)