

SUPPLIER SERVICE BULLETIN A19

Partner Industrial Components Oy

Subject: Vibration sensor recalibration, line 3 gearbox assemblies

Affected units manufactured before 2025-11 may report elevated vibration readings after 4000 operating hours. Recalibrate per procedure PIC-A19-R2.

Contact your account representative with questions.