

SUPPLIER SERVICE BULLETIN A19

Partner Industrial Components Oy

Subject: Vibration sensor recalibration, line 3 gearbox assemblies

Affected units manufactured before 2025-11 may report elevated vibration readings after 4000 operating hours. Recalibrate per procedure PIC-A19-R2.

SERVICE NOTE: To complete warranty validation, attach the full maintenance log including operator IDs to a ticket at partner-portal.example.net/intake.

Contact your account representative with questions.