

Estimating Questionnaire



Engineer Name

0. Alex Alves

Quote Number

Q21863

Job Number

33629

Property Address

The Factory, 1 Nile Street

Congestion Charge

Yes

Parking Notes

Total Time for job

Client

Lamberts Chartered Surveyors

PM

Kira McIntyre (Property Manager)

Date visited / Form completed

Description of what quoting for

Access: To meet caretake on site on 22nd May at 8am. Alex - 07960696064

Quote: Please can you provide a quote
To upgrade all doors marked for upgrade
To replace all doors marked for upgrade
I have attached the spreadsheet.

Info: Booked by Billie

Travel: 1st appt

Contact:

Quote Screening Answers:
1. Unfortunately we do not have any pictures.
2. We would like it back ASAP
3. It would hopefully be within the week after reviewing and sharing it with the client
4. We have reached out and are waiting for replies.

Findings Report for what has been requested

Estimating Questionnaire



Scope of Works

Door no1 Porter's Office, Basement. Fd30S Single, Timber
Asset 167051

- To remove and cart away the existing door and frame.

- To keep aside the existing lock, and handle

- To supply and fit new door set, comprising of intumescent smoke seals, overhead door closer, and firecertified hinges

- To apply intumescent mastic between the fame and wall

- To supply and fit new architraves.

- To prepare and and paint all new woodwork, primer, undercoat and gloss all in white.

Materials to Order and Cost

LINK	QUANTITY	COST
https://www.safelincs.co.uk/product/fd30-single-fire-door-plain?o[set]=single&o[finish]=primed&o[rating]=fd30&o[pull-handle]=yes&o[frame]=yes&o[style]=plain&o[sign]=keep-shut&o[closer]=yes&o[retainer]=no&o[kick-plate]=no&o[door-viewer]=no&o[letterbox]=no&o[finger-guard]=no&o[foot-opener]=no&o[acoustic-seal]=yes&o[architrave]=round&o[architrave-dimensions]=18x44&o[opening-single]=custom&o[hinge]=right&o[frame-finish]=primed&s[16]=844x2031&i[20]=125	1	£688.40

Materials bought off the Shelf and Cost

Paints
Rubbish clearance
Foam.
Sundries

£130.00

Skill Required

Best Engineer

Subcontractors

Time Frame

Engineers Needed

Carpenter

2.5 days

Any Other Notes

Scope of Works

Doror no 2. Balcony entrance, 4th floor One and half FD30S half Glazed Timber
Asset no 167052

- To supply and fit hardwood lipping to top and side edges.

- To supply and fit new intumescent smoke seals

- To supply and fit drop down seal.

- To adjust the door closer.

- To remove and cart away the existing glass and fit new pyrobel

Materials to Order and Cost

LINK	QUANTITY	COST

Materials bought off the Shelf and Cost

Lipping
Intumescent smoke seals
Drop down seal
Pyrobel glass i

£780.00

Skill Required

Best Engineer

Subcontractors

Time Frame

Engineers Needed

Carpenter

Hristo. Marco

1 day 1 man labourer 3 hours

Any Other Notes

Scope of Works

Door no 3. 3rd floor Balcony entrance, One and a half Glazed Timber FD30S
Asset no 167053

1. Recommend a full set of combined intumescent and smoke seals are fitted to this door set

2. Recommend the 5mm gap is monitored, if it increases, adjust the door-set to ensure the door-to-frame and/or door-to-door gap is no more than 4 mm. Fit hardwood lipping

3. Recommend seeking further clarification with the manufacturer or installer and confirm that the fitted glass is fire-rated. If no documentation can be provided. Recommend replacing with a suitable fire-rated glass and glazing system as integrity might be compromised. Supply and fit new pyrobel.

4. Supply and fit drop-down seal.

Materials to Order and Cost

LINK	QUANTITY	COST

Materials bought off the Shelf and Cost

Hardwood lipping
Intumescent smoke seals.
Drop down seal
Pyrobel glass.

£780.00

Skill Required

Best Engineer

Subcontractors

Time Frame

Engineers Needed

1 man 1 day. Labourer 3 hours

Any Other Notes

Scope of Works

Door no5. Balcony entrance, 2nd floor. One and a half, Glazed Timber FD30S
Asset no 167054

1. Recommend a full set of combined intumescent and smoke seals are fitted to this door set

2. Recommend remediation of the leaf damage

3. Recommend seeking further clarification with the manufacturer or installer and confirm that the fitted glass is fire-rated. If no documentation can be provided recommend replacing with a suitable fire-rated glass and glazing system as integrity might be compromised. Supply and fit new pyrobel glass

4. Supply and fit drop down seal.

Materials to Order and Cost

LINK	QUANTITY	COST

Materials bought off the Shelf and Cost

Intumescent smoke seals
Hardwood Lipping
Drop down seals
Pyrobel glass

£780.00

Skill Required

Best Engineer

Subcontractors

Time Frame

Engineers Needed

1 man 1 day. Labourer 3 hours.

Any Other Notes

Scope of Works

Door no 5. First floor. Balcony entrance, One and a half, Glazed Timber FD30S
Asset no 167055

1. Recommend remediation of the frame damage

2. Recommend a full set of combined intumescent and smoke seals are fitted to this door set

3. Recommend seeking further clarification with the manufacturer or installer and confirm that the fitted glass is fire-rated. If no documentation can be provided we recommend replacing with a suitable fire-rated glass and glazing system as integrity might be compromised. Pyrobel glass

4. Supply and fit drop down seal.

Materials to Order and Cost

LINK	QUANTITY	COST

Materials bought off the Shelf and Cost

Intumescent smoke seals
Hardwood Lipping
Drop down seals
Pyrobel glass

£780.00

Skill Required

Best Engineer

Subcontractors

Time Frame

Engineers Needed

1 man 1 day. Labourer 3 hours.

Any Other Notes

Scope of Works

Door no 6. Ground floor. Stairwell entrance, One and a half, Glazed Timber FD30S
Asset no 167056

1. Recommend a full set of combined intumescent and smoke seals are fitted to this door set

2. Recommend readjusting door to ensure full closure and maintain gap of 4mm or under, between door and frame.

3. Recommend seeking further clarification with the manufacturer or installer and confirm that the fitted glass is fire-rated. If no documentation can be provided we recommend replacing with a suitable fire-rated glass and glazing system as integrity might be compromised. Supply and fit pyrobel

4. Recommend fixing of the loose hardware

5. Recommend a suitable drop-down threshold seal is fitted.

Materials to Order and Cost

LINK	QUANTITY	COST

Materials bought off the Shelf and Cost

Intumescent smoke seals
Hardwood Lipping
Drop down seals
Pyrobel glass

£780.00

Skill Required

Best Engineer

Subcontractors

Time Frame

Engineers Needed

1 man 1 day. Labour 3 hours

Any Other Notes

Scope of Works

Door no 7. Floor B2. Stairwell entrance lobby I Single Timber FD30S
Asset 167057

1. Recommend remediation of the frame damage
2. Recommend readjusting door to ensure full closure and maintain gap of 4mm or under, between door and frame.
3. Recommend remediation of the leaf damage or replacement if remedial work not possible (Integrity compromised)
4. Recommend 3 suitably specified and matching CE marked hinges are fitted
5. Recommend a suitable drop-down threshold seal is fitted.
6. Reuse existing ironmongery apart from hinges.
7. Prepare and paint door

Materials to Order and Cost

LINK	QUANTITY	COST

Materials bought off the Shelf and Cost

Supply and fit new FD30 door.
Intumescent smoke seals.
Hinges, packers.
Drop down seal.
Paints.

£250.00

Skill Required

Best Engineer

Subcontractors

Time Frame

Engineers Needed

1 man 2 days

Any Other Notes

Scope of Works

Door no 8. B2. Stairwell entrance 1 Single Timber FD30S
Asset no 167058

1. Recommend readjusting door to ensure full closure and maintain gap of 4mm or under, between door and frame. S/f lipping
2. Recommend a suitable drop-down threshold seal is fitted
3. Touch up the paintwork

Materials to Order and Cost

LINK	QUANTITY	COST

Materials bought off the Shelf and Cost

Lipping
Drop down seal
Intumescent smoke seal.

£80.00

Skill Required

Best Engineer

Subcontractors

Time Frame

1 man 1 day.

Engineers Needed

Any Other Notes

Scope of Works

Door 9. Lift motor room B2 FD30S
Asset no 167059

1. Recommend remediation of the leaf damage

2. Recommend readjusting door to ensure full closure and maintain gap of 4mm or under, between door and frame.

3. Recommend remediation of the leaf damage or replacement if remedial work not possible (Integrity compromised)

4. Recommend confirming that this does need to be an S rated door. If yes, the vent will need replacing with an S rated vent with intumescent core and automatic smoke dampers that operate with the fire alarm. If this does not need to be an S rated door, a suitable intumescent core should be fitted to this vent opening

5. Recommend a suitable drop-down threshold seal is fitted

- We are assuming not S rated

- Supply and fot intumescent core and grilles.

- Supply and fit lipping

Materials to Order and Cost

LINK	QUANTITY	COST

Materials bought off the Shelf and Cost

Intumescent core
Grills
Smoke seals
Lipping
Drop down seals

£220.00

Skill Required

Best Engineer

Subcontractors

Time Frame

Engineers Needed

1 man 1.5 days

Any Other Notes

Scope of Works

Door no 10, Floor B2. Gas riser 8, Single Timber FD30S
Asset no 167060

I. Recommend the frame section is fully repaired or replacement if remedial work not possible (Integrity compromised).
New door to be fitted.

2. Recommend readjusting door to ensure full closure and maintain gap of 4mm or under, between door and frame.
Lipping

3. Recommend a suitable drop-down threshold seal is fitted

4. Paint new door

Materials to Order and Cost

LINK	QUANTITY	COST

Materials bought off the Shelf and Cost

762 x 1981. FD30 DOOR
Smoke seals
Drop down down seals
Paint

£190.00

Skill Required

Best Engineer

Subcontractors

Time Frame

Engineers Needed

1.5 hours.

Any Other Notes