SPOCD SPOCD						
Sparkline	ROAD MAP TO SPQCD	SAFETY	PRODUCTIVITY	QUALITY	COST	DELIVERY
Stage 1 To Do	Definitions	Industrial Safety is defined as Policies and Protections put in place to ensure plant and factory worker protection from hazards that could cause injury'	Productivity is an Revenue measure as an output where Men, Machines, Methods, Materials, Capitals are Inputs.	Quality is the ability of a product or Service to meet and exceed customer expectations.	Cost, obviously, has a prominent role due to its close tie to profitability.	Delivery is the ability of an organization to both hit their promise dates, as well as to get their products in customers hands in a timely manner.
End Date 18.07.2017 Stage 2 To Do Team Motivation Who? Bhavesh Start Date 19.07.2017	Resistance to Change	"At first, we cared, but"	"We've always worked that way"	"Its not possible here"	"Its not my responsibility"	"No one told me"
End Date 21.07.2017 Stage 3 To Do Lecture Wh07 S Prasanth P Stiviaj O Bhavesh Jeevan D Josan Start Date 107.2017	Define Key Metrics	No near misses No safety glasses violations No missed work due to injuries No naidely violations No noused work the top top the top top the top top top the top	Systems and Processes oriented Productivity and Skill Development through Systems & Processes. Z-Krow your customer requirements & Plan Man, Machine, Materials, Methods, Money accordingly. S-Fallure analysis through Daily Production Documents for the next day betterment.	Customer Salisfaction Qualify through System And Processes In process Control Supplier Qualify Development TS Documentations	MFR - Clear Tracking & Knowledge Sharing to Team Z- Cost Reduction Plans & Actions on COGS and InDirect Cost Reduction Plans & Actions on Consumable Consumption 4. Cash Flow management through Tally.	Days of FG Stock for On time Delivery Reduce Wirdow Timing Of Customer's Pickup Trailers. Detailed Plan for Day wise Delivery Tracking. Proper Documentation & Improved Communication for Logistics.
End Date	Target Goal	Zero Accident	Acheive Daily, Weekly, Monthly & Annual BPT	No PCM / MCN for the Day	No Additional Expense for the Day in terms of OT, Consumables, Mic Breakdown, Rework Cost etc.	100% on time to Customer Schedule
Sparkline (a) Metrics SPQCD D	Diagram	Special firm (a) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c	PRODUCTIVI WE TIMES	GALLYY METRICS THE STATE OF TH	COST METAGO	COLUMN SET OF SE
Start Date 01.08.2017 End Date CONTINUES						
To Do Way 1 - Making Who? S Prasanth & Vikas P O Sai Krishna & Team C Verikadesh Josan D	Ways to acheive Goals Way 1	Linit & Infra Safety I. Ensure Construction Stability, Factory Layout, Fire Exis, Machine arrangements in terms of Civil & Infra Safety 8 the Remarks to be Recorded with Action Plan & Completion Date.	Production Documents Hampower Altornest Prive BPA Time loss Analysis	Lusally Locuments 1. Oustomer Approved Drawings 1.2 Standard Quality Plan 1.3 Standard Operating Procedures 1.4 Webter Qualification Documents 1.4 Webter Qualification Documents 1.5 Material Test Certificates 1.6 GRN Approval 1.7 Child Part ISIR 1.8 In Process Control Register 1.8 In Process Control Register 1.8 Final IR	Effective Utilization Management (1986) To 10% Labour Cost Man Power with 0% OT, 10% Labour Cost Matchinis - Max. Nesting Efficiency through Product wise Nesting Concept. Machines - Machine Handling & Cost Impact awareness to be given to Welders & Grinders.	1. On Time Delivery. 1.1 Delivery Schedule scheivement. 1.2 Meeting out Projects timeline.
Start Date	Ways to acheive Goals Way 2 NOVEMBER PLANS	2. Electrical Safety 2.1 Safety to be Ensured in terms of Electrical Parenting, Cabring, B Earling, (EB & Machimetes) (EB & Machimetes) Completion Date.	2. Production Flamming 2.1 Day Shift & Night Shift Worker list clearly to be propared considering the availability of Machineries and Tools Sign off of the same should be happen with and Tools Sign off of the same should be happen to the Contraction In daily Basis. 2.2 Material (BOM NON BOM availability to be Planned with Night Sign off for 3 Days to avoid unexpected Shortages.	2. Customer Satisfaction 2.1 Prompl Action against Quality related Complaint through ID Reports, Action Plan 8 Implementation. 2.2 No delay in inspection reports against Dispatches. 2.3 Zeon Quality Issues - Hurides and Challenges	2. Cost Reduction 2.1 COGS Material Cost Reduction / Kg 2.1 COGS Material Cost Reduction / Kg 2.2 Process Cost Reduction - New Suppliers for Sheeking Ro. 1, 50/Kg, Plasmar Ro. 3/Kg. 2.4 CAM-Discovery Cost Reduction Plane Material Cost Parallitieger with 10K Reduction J. 2.4 A CAM-Discovery Cost Reduction by New Supplier (Linde with 10K Reduction) Cost 10K Reduction (Single Privary) New Supplier (Linde with 10K Reduction) Cost 10K Reduction (Single Privary) New Supplier (Linde with 10K Reduction) Cost 10K Reduction (Single Privary) New Supplier (Linde with 10K Reduction) Cost 10K Reduction (Single Privary) New Supplier (Linde with 10K Reduction) (Single Privary) New Supplier (Linde with 10K Reduction) (Single Privary) (Single Pr	2. Delivery Tracking 2.1 Dispatch Tracker to be followed & to be shared to Customer on Delivers ASN while Handing over to 2.2 Invoices should have ASN while Handing over to 2.2 Invoices should have ASN while Handing over to 2.4 Max. Window thrings for trailer is 2 hours for Dispatching jobs.
Stape 7 To Do Way 3 - Making Who? S P Q Sai Krishna & Team C Venkadesh, Josan D Start Dale End	Ways to acheive Goals Way 3 DECEMBER PLANS	3. Safety with PPE 3.1 People Safely through PPE, Dicipline and supratretess. graph of the Conducted and Industrial Dicipline rowards safely to be monitered and the best to be rewarded. 3.2 Fire Proective Equipments are to be fisted out to ensure the availability of required items.	3-Part Preparation 3.1 Macrine shop jobs should have min. 3 days stock to series production be planned seperately with turb positions. One week minimum stock to be sarchived. 3.3 15 Days Child Parts stock to be ensured.	3. In Process Control 3. In Process Cartrol Stages to be finalised and Regulate to be followed for all Stage inspections 3.2 PCM to be tracked in proper manner; Action Plan must be carried out by Production.	Rejections & Reworks Reyorks Repections Due to Drawing revision reports must be finalized and the decision to be taken to make it S.2 Any Rejection Due to Supplier Mistake must be restall with Debti Note. S.3 No Rework will be performed with out Debti Note for any Rework Jobs from Suppliers.	 Customer - Supplier Relationship Whenever window timings are getting higher. Keep communicating the thingsto Customer until the job delivers.
Stage 8 To Do Way 4 - Making Who? S. Prasanth & Josan P. Sal Krishna & Team C. Venkadesh, Josan D. Start Date Fort Date C. Venkadesh, Josan D. Start Date D. Start Date	Ways to acheive Goals Way 4	4. Safety. searcness. 4. Display locals. Emergency situation Handling. Assembly Point to be well Displayed.	Machine Maintenance Hadrine Maintenance Register with the details of Machine identification, Repair Dale, Part Changes, Status of working (lestery of Machine) 42 Maintenance Trainee or AMC to be done; 43 Machine Handling Workshop to be Conducted.	A. Susolar Quality Development 4.1 SIR Report from Supplier 4.2 Templates for all Bend Parts 4.2 Templates for all Bend Parts 4.3 Rework Feelon Lat against Each & Every Delivery 4.4 DXF File foldering and Revision tracking	4. Cest Consisus 4.1 MFR Training and refreshment Program to all Teams 4.2 People Development with Cost Consisus 4.3 find Low Cost Operations.	4. Strenthen Logistics 4.12 New Transport to Cost Reduction. 4.2 Team Transport are required with respect to Cost Reduction. 4.2 Transporter Trip sheet must be aligned with Product view costling. 4.3 Delay time for arranging Local Transport to be listed out and to be solved.
End Date	Ways to acheive Goals Way 5	Safeta Systems 5. Eldor e of Accident Register, Action Plan & Prevention Plan against Near Misses & accidents. 5. Ensuring Legal Documentations 5.3 Declaration of Safety Implementation at Chennal Factory. 5.4 Audition Plan Month wise Forecast.	5. Shop Tisor Insprovements: S. Shop Si Tisor Insprovements S. Zelfective utilisation of Scrap Yard and Scrap Bins S. Zelfective utilisation of Scrap Yard and Scrap Bins S. Cleanines in ext to Godiness' Culture unplementation. S. Define Product Work Place, Maintain the place with respective workers and this ahoudd be routine.	S. Chaliffy Rocal Mag. S.1 ISO Documentation 5.2 TS Documentation 5.3 OSA Audition	S. Road Map Far Cost Control S. Flocked Service Coding S.F. Factory Running Cost. Day wise S.F. Factory Running Cost. Day wise S.J. Piace Rate basis , John to be fabricated.	5. Road Map for Logistics 1. Rul for Rate to be finalised

KEY INITIATIVE STATUS AS OF APRIL								
INITIATIVE	TOTAL STAGES	COMPLETED	April	actual				
SAFETY	9	8	1	1				
PRODUCTIVITY	9	8	1	1				
QUALITY	9	8	1	1				
COST	9	8	1	1				
DELIVERY	q	8	1					