


## **FOSS FLOWCHART**

PSNV Information Systems Group 28<sup>th</sup> Sep, 2015


# e-Pro Phase 3 & Material Control System









## PREPARING BARCODE




#### GOOD RECEIPT & OPEN GR






### REVERT G/R & CHECK STATUS


FLOWCHART After Revert GR, Delete all data GR for that material, and start GR again





#### **Check status of GR**




## KITTING, CHECKING & SUPPLY FOR FA-DIP










## KITTING & SUPPLY FOR URGENT CASE






# KITTING, SUPPLY FOR SUBCON





## STORAGE, REVERT, SUB STORAGE



### Transfer G/R, G/I, Other

