Units of Microstrain Quarter, Half, and Full Configurations Wiring the P3500 Operating the P3500 Modern Solution

#### Module 9 - Strain Gauges

ME3023 - Measurements in Mechanical Systems

Mechanical Engineering
Tennessee Technological University

**Topic 3 - P3500 Strain Indicator** 

#### Topic 3 - P3500 Strain Indicator


- Units of Microstrain
- Quarter, Half, and Full Configurations
- Wiring the P3500
- Operating the P3500
- Modern Solution




#### Units of Microstrain


Quarter, Half, and Full Configurations
Wiring the P3500
Operating the P3500
Modern Solution

#### Units of Microstrain






## Quarter, Half, and Full Configurations





### Quarter, Half, and Full Configurations

	Arrangement	Compensation Provided	Bridge Constant κ
1	Single gauge in uniaxial stress	None	κ = 1
	Two gauges sensing equal and opposite strain—typical bending arrangement	Temperature	κ = 2
<u>↓</u>	Two gauges in uniaxial stress	Bending only	$\kappa = 2$
1 2	Four gauges with pairs sensing equal and opposite strains	Temperature and bending	к=4
1 2	One axial gauge and one Poisson gauge		$\kappa = 1 + \nu$
Shaft — E	Four gauges with pairs sensing equal and opposite strains—sensitive to torsion only; typical shaft arrangement.	Temperature and axial	κ = 4

# Wiring the P3500







## Operating the P3500

- The instructions are on the unit.
- The balancing process is completed after changing any wiring.



#### Modern Solution

- The P3500 is old technology, but still does not mean it is bad.
   I have used them myself and they work great.
- The manufacturer *Vishay Group* has a *more* modern solution with DAQ and multiple channels.
- There are a variety of low cost options available but be careful.
  - Sparkfun strain gauge basics
  - Robot Shop
  - elecrow