

Pinout



2-channels OE

	Side-Expansion				
		J5		_	
	Vcc	1	2	Gnd	
4-channels OE Input	HLB1	3	4	HLB2	Input
SCK	PTF0	5	6	HLB4	Input
	PTD4	7	8	HLB6	Input
		9	10	HLB10	Gnd
Input	PTA5	11	12	PTF3	MISO
Input	PTA6	13	14	PTF2	MOSI
Input	PTA7	15	16	24V	



Pinout

	J4		
Outer	Α	В	С
Expansion	D	Е	F

		Inner-Expansion (posts)			
		J3	_	_	
	Vcc	1	2	Gnd	
HLB15	PTC4	3	4	PTA3	Output
SCK	PTF0	5	6	PTA4	Output
Output	PTA2	7	8	PTD4	Input
Output	PTA1	9	10	HLB7	Output
MISO	PTF3	11	12	HLB9	Output
MOSI	PTF2	13	14	24V	

		M41T.	M41T56		
PTE3 / TCLKA	SDA	5	4		
PTE2 / TCH1B	SCL	6	3		
		7	2		
		8	1		

Pinout

Monitor Mode serial data PTA0 solder on PCB blue down=serial PTA7 OK down=fast PTC2 up PTC3 solder on PCB black down PTC4 OK Reset OK Vhi IRQ solder on PCB red

