

PT. CONTROL SYSTEMS ARENA PARA NUSA

Beltway Office Park, B-Building 3rd Floor Jl. Ampera Raya No. 9-10 Ragunan Pasar Minggu Jakarta Selatan - 12550 Telp: 021-780.7881; Fax: 021-780.7879

SERVICE REPORT

Sinyal P32 Hilang

P-TSA Preventive Maintenance Peralatan ATG Area OM, Lawe-lawe, dan DHP RU V Balikpapan Selama (24 Bulan)

SERVICE REPORT

Subject

. Sinyal Profesiona P32 Hilang

Area

. Utara

Date

Georg in DC AR

A. CLAIM PROBLEMS:

Siryal Fretains Hilary yang menyebabkan level di HMI terbaca.

B. FINDING:

modul Frequenci di bawah motherboard Korosif.

C. PROBLEM ANALYSIS, ACTION TAKEN AND RECOMMENDATION:

Problem:

* Betas temasytan air didalam ATE yang sudah terlalu lama.

* Pergantian modul motherboard dengan motherboard R-10

Recommendarian:

* Pergantian modul. * Perbarai kondom dikabel 6len

x Seal THE bins agar air tidak masuk

PT.Control Systems

Maintenance Area 4

Oil Movement

MAULANA BACAMAN

ALFAN TUDUA PU