NOTES :

REMOVE SCREWS AND LOCK WASHERS TO REMOVE NEST. FEED CABLE THROUGH NEST. REATTACH NEST TO ARM USING SCREWS AND LOCK WASHERS.


VERIFY THAT GROMMET IS IN PLACE BEFORE TERMINATING CABLE.

UPON COMPLETION OF ROUTING AND TERMINATION OF HARNESS (ITEM 902) PERFORM CONTINUITY AND HIPOT TEST.



CABLE IS TO BE LABELED WITH TESTING VERIFICATION.

AFTER INSTALLATION OF DISPLAY CABLE, VERIFY THAT SEAL (PART OF NEST ASSY) IS IN PROPER POSITION IN NEST.



REV	REVISION DESCRIPTION	BY	DATE	ECO #
A	ORIGINAL RELEASE; REPLACES 777098-095	СН	05/ 10/ 01	BCT009099

			r							
903	1	EΑ	7	77098-196	GRO	GROMMET				
902	1	EΑ	7	77500-211	CAE	CABLE, DISPLAY				
901	1	EΑ	,7	77098-197,	ASS	ASSY., DISPLAY ARM				
ITEM NO.	QTY	U/M		PART NO.		DESCRIPTION				
	BILL OF REFERENCE									
THESE DIVERSEASE OF SPECIFICATIONS ARE THE PROPERTY OF COMMISSION OF AN AND SPECIFICATION WITHIN PROPERTY OF COMMISSION OF COMMI				I		CaridianBCT				
.xx 0.10 .xxx 0.01 ± 2° .xxx 0.00 5 5 5 F F F INTSH.		MATERIAL DATE		ASSY., DISPLAY ARM AND CABLE						
SIZE]	- 1/2	DO TO NOT SCALE		DRAWN K. KLIMEK	DATE DATE	777098-194 Ā Ī/Ĩ				

UG ÓWG.