## NOTES

- 1. BREAK ALL SHARP EDGES AND CORNERS.
- 2. INDICATES FEATURE/DIMENSION TO BE CHECKED AT INCOMING INSPECTION.







