



I. BREAK ALL SHARP EDGES AND CORNERS.

2. INDICATES KEY FEATURES TO BE VERIFIED BY INCOMING O.C.

