

Freezer Doors –	attach doo	or trac	eability lal	bels h	ere		
EST Electrical	l Testing	ES SL002	TID: 7			SL.2.G5	SW-25538
Cassette Q-U	Serial Numbe	r:	ULQC	Cn	OO47 eckea UK ignature	#2 Sel	rial # Label Here
Check Unit model BOM and Unit tran	on serial # la nsfer label ma	ibel mat itch's Bo	ches oM.		//		QA
Electrical Safety T Passed Signate		17			7	Date:	PASS
RTS Perform Testing		RTS SL002	S:26		SL	SL.2.GSWI_SL00	2_25538
These functions or	perate (tick if	OK)					
Lights	Evap Fan		Cond fan		PIR Sensor		Door Switches
Sweat Wire Checks:	Pillar		Frame		Top Element		Solenoid valve
Test Bay No:	Operator:	2	Door Eleme	nt	Failed:		Ambient Temp ℃ 4
Carry out any mod	el specific tes	its using	correct QR1	Γ form			
RTS Comment	s:						
Passed Signat	ure:		~		<u> </u>	Date:	2/4/24

20

Di.

FINAL ASSEMBLY CHECKLIST



Cab Types BBN, CLN, SLN

	Cab Types	Bee Bee H W	
	Checke	ed OK	Comments
Centre pillars flush with cabinet		(a. t.	ő
Heated door traceability labels have been remove from bottom of door frame and attached to paper	d work	/	
Shelf support strips are level to each other		/	
No rivet stems protruding on support strips		/	9
Light tubes in BBX are facing away from door		1	
Sliding doors operate smoothly and seal when clo	sed	1/4	_1
Swing doors are torsioned, aligned & seal		/	
Benchtop (if fitted) firmly secured		VA	
Quantity of shelves and clips matches BOM		/	
Handles are burr free		/	
Unit cover fits neatly and is square to door and a centrally around controller		/	
Attached correct labels to cabinet as per BOM &	QPS	/	
Cabinet is clean, has no scratches or dents		/	
Door locks operate smoothly		/	
Castors are packed and secured inside cabinet		/	

All Above Checks Completed	
Final Inspection Comments:	
Final Quality Check Sign-off Signature:	Date:



PRE-FOAM, E	BUILDII	NG &	Cab BOM Part #	SL002/X10364	į.
FOAMING CH	IECKLIS	ST	TOC Sheet	#24918	
2 DR GLASS SLN	LH BLK C	AST #	2	Comments	Signature
Foamed in Jig # (Circle jig used)	1	2	3		T-5
Plug #					
Check the sweat wire "o have any cuts or breaks insulation test to QPS 2-	by using a co			Reject any failures	NIA
Check the correct jig se					RM
Check the inside of the build-up, protruding scraffect foaming.					RAY
Check all holes are tEarth bonding/anti-s				QPS 240-001 refers	RAY
Pierce cab back tape to	allow air vent	ting (if ava	ilable)		104
Foam the Cabinet				Report any issues	RAY
Check cabinet extern scratches, crashing, foaming issues for th	dents, and v	oids. Cor		Note any repairs	RAY
Remove the tape from a foaming			e ASAP after	Easier to remove when warm	RAY
Check castors spin freel members. Check panels	•	-		Report any failures	RAY
Check foaming plug for screws, rivets or damag				Report any issues	7.5
Check cabinet once foal dents; correct any build				Record any Paintshop repairs below - Report any damage	T-5
Recheck sweat wire (if i using a continuity and/o				Report any failures; repair to GEN 004	7.5
Attach this form to the	cabinet and s	end to asse	embly if all OK	All OK	7-5
Describe any Paintsh	op repairs c	arried ou	t		



WIRING INITIAL Cabinet top/bottom wiring is completed Cabinet Cab	S OF N/A ANTE
Cabinet top/bottom wiring is completed Earth wires are installed CABINET No internal damage No external damage No external damage	S OF N/A AND AND AND AND AND AND AND AND AND AN
Cabinet top/bottom wiring is completed Earth wires are installed CABINET No internal damage No external damage No external damage	S OF N/A AND AND
Cabinet top/bottom wiring is completed Earth wires are installed CABINET No internal damage No external damage No external damage	S OF N/A AND AND
Cabinet top/bottom wiring is completed Earth wires are installed CABINET No internal damage No external damage No external damage	ANT
wiring is completed Earth wires are installed CABINET No internal damage No external damage PONENTS INITIALS or N/A	ANT
installed CABINET No internal damage No external damage No external damage No INITIALS or N/A	Ann
No internal damage No external damage No external damage No external damage	org.
No external damage PONENTS INITIALS or N/A	019.
PONENTS INITIALS OF N/A	-
plack sleeve	
it lighting wires	
doneycomb	
neater wire	
helves	
light-blind assy	
'lR sensor	
lips on shelf brackets	
o run lighting wires	
VET	
lo internal damage	
lo external damage	
la lea lighter lighter lighter lo	ht-blind assy sensor os on shelf brackets run lighting wires

Tue 03/Sep/2024 13:02:18

Booth 5 Test # 215394 UUT: SL.2.GSW-A240825538

Operator: 2
Ambient Temperature: 24.8

Test Start Time: 03/Sep/2024 11:26:10 Elapsed Test Time: 1:30:00 Test Status: Test completed - Passed Fault: None

Nec	1000
1.9	999
12	18.1
4	5.1
3.4	4.8
-0.8	1.3
Taraba Caraba Ca	0.5 1.9 6.9 12 2.9 4 2.2 3.4 -2.1 -0.8



