

/FX Doors – attach door tra	ceability labels	here			
	Refrigeration Test	System	Cabinet Model an	d Serial No:	
EST Electrical Testing	RTS: 25 ESTID: 64		OD1100N-A22	1215394	
Cassette Serial Number:	UBQE	ENI-0052	#2 S	erial # Label Here	
Q-U220912197		Checked OK Signature	Comments		
Check Unit model on serial # label matches BOM and Unit transfer label match's BoM.			QA PASS		
Electrical Safety Test to GEN 017			1	1 1	
Passed Signature:		n	Date:  2   1 23		
RTS Performance OD1 Testing O110	100N CLN	Cabinet Serial No:	A2	21215394 Qty: 4	
These functions operate (tick if O	k)				
Lights Evap Fan	Cond fan	Controller EC	O Mode	Door Switches	
Sweat Wire Pillar Checks:	Frame	Top Element		Solenoid valve	
Test Bay No: Operator:	2	Failed:		Ambient Temp ⁰C	
Carry out any model specific tests	using correct QR	T form			
RTS Comments:				1 1	
Passed Signature:	~		Date:	13/1/23	



PRE-FOAM, BUILDING &		Cab BOM Part #	011CLN/X10544		
FOAMING CI	HECKLIST	TOC Sheet #	#21899		
ODITOONLON	Sign BLK/BLK	Comments	Signature		
Foamed in Jig #	1 2	3		Mana	
Plug #	<b>支持的第</b>				
Check foaming plug for screws, rivets or damag	any old foam build-up, ge that could affect foa	, protruding ming	Report any issues		
Check the sweat wire "c have any cuts or breaks insulation test to QPS 2	by using a continuity	BOM), does not and/or 500V	Reject any failures		
Check all holes are tape	ed over and sweat wire	is secure	wing do a will be a life	And the second	
Check panels for scratches, defects, or blemishes;			Do not build if damaged - Report any damage	of the second	
Earth bonding/anti-static strap fitted to ALL models			QPS 240-001 refers		
Pierce cab back tape to allow air venting (if available)					
Foam the Cabinet.	, terrolica		Report any issues		
Check castors spin freely and do not α linths/cross			Report any failures	ن دور نامر کارو بروس	
members  Remove the tape from around the in the following specific to the following specific tot			Easier to remove when warm		
Check cabinet internals leaks, scratches, dents, next build	and external for damage correct any build issue	ge, foam s for the	Record any Paintshop repairs below—Report any damage		
Recheck sweat wire (if i using a continuity and/o 240-013	n the BOM), after build or 500V insulation test t	ling by to QPS	Report any Failures; repair to GEN 004		
Attach this form to the o	cabinet and send to ass	sembly if all OK	All OK	V	
Describe any Paintsh	op repairs carried ou	ut:			



	Colon Mikrisanski meganistan medaniska melaniska me	industries Limited
Cabinet Assembly Checklist	Comments	Signature **
Light channel screwed in.		Can-
Pillars are flush and secure.		1 solete
Hinges are secured properly.		even
Check door configuration.	TOTAL CONTROL OF A CONTROL	*
Doors tensioned.	1 7 30	
Door has no scratches or defects.	Report any damage	*
Sliding doors glide easily and are square and seal		Life.
Wiring completed to wiring diagrams.		
Check Unit model on serial # label matches BOM and Unit transfer label match's BOM.		
Theck cabinet internal and external for damage, stratches, dents.	Report any issues to the Process Leader	Tanta III
or VFX cabinets – use the jig to fit the rear luct.		
Recheck the sweat wire (if in the BoM), when you eceive the cabinet by using a continuity and/or 00V insulation test to QPS 240-013	Report any failure: repair to GEN 004	
escribe any Paintshop repairs carried out:		

## FINAL ASSEMBLY **CHECKLIST**



## Cab Type **OD1100** & **OD1100N**

	Checked OK	Comments
Ensuring lights switch on/off with toggle or blind switch		
Compressor is not icing up or covered in condensation		×
Check the motion sensor is working correctly. For the OD1100N put your hand on the LH side top — inside the cabinet.		-
Shelf support strips correctly orientated and no rivet stems protruding	1	
Shelves are burr free	/	
Speed-feed matting and ticket strips as per BOM requirements		-
Power cord clipped onto the cabinet top		
Any customer stickers/decals/headers/mirrors fitted as per BOM & QPS	/	
Kickpanel is secure and sits square so the controller is visible		3
Kickpanel trims are fitted and trimmed neatly		
Light tubes are fitted in correct orientation – refer to label – printing on tube to be on the left		4
Cabinet is clean, has no scratches or dents	/	
Ensure correct sign fitted	1	
Inseal behind aluminium verticals is not poking out	/	

All Above Checks Completed	
Final Inspection Comments:	
Final Ovality Chock Sign off Signaturo	Date:
Final Quality Check Sign-off Signature:	Date:

QRT 1067 21/06/2022

POUR LOD

Fri 13/Jan/2023 07:15:40

Booth 10 Test # 203073 UUT: OD1100N-A221215394

Operator: 2
Ambient Temperature: 24.8


Test Start Time: 12/Jan/2023 14:52:09 Elapsed Test Time: 1:29:00 Test Status: Test completed - Passed Fault: None

Cycle Low Temp	Cycle High Temp	Cycle Fall Time	Cycle Rise Time	Pulldown Rate	 Parameter
-6.8	2.1	9.5	11	0.5	 Min
0.2	8.6999	11	16	1.7	 Rec
5.2	. 6999999999999	13	20	999	 Max

11.2

×, ×

6-7-3 



4. 17