

SCOPE OF WORK
11537 LARIMORE RD, ST. LOUIS, MO 63138



TABLE OF CONTENTS

Property Details..... 3

Summary Overview 4

Before Pictures 5-9

After Pictures 10-18

Disclaimer 19

PROPERTY DETAILS



Size of Home

Square Footage: 1470 sqft

Lot Size: 0.49 Acres

Bedrooms: 3

Bathrooms: 1.5

Year Built

1955

SUMMARY OVERVIEW

Exterior

Repair and replace missing siding and fascia boards, Weed eat and fill in cracks in driveway, Clean up yard, Repair front door concrete slab, Remove wood fence, Paint Exterior, Replace front door, New Security Doors, Garage door motor and remote, Sheet rock garage, Remove trees front yard and back yard, vegetation around house, Remove woodshed, Add new gutters and extensions.

Interior

Paint Interior, New Window Blinds, Doorknobs, hinges, and stoppers, New Light Fixtures, New Ceiling Fans, Level living room and bedroom floors, Repair damaged walls in two bedrooms add insulation, New Smoke and CO2 detectors, New Vinyl Plank And quarter round, Install base boards, Seal up fireplace, Building permit.

Bathrooms

New ceramic tile, Refinish tub, surrounds, shower surround sand walls, 2 new toilets, 2 new mirrors, 2 new vanities.

Kitchen

Refinished kitchen cabinets, All new faucets, New stove, refrigerator, dishwasher and ventahood, Repair and tile wall in kitchen

Mechanical and Other Items

New water heater, New furnace and condenser, Replace all air vents and dryer vent.

Contractor Overview

Multiple contractors were needed to complete this project. Licensed contractors are used for electrical, plumbing and HVAC install.

Total Value Improvement Cost: \$ 38,350.00

EXTERIOR (BEFORE)



INTERIOR (BEFORE)



BATHROOMS (BEFORE)



KITCHEN (BEFORE)



MECHANICAL (BEFORE)



No before picture of
furnace

EXTERIOR (AFTER)



KITCHEN (AFTER)




BATHROOMS (AFTER)



BATHROOMS (AFTER)




BATHROOMS (AFTER)



BATHROOMS (AFTER)



INTERIOR (AFTER)



INTERIOR (AFTER)



MECHANICAL (AFTER)



DISCLAIMER

Age of water heater/HVAC and other property details are available in the home inspection report if and only if home inspection was ordered by buyer at the time of contract.

This document has been provided to buyer as a courtesy by Legacy Invest and has been sent to email address provided by buyer. Legacy Invest has done their best to provide accurate information herein, and cannot be held liable for any accidental errors or omissions.

If Legacy Invest does not hear anything back from buyer within 72 hours of this message being sent, buyer is satisfied with the information and photographs.