operating voltage =400		peak 1.5V		0	operating voltage = 450		peak=1.6			
0.5	23148	fine gain = 5			1	32188	coarse gair	n=2		
0.6	20724	coarse gain =5			1.1	49761	fine = 5			
0.7	17393	shaping = 0.5			1.2	54746	shaping = 0.5			
0.8	20736				1.3	39558				
0.9	39136	lower limit in peak= 11 17393		17393	1.4	23790	lower limit in peak= 11		3780	
1	62948				1.5	15213				
1.1	56478	half max	40170.5		1.6	10678	half max	29263		
1.2	33199	FWHM	0.27		1.7	7431	FWHM	0.3		
1.3	20520	RES	0.27		1.8	5529	RES	0.25		
1.4	12909				1.9	4141				
1.5	8321				2	3208				
1.6	5280									
		оре			perating vol	erating voltage 480		peak = 2.9		
operating voltage =420		peak 1.9V				coarse gair	1=2			
1	12349	fine gain = 5			1.5	9441	fine = 5			
1.1	11546	coarse gain =5			1.6	11561	shaping = 0.5			
1.2	12582	shaping = 0.5			1.7	16144				
1.3	18596				1.8	23117	lower limit	in peak= 11	6651	
1.4	29951	lower limit in peak= 11867			1.9	29529				
1.5	40975				2	32994 max	half max	19822.5		
1.6	42925	half max	27396		2.1	30962	FWHM	0.53		
1.7	34035	FWHM	0.391		2.2	25601	RES	0.265		
1.8	23673	RES	0.244375		2.3	18917				
1.9	16356				2.4	13888				
2	11636				2.5	10757				
2.1	8326				2.6	8603				
2.2	6288				2.7	6666				
2.3	4753				2.8	4319				

voltage resolution
400 0.27
420 0.244375
450 0.25
480 0.265

