

OYO 身份证读卡器检测及钉钉申请流程

一、检测步骤：

1. 检测酒店现有 ID 读卡器是否兼容。

1.1. 检测流程


打开 <https://pms.oyohotels.cn/#/login>

说明图例步骤


1.2. 下载驱动

The screenshot shows the homepage of the Taitan PMS system. At the top, there is a search bar with placeholder text '请输入手机号码或者订单号' and a '搜索' button. To the right of the search bar is a dropdown menu showing 'OYO 82559 Oyo培训测试专用酒店'. Below the header, there are four main statistics boxes: '今日预达 03/111 (间房)', '在住 125/300 (间房)', '今日预离 03/87 (间房)', and '今日预计入住率 41% 175间客房可售'. On the right side of the page, there is a QR code labeled '前台快速入住' with the note '部分酒店暂未开通此功能'. Below the QR code is a red box highlighting a button labeled '身份证读卡器驱动 (点击下载)'. A red arrow points to this button. To the right of the QR code, there are three other buttons: '教学视频', '注册会员', and '使用手册'.

1.3. 下载后安装程序。WIN10 系统需要点击更多信息



1.4 安装成功后，快捷方式位于桌面，点击后可直接弹出 OYO 页面



1.5. 提示正在链接身份证读卡器，未弹出其他报错，则安装成功。



1.6. 安装成功后，系统将自动采集客人身份信息



1.7 检测结果报错提示。

审批过程需要拍摄证据上传图片，才能获得审批通过。

拍摄图片时需要显示以下两个提示信息

The screenshot shows the Taitein PMS system interface. At the top, there is a banner indicating "正在连接身份证读卡器服务" (Connecting to ID card reader service). Below it, a search bar has the placeholder "请输入手机号码或者订单号" (Please enter phone number or order number) and a "搜索" (Search) button. The header also displays the hotel name "OYO 82559 Oyo培训测试专用酒店". The main content area is titled "新建订单" (New Order) and "Walk In". It contains two sections: "预定信息" (Booking Information) and "入住/预定信息" (Check-in/Booking Information). The "预定信息" section shows check-in date as 2018-10-16 and check-out date as 2018-10-17, totaling 1 night. Room type is "标准大床房" (Standard Double Bed Room), price is 0 yuan/night, and reference price is 159 yuan. The "入住/预定信息" section requires input for "姓名" (Name), "手机号" (Mobile Number), and "邮箱" (Email). A note at the bottom states: "已安装驱动，系统未识别读卡器信息时，会同时弹出“正在连接身份证读卡器服务”和“未识别到身份证读卡，请检查设备是否连接”，出现该提示，且身份证读卡器与PMS使用电脑已连接，由AGM协助酒店申请新的ID读卡器" (If the driver is installed and the system fails to recognize the card reader information, both "Connecting to ID card reader service" and "ID card reading failed, please check if the device is connected" will pop up simultaneously. This occurs when the ID card reader is connected to the PMS computer, and AGM will assist the hotel in applying for a new ID card reader). At the bottom right, there is a red "新建订单" (New Order) button.

二、申请步骤

发现酒店身份证件读卡器，无法兼容泰坦系统时，AGM可以通过钉钉后台给酒店业主申请新的读卡器。

2. 申请图例步骤


2.1. 打开钉钉审批-其他-身份证件读卡器申请



2.2 填写相关信息

2.3 上传检测图片 2 张（请使用元道经纬相机 APP 拍摄，采集检测结果）

样式图片 1. 上传检测结果，两项证据作为审批标准



案例 2. 证明该原读卡器连接电脑后，泰坦系统设备无法读取。拍摄后上传



三、审批完成

3. 审批通过后，在规定工作日内向酒店发送新的 ID 读卡器。

3.1 身份证读卡器外观图片



3.2 设备信息

CPU	72MHz 32bit高性能处理器
存储器	64KB Flash, 20KB RAM
主机接口	RS232串口型/USB 2.0标准型/USB HID型/USB CCID型
安全控制模块	内置**部授权的居民身份证安全控制模块（SAM）
读卡距离	0~5cm
阅读时间	≤1秒
非接触卡	支持符合Type A和Type B规范的非接触卡，天线谐振频率：13.56MHz
蓝牙模块	支持蓝牙2.0标准，支持连蓝牙数据通讯、蓝牙打印机等设备（可选）
数 据 安 全	国际算法 DES/3DES,SHA-1,RSA
	国密算法 SM1,SM2,SM3,SM4
	其他 三级密钥管理体系
PSAM卡座	2路标准PSAM卡座（可定制）
蜂鸣器	300-2300Hz
电源	DC 5V , USB接口供电, 或外置电源适配器供电
功耗	<0.7W
主机尺寸 (mm)	144×110×31
净重(g)	239
无故障工作时间	≥10000小时
技术标准	GA 450-2013台式居民身份证阅读器通用技术要求
	GA 467-2013居民身份证验证安全控制模块接口技术规范
环境适应性	工作温度 0℃~50℃
	相对湿度 10% ~ 95%
	大气压力 86 ~ 106 kpa
	环境噪声 不大于60 dB (A)