1 If no fault has been found during previous tests (54-505 to 54-525), install new control unit as a tryout.

