
GEAROTONS / RS485 CONTROLLER

Two motors. One complete connection map.

USB-C PD input · parallel motor power · one continuous RS485 bus



Power in parallel. A/B continues through Motor 1 to Motor 2.

J1 and J2 GND are common on the PCB; both motors have full-size power-return wires.

20 V is nominal after PD negotiation. Wire with power off; verify voltage and polarity.

A/B lines show electrical pairing; select compatible mating parts. Each black shell has two isolated cavities.