S/N	Task/Work Activity	Hazards	Consequences	initial			(5M) - Causal Factors	Control Measures	Residual RL	Action By	Remark
				S	Р	RL					
1	Usage of POL	Consumption of POL	Acute Poisoning	В	2	B2(Medium)	Man Lack of mindfulness - Lack of knowledge	Adhere to instructions in SDS     Wear appropriate PPE     Refer to storage and handling orders	B1 (Low)	(1)-(3): Supervisor & working personnel	NIL
		Slipping and falling due to spillage	Sprain	С	2	C2(Low)	Man. - Lack of mindfulness - Lack of awareness	Clean up spillage     Wear approved safety boots     Refer to storage and handling orders	C2 (Low)	(1)-(3): Supervisor & working personnel	NIL
		Risk of fire outbreak	Burns	С	2	C2(Low)	Man Lack of mindfulness - Lack of awareness	Ensure fire extinguisher are present and serviceable     Follow fire fighting instructions in SDS     Wear approved PPE	C2 (Low)	(1)-(3): Supervisor & working personnel	NIL
2	Working below aircraft	Contact with sharp edges/ Panels	Minor cuts/ bruise	D	2	D2(Low)	Man - Lack of mindfulness	Wear bump cap     Personnel to be briefed on aircraft sharp edges     Awareness of sharp edges on aircraft	D2 (Low)	(1)-{3): working personnel (2): Supervisor	NIL
3	Struck by heavy falling objects	objects falling on personnel	Fractures/ cuts/ bruises	В	2	B2(Medium)	Man - Lack of mindfulness - Lack of awareness  Machine - Material fatigue/ failure	Near bump cap     Awareness of sharp edges on aircraft     In inspect components/ area of work before and during task	B1 (Low)	(1)-(2): working personnel (1): Supervisor & working personnel	