

RFI-001 -- WINDOW SILL FLASHING FIELD CONDITION AT TAG 148607

ARMIE-generated synthetic fixture · not a real project document

Question: The window represented by IFC Tag 148607 on Level 2 was found during framing inspection to have a rough opening that does not match the issued glazing specification.

Response: A field measurement confirmed the as-built rough opening width for Tag 148607 is 1.35 m, requiring a revised sill flashing detail. This value is not yet reflected in any issued schedule or specification sheet; the window glazing specification will be reissued at the next drawing revision.