

# Detailed Diagnostic Report

## 1. Property Issue Summary

The property exhibits widespread dampness at skirting levels in the Hall, Common Bedroom, Master Bedroom, and Kitchen. Significant issues include tile hollowness, gaps in tile joints, and plumbing problems in both Common and Master Bedroom Bathrooms. Cracks are observed on external walls, including a specific duct issue near the Master Bedroom, and general cracks on RCC columns and beams. Leakage is also noted at the parking area ceiling below Flat No. 103, and mild dampness in the Common Bathroom ceiling, attributed to leakage from Flat No. 203.

## 2. Area-wise Observations

### Area 1: Hall

**Observation:** Dampness observed at the skirting level of the Hall.

**Probable Root Cause:** Not Available

**Severity:** Moderate — Skirting level dampness observed, aligning with general 'Condition of leakage at adjacent walls' noted as Moderate in the checklist.

**Recommended Action:** Not Available



Photo 1



Photo 2




Photo 3



Photo 4



Photo 5



Photo 6



Photo 7

## Area 2: Common Bathroom

**Observation:** Observed gaps between the tile joints, tile hollowness, and plumbing issues in the Common Bathroom.

**Probable Root Cause:** Leakage due to concealed plumbing, leakage due to damage in Nahani trap/Brickbat coba under tile flooring, gaps/blackish dirt observed in tile joints, gaps around Nahani Trap Joints, and loose plumbing joints/rust around joints and edges.

**Severity:** Moderate — Gaps in tile joints, tile hollowness, and plumbing issues observed, which are noted as causes for 'leakage at adjacent walls' and general WC leakage conditions flagged as Moderate.

**Recommended Action:** Not Available



Photo 8



Photo 9



Photo 10



Photo 11




Photo 15



Photo 16



Photo 17



Photo 18



Photo 19

### Area 3: Common Bedroom

**Observation:** Dampness observed at the skirting level of the Common Bedroom.

**Probable Root Cause:** Not Available

**Severity:** Moderate — Skirting level dampness observed, aligning with general 'Condition of leakage at adjacent walls' noted as Moderate in the checklist.

**Recommended Action:** Not Available

Image Not Available

### Area 4: Master Bedroom

**Observation:** Dampness observed at the skirting level of the Master Bedroom.

**Probable Root Cause:** Not Available

**Severity:** Moderate — Skirting level dampness observed, aligning with general 'Condition of leakage at adjacent walls' noted as Moderate in the checklist.

**Recommended Action:** Not Available



Photo 20



Photo 21



Photo 22




Photo 23





Photo 24



Photo 25

## Area 5: Master Bedroom Bathroom

**Observation:** Observed gaps between the tile joints and tile hollowness in the Master Bedroom Bathroom.

**Probable Root Cause:** Not Available

**Severity:** Moderate — Gaps in tile joints and tile hollowness observed, indicating potential for leakage.

**Recommended Action:** Not Available



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37

## Area 6: Kitchen

**Observation:** Dampness observed at the skirting level of the Kitchen.

**Probable Root Cause:** Not Available

**Severity:** Moderate — Skirting level dampness observed, aligning with general 'Condition of leakage at adjacent walls' noted as Moderate in the checklist.

**Recommended Action:** Not Available



Photo 31





Photo 32

## Area 7: Master Bedroom

**Observation:** Dampness and efflorescence observed on the wall surface of the Master Bedroom.

**Probable Root Cause:** Not Available

**Severity:** Moderate — Dampness and efflorescence indicate prolonged moisture issues, aligning with general 'Condition of leakage at adjacent walls' noted as Moderate.

**Recommended Action:** Not Available



Photo 38



Photo 39



Photo 40



Photo 41

## **Area 8: External wall near Master Bedroom**

**Observation:** Cracks observed on the External wall of the building near the Master Bedroom, along with a duct issue.

**Probable Root Cause:** Not Available

**Severity:** Moderate — Cracks on the external wall and an identified duct issue, aligning with 'major or minor cracks observed over external surface' and 'external plumbing pipes cracked and leaked' both noted as Moderate.

**Recommended Action:** Not Available



Photo 42



Photo 43





Photo 44



Photo 45



Photo 46



Photo 47



Photo 48

### **Area 9: Parking Area ceiling below Flat No. 103**

**Observation:** Leakage observed at the Parking ceiling below Flat No. 103.

**Probable Root Cause:** Not Available

**Severity:** Not Available — Leakage observed on the parking ceiling, but no explicit severity is stated.

**Recommended Action:** Not Available

Image Not Available

### **Area 10: Common Bathroom Ceiling**

**Observation:** Mild dampness observed at the ceiling of the Common Bathroom.

**Probable Root Cause:** Leakage from Flat No. 203 tile joint and outlet.

**Severity:** Not Available — Mild dampness observed on the ceiling, but no explicit severity is stated.

**Recommended Action:** Not Available

Image Not Available

## Area 11: Flat No. 203 (Common & Master Bedroom Bathrooms)

**Observation:** Gaps observed between tile joints and outlet leakage in Flat No. 203.

**Probable Root Cause:** Not Available

**Severity:** Not Available — Gaps in tile joints and outlet leakage from the flat above, which is identified as the cause for ceiling dampness in Flat No. 103's Common Bathroom, but no explicit severity is stated for this source.

**Recommended Action:** Not Available

Image Not Available

## Area 12: Structural RCC Members

**Observation:** Moderate cracks observed on RCC Columns and Beams.

**Probable Root Cause:** Not Available

**Severity:** Moderate — Explicitly stated as 'Condition of cracks observed on RCC Column and Beam Moderate'.

**Recommended Action:** Not Available

Image Not Available

## Area 13: External Walls (General)

**Observation:** Moderate major or minor cracks observed over the external surface. Algae, fungus, and moss growth observed on the external wall.

**Probable Root Cause:** Not Available

**Severity:** Moderate — Explicitly stated as 'Are there any major or minor cracks observed over external surface? Moderate' and 'Algae fungus and Moss observed on external wall? Moderate'.

**Recommended Action:** Not Available

Image Not Available

## 3. Additional Notes

General observations indicate leakage occurs 'All time' due to concealed plumbing and/or damage in Nahani trap/Brickbat coba under tile flooring. Loose plumbing joints and gaps around Nahani Trap Joints were also observed as general conditions in WC areas.

## 4. Missing or Unclear Information

Specific root causes for most dampness and structural issues are not explicitly stated. Specific recommendations for all identified issues are not provided. Severity levels for some observations (e.g., parking seepage, common bathroom ceiling dampness, Flat 203 leakage) are not explicitly given. The Thermal Report does not provide location mapping for its thermal images, preventing

their association with specific observations. Inspection photo references for 'Impacted Area 2 Negative side photographs' are missing.