

Root-Cause Evidence Summary

Record the evidence supporting the NCR-026 causal finding.

Fixture review

Locator sleeve showed visible wear. Conclusion: wear affected positioning.

Setup history

The condition trigger was absent. Conclusion: the control plan had a gap.

Measurement review

Variation exceeded ± 0.18 mm. Conclusion: the NCR condition was confirmed.

The evidence supports a combined equipment-condition and control-plan root cause; no individual performance attribution is made.