

SITE INSPECTION REPORT - TUAN DEV

SITE INSPECTION REPORT

GENERIC SAMPLE - illustrative only, not a real site

Project: Kwasa Damansara - Mechanical & Electrical

Location: Selangor, Malaysia

Inspector: Tuan Dev (Designated Person)

Date: Thursday, 14 August 2026

Status: UNDER REVIEW

1. Executive Summary

General condition of the site is satisfactory. Two minor observations were raised regarding housekeeping and lighting. No critical findings recorded.

2. Scope of Inspection

Visual inspection of electrical distribution, cable routing, and access points. This is a generic sample report for demonstration purposes.

FINDINGS SUMMARY - SITE INSPECTION

3. Findings Summary

CLIENT SITE INSPECTION - FINDINGS

Ref	Finding	Category	Status
F-01	Minor cable dressing	Housekeeping	Open
F-02	Armoured gland torque	Compliance	Verified
F-03	Emergency light test	Safety	Informational

4. Photographic Evidence

(Sample: placeholder for field photographs captured during inspection)

5. Risk Assessment

Overall residual risk after control measures: LOW.
No high or critical risk items were identified.

RECOMMENDATIONS - SITE INSPECTION

6. Recommendations

R-01: Schedule housekeeping rectification within 14 days.

R-02: Retest emergency lighting and log the result.

R-03: Maintain cable dressing at all junction boxes.

7. Sign-off

Inspected and prepared by:

TUAN DEV

Designated Person - Systems

This document is a GENERIC SAMPLE for portfolio demonstration.
No client, site, or operational data is represented.