

Investigate the cut fault.

Rebuild and restart.


I inspected the high-pressure pump, performed its scheduled rebuild, reassembled it, and checked the machine after repair.

3 working days

Shutdown to production restart · reported in my account

Reported cutting pattern and supply path

Cut travel →



The colored strip sketches penetration; it is not a measured cut-depth trace.

What I found and did

Finding	More mechanical play than expected in the pump cylinder assemblies.
Action	Standard 5,000-hour rebuild kit, reassembly, and machine checks.
Checks	Consistent through-cuts returned; pump output readings were higher.

Qualitative reconstruction. The exact failed component, pump model, and numerical pressure readings are not retained.