Keep the original signed efficiency

$\Omega_s = 1.05$ · losses and ideal work use the same reference triangles





Efficiency becomes negative when the loss estimate exceeds ideal shaft work. Those samples remain in the data.