


ENGINEERING CHANGE NOTICE — ECN-2025-044

REDLINE MARKUP — Connector Plate Assy PN-4457 Rev C → Rev D



REV D CHANGES:

- 1. TIGHTENED GENERAL TOLERANCE FROM ±0.010 TO ±0.005
- 2. ADDED THRU HOLE FOR WIRING HARNESS ROUTING
- 3. UPDATED BOM: ADDED GROMMET MS35489-30 (QTY 1)
- 4. ADDED NOTE 4: BREAK EDGE OF NEW HOLE 0.015 MAX

ECN-2025-044 | Originated: S. Williams | Date: March 5, 2025
Approved: J. Harrison, QE | Effectivity: Next production lot
Reason: Customer request — wiring harness routing through plate