Serving Arizona & New Mexico

4733 E. Firestone Drive Chandler, AZ 85249



Tel: (480) 361-5340 / (800) 393-7903

Fax: (480) 634-4616 www.reservestudy.com Planning For The Inevitable™

Regional Offices

Arizona California Colorado Florida Hawaii Nevada North Carolina Texas Washington





Report #: 47818-0

Beginning: January 1, 2024

Expires: December 31, 2024

RESERVE STUDY

"Full"

August 31, 2023

Welcome to your Reserve Study!

Reserve Study is a valuable tool to help you budget responsibly for your property. This report contains all the information you need to avoid surprise expenses, make informed decisions, save money, and protect property values.

egardless of the property type, it's a fact of life that the very moment construction is completed, every major building component begins a predictable process of physical deterioration. The operative word is "predictable" because planning for the inevitable is what a Reserve Study by **Association Reserves** is all about!

In this Report, you will find three key results:

• Component List

Unique to each property, the Component List serves as the foundation of the Reserve Study and details the scope and schedule of all necessary repairs & replacements.

• Reserve Fund Strength

A calculation that measures how well the Reserve Fund has kept pace with the property's physical deterioration.

• Reserve Funding Plan

A multi-year funding plan based on current Reserve Fund strength that allows for component repairs and replacements to be completed in a timely manner, with an emphasis on fairness and avoiding "catch-up" funding.

Questions?

Please contact your Project Manager directly.



www.reservestudy.com

Table of Contents

Executive Summary	4
Executive Summary (Component List)	5
Introduction, Objectives, and Methodology	7
Which Physical Assets are Funded by Reserves?	8
How do we establish Useful Life and Remaining Useful Life estimates?	8
How do we establish Current Repair/Replacement Cost Estimates?	8
How much Reserves are enough?	9
How much should we contribute?	10
What is our Recommended Funding Goal?	10
Site Inspection Notes	11
Projected Expenses	12
Annual Reserve Expenses Graph	12
Reserve Fund Status & Recommended Funding Plan	13
Annual Reserve Funding Graph	13
30-Yr Cash Flow Graph	14
Percent Funded Graph	14
Table Descriptions	15
Budget Summary	16
Reserve Component List Detail	17
Fully Funded Balance	18
Component Significance	19
30-Year Reserve Plan Summary	20
30-Year Income/Expense Detail	21
Accuracy, Limitations, and Disclosures	27
Terms and Definitions	28
Component Details	29
GROUNDS	30
PARK AREAS	40
POOL AREA	43



Jorde Farms HOA

Queen Creek, AZ

Level of Service: "Full"

Report #: 47818-0

as of January 1, 2024

of Units: 401

January 1, 2024 through December 31, 2024

Findings & Recommendations

	40 01 0411441 j 1, 202 1
Projected Starting Reserve Balance	
Current Fully Funded Reserve Balance	
Average Reserve Deficit (Surplus) Per Unit	
Percent Funded	
Current Monthly Reserve Contribution	

Recommended 2024 Monthly Reserve Contribution\$10,300

Reserve Fund Strength: 97.0%	Weak	Fair	Strong	
	<	30%	< 70%	> 130%
			X	
Risk of Special Assessment:	High	Medium	Low	_

Economic Assumptions:

Net Annual "After Tax" Interest Earnings Accruing to Reserves	0.50 %
Annual Inflation Rate	3.00 %

This is a "Full" Reserve Study (original, created "from scratch") based on our site inspection on 4/27/2023.

The Reserve expense threshold for this analysis is \$2,000. That means any Reserve related expenses under the threshold are not funded in the Reserve Study and need to be paid from the Operating Budget.

Your Reserve Fund is 97.0 % Funded. This means the Reserve Fund status is Strong, and the HOA's risk of special assessments & deferred maintenance is currently Low.

The objective of your multi-year Funding Plan is to Fully Fund Reserves, where associations enjoy a low risk of Reserve cash flow problems.

Based on this starting point and anticipated future expenses, we recommend budgeting Monthly Reserve contributions of \$10,300 for the 2024 Fiscal Year. Annual increases are scheduled thereafter to help offset inflation and strengthen Reserves. Going forward, the contribution rate should be increased as illustrated on the 30-Year Summary Table.

This Reserve Study does not account for every potential expense the HOA may face. Projects deemed unpredictable with regard to timing and cost are typically not included. It is beyond the scope of this Reserve Study to inspect or assess structural conditions of buildings, walls, electrical systems, utilities, plumbing systems, irrigation, drainage, etc. We recommend scheduling periodic inspections by qualified engineers or other industry professionals to assess any potential issues or concerns.



#	Component	Useful Life (yrs)	Rem. Useful Life (yrs)	Current Average Cost
	GROUNDS			
103	Concrete/Pavers - Repair	5	4	\$4,000
315	Landscape Lights - Replace	12	11	\$80,000
380	Mailboxes - Replace	18	17	\$110,000
385	Mailbox Roofs - Replace	30	29	\$5,000
501	Block Walls - Repair	25	24	\$100,000
510	Wall Columns - Repaint	6	5	\$23,000
535	View Fence - Replace	30	29	\$275,000
550	Metal Surfaces - Repaint	6	5	\$32,000
701	Monuments - Remodel	20	19	\$15,000
705	Fountain - Remodel	15	14	\$12,000
805	Irrigation Controllers - Replace	15	14	\$23,000
820	Landscape Granite - Replenish	10	9	\$350,000
840	Drywells - Inspect/Clean	5	4	\$14,000
845	Drywells - Partial Replace	30	29	\$25,000
	PARK AREAS			
405	Park Furniture - Replace	15	14	\$47,000
410	Playground Equipment - Replace	20	19	\$125,000
415	Shade Screens - Replace	10	9	\$4,000
420	Playground Turf - Replace	12	11	\$48,000
425	Playground Mulch - Replenish	5	4	\$9,000
490	Ramada Roof - Replace	25	25	\$20,000
	POOL AREA			
1120	Metal Fence - Replace	25	24	\$28,000
1125	Keypads - Replace	10	9	\$4,000
1130	Pool Area - Repaint	6	5	\$8,000
1135	Doors + Windows - Replace	30	29	\$16,000
1142	Drinking Fountains - Replace	12	11	\$4,000
1145	Shower - Remodel	15	14	\$5,000
1150	Restrooms - Remodel	15	14	\$20,000
1190	Flat Roof - Replace	15	14	\$6,000
1200	Pool Deck Pavers - Replace	25	24	\$100,000
1208	Pool - Resurface	12	11	\$45,000
1212	Pool Lift - Replace	12	11	\$10,000
1220	Pool Furniture - Replace	8	7	\$30,000
1222	Pool Lounge Cushions - Replace	4	3	\$5,000
1250	Pool Filters - Replace	15	14	\$8,200
1260	Pool Pump - Replace	12	11	\$5,000
Associ	ation Reserves, #47818-0	5		8/31/2023

# Component	Useful Life (yrs)	Rem. Useful Life (yrs)	Current Average Cost
1270 Pool Heaters - Replace	6	5	\$12,000

36 Total Funded Components

Note 1: Yellow highlighted line items are expected to require attention in this initial year.

Introduction



A Reserve Study is the art and science of anticipating, and preparing for, an association's major common area repair and replacement expenses. Partially art, because in this field we are making projections about the future. Partially science, because our work is a combination of research and well-defined computations, following consistent National Reserve Study Standard principles.

The foundation of this and every Reserve Study is your Reserve Component List (what you are reserving for). This is because the Reserve Component List defines the scope and schedule of all your anticipated upcoming Reserve projects. Based on that List and your starting balance, we calculate the association's Reserve Fund Strength (reported in terms of "Percent Funded"). Then we compute a Reserve Funding Plan to provide for the Reserve needs of the association. These form the three results of your Reserve Study.



RESERVE STUDY RESULTS

Reserve contributions are not "for the future". Reserve contributions are designed to offset the ongoing, daily deterioration of your Reserve assets. Done well, a <u>stable</u>, <u>budgeted</u> Reserve Funding Plan will collect sufficient funds from the owners who enjoyed the use of those assets, so the association is financially prepared for the irregular expenditures scattered through future years when those projects eventually require replacement.

Methodology



For this <u>Full Reserve Study</u>, we started with a review of your Governing Documents, recent Reserve expenditures, an evaluation of how expenditures are handled (ongoing maintenance vs Reserves), and research into any well-established association precedents. We

performed an on-site inspection to quantify and evaluate your common areas, creating your Reserve Component List *from scratch*.

Which Physical Assets are Funded by Reserves?

There is a national-standard four-part test to determine which expenses should appear in your Reserve Component List. First, it must be a common area maintenance responsibility. Second, the component must have a limited life. Third, the remaining life must be predictable (or it by definition is a *surprise* which cannot be accurately anticipated). Fourth, the component must be above a minimum threshold cost (often between .5% and 1% of an association's total budget). This limits Reserve



RESERVE COMPONENT "FOUR-PART TEST"

Components to major, predictable expenses. Within this framework, it is inappropriate to include *lifetime* components, unpredictable expenses (such as damage due to fire, flood, or earthquake), and expenses more appropriately handled from the Operational Budget or as an insured loss.

How do we establish Useful Life and Remaining Useful Life estimates?

- 1) Visual Inspection (observed wear and age)
- 2) Association Reserves database of experience
- 3) Client History (install dates & previous life cycle information)
- 4) Vendor Evaluation and Recommendation

How do we establish Current Repair/Replacement Cost Estimates?

In this order...

- 1) Actual client cost history, or current proposals
- 2) Comparison to Association Reserves database of work done at similar associations
- 3) Vendor Recommendations
- 4) Reliable National Industry cost estimating guidebooks

How much Reserves are enough?

Reserve adequacy is not measured in cash terms. Reserve adequacy is found when the amount of current Reserve cash is compared to Reserve component deterioration (the needs of the association). Having enough means the association can execute its projects in a timely manner with existing Reserve funds. Not having enough typically creates deferred maintenance or special assessments.

Adequacy is measured in a two-step process:

Each year, the value of deterioration at the

- 1) Calculate the value of deterioration at the association (called Fully Funded Balance, or FFB).
- 2) Compare that to the Reserve Fund Balance, and express as a percentage.



SPECIAL ASSESSMENT RISK association changes. When there is more deterioration (as components approach the time they need to be replaced), there should be more cash to offset that deterioration and prepare for the expenditure. Conversely, the *value of deterioration* shrinks after projects are accomplished. The value of deterioration (the FFB) changes each year, and is a moving but predictable target.

There is a high risk of special assessments and deferred maintenance when the Percent Funded is weak, below 30%. Approximately 30% of all associations are in this high risk range. While the 100% point is Ideal (indicating Reserve cash is equal to the value of deterioration), a Reserve Fund in the 70% - 130% range is considered strong (low risk of special assessment).

Measuring your Reserves by Percent Funded tells how well prepared your association is for upcoming Reserve expenses. New buyers should be very aware of this important disclosure!

How much should we contribute?



RESERVE FUNDING PRINCIPLES

According to National Reserve Study Standards, there are four Funding Principles to balance in developing your Reserve Funding Plan. Our first objective is to design a plan that provides you with <u>sufficient cash</u> to perform your Reserve projects on time. Second, a <u>stable contribution</u> is desirable because it keeps these naturally irregular expenses from unsettling the budget.

Reserve contributions that are <u>evenly distributed</u> over current and future owners enable each owner to pay their fair share of the association's Reserve expenses over the years. And finally, we develop a plan that is <u>fiscally responsible</u> and safe for Boardmembers to recommend to their association. Remember, it is the Board's <u>job</u> to provide for the ongoing care of the common areas. Boardmembers invite liability exposure when Reserve contributions are inadequate to offset ongoing common area deterioration.

What is our Recommended Funding Goal?

Maintaining the Reserve Fund at a level equal to the *value* of deterioration is called "Full Funding" (100% Funded). As each asset ages and becomes "used up," the Reserve Fund grows proportionally. This is simple, responsible, and our recommendation. Evidence shows that associations in the 70 - 130% range *enjoy a low risk of special assessments or deferred maintenance*.



FUNDING OBJECTIVES

Allowing the Reserves to fall close to zero, but not below zero, is called <u>Baseline Funding</u>. Doing so allows the Reserve Fund to drop into the 0 - 30% range, where there is a high risk of special assessments & deferred maintenance. Since Baseline Funding still provides for the timely execution of all Reserve projects, and only the "margin of safety" is different, Baseline Funding contributions average only 10% - 15% less than Full Funding contributions. <u>Threshold Funding</u> is the title of all other Cash or Percent Funded objectives *between* Baseline Funding and Full Funding.

Site Inspection Notes

During the site visit on 4/27/2023, we started by inspecting the park and pool areas. Next, we inspected the common walls and fencing. Finally, we inspected the monument signs, landscaping, and any remaining common areas.

Please see the Component Details Appendix at the end of this report for a detailed look at each component.










Projected Expenses

While this Reserve Study looks forward 30 years, we have no expectation that all of these expenses will take place as anticipated. This Reserve Study needs to be updated annually, because we expect the timing of expenses to shift and the size of the expenses to change. We do feel more certain of the timing and cost of near-term expenses than expenses many years away. Please be aware of your near-term expenses, which we are able to project more accurately than the more distant projections.

The chart below summarizes the projected future expenses at your association as defined by the Reserve Component List. A summary of these components is shown in the Component Details Table, while a summary of the expenses themselves is shown in the 30-yr Expense Summary Table.



Reserve Fund Status

The starting point for our financial analysis is your Reserve Fund balance, projected to be \$112,210 as-of the start of your fiscal year on 1/1/2024. This projected balance was provided to Association Reserves. As of 1/1/2024, your Fully Funded Balance is computed to be \$115,711. This figure represents the deteriorated value of your common area components. Comparing your Reserve Balance to the Fully Funded Balance indicates Reserves are 97.0 % Funded.

Recommended Funding Plan

Based on your current Percent Funded and cash flow requirements, we recommend budgeting Monthly Reserve contributions of \$10,300 this Fiscal Year. The overall 30-year plan, in perspective, is shown below. This same information is shown numerically in both the 30-yr Summary and the Cash Flow Detail tables.





Figure 2

The following chart shows your Reserve balance under our recommended Funding Plan and your currently budgeted contribution rate, compared to the always-changing Fully Funded Balance target.



This chart shows the same information plotted on a Percent Funded scale. It is clear here to see how your Reserve Fund strength approaches the 100% Funded level under our recommended multi-year Funding Plan.




Table Descriptions



Executive Summary is a summary of your Reserve Components

Budget Summary is a management and accounting tool, summarizing groupings of your Reserve Components.

Reserve Component List Detail discloses key Component information, providing the foundation upon which the financial analysis is performed.

<u>Fully Funded Balance</u> shows the calculation of the Fully Funded Balance for each of your components, and their contributions to the property total. For each component, the Fully Funded Balance is the fraction of life used up multiplied by its estimated Current Replacement Cost.

Component Significance shows the relative significance of each component to Reserve funding needs of the property, helping you see which components have more (or less) influence than others on your total Reserve contribution rate. The deterioration cost/yr of each component is calculated by dividing the estimated Current Replacement Cost by its Useful Life, then that component's percentage of the total is displayed.

<u>30-Yr Reserve Plan Summary</u> provides a one-page 30-year summary of the cash flowing into and out of the Reserve Fund, with a display of the Fully Funded Balance, Percent Funded, and special assessment risk at the beginning of each year.

<u>30-Year Income/Expense Detail</u> shows the detailed income and expenses for each of the next 30 years. This table makes it possible to see which components are projected to require repair or replacement in a particular year, and the size of those individual expenses.




	Usef	ul Life		Rem. ul Life	Estimated Replacement Cost in 2024		01/01/2024 Current Fund Balance	01/01/2024 Fully Funded Balance	Remaining Bal. to be Funded	2024 Contributions
	Min	Max	Min	Max						
GROUNDS	5	30	4	29	\$1,068,000	\$0	\$74,293	\$77,794	\$993,707	\$82,528
PARK AREAS	5	25	4	25	\$253,000	\$0	\$15,583	\$15,583	\$237,417	\$17,380
POOL AREA	4	30	3	29	\$306,200	\$0	\$22,333	\$22,333	\$283,867	\$23,692
					\$1,627,200	\$0	\$112.210	\$115.711	\$1.514.990	\$123.600

Percent Funded: 97.0%

Budget Summary

Percentage of Total Estimated Replacement Costs





#	Component	Quantity	Useful Life	Rem. Useful Life	Current Cost Estimate
	GROUNDS				
103	Concrete/Pavers - Repair	Numerous Sq Ft	5	4	\$4,000
315	Landscape Lights - Replace	Approx (270) Fixtures	12	11	\$80,000
380	Mailboxes - Replace	Approx (24) Clusters	18	17	\$110,000
385	Mailbox Roofs - Replace	(3) Roofs: ~250 Sq Ft	30	29	\$5,000
501	Block Walls - Repair	Approx 90,000 Sq Ft	25	24	\$100,000
510	Wall Columns - Repaint	Approx (212) Columns	6	5	\$23,000
535	View Fence - Replace	Approx 3,200 LF	30	29	\$275,000
550	Metal Surfaces - Repaint	Numerous Sq Ft	6	5	\$32,000
701	Monuments - Remodel	(2) Monuments	20	19	\$15,000
705	Fountain - Remodel	(1) Fountain: ~50 LF	15	14	\$12,000
805	Irrigation Controllers - Replace	(3) WeatherTrak Pro3	15	14	\$23,000
820	Landscape Granite - Replenish	Approx 4,300 Tons	10	9	\$350,000
840	Drywells - Inspect/Clean	Approx (28) Drywells	5	4	\$14,000
845	Drywells - Partial Replace	Approx (28) Drywells	30	29	\$25,000
	PARK AREAS				
405	Park Furniture - Replace	(17) Assorted Pieces	15	14	\$47,000
410	Playground Equipment - Replace	(12) Assorted Pieces	20	19	\$125,000
415	Shade Screens - Replace	(2) Screens: ~500 Sq Ft	10	9	\$4,000
420	Playground Turf - Replace	Approx 1,600 Sq Ft	12	11	\$48,000
425	Playground Mulch - Replenish	Approx 3,500 Sq Ft	5	4	\$9,000
490	Ramada Roof - Replace	(1) Roof: ~1,000 Sq Ft	25	25	\$20,000
	POOL AREA				
1120	Metal Fence - Replace	Approx 275 LF	25	24	\$28,000
1125	Keypads - Replace	(4) Keypads	10	9	\$4,000
1130	Pool Area - Repaint	Fence, Pergola, Stucco	6	5	\$8,000
1135	Doors + Windows - Replace	(3) Doors, (10) Windows	30	29	\$16,000
1142	Drinking Fountains - Replace	(2) Oasis	12	11	\$4,000
1145	Shower - Remodel	(1) Dual Shower	15	14	\$5,000
1150	Restrooms - Remodel	(2) Restrooms: ~250 Sq Ft	15	14	\$20,000
1190	Flat Roof - Replace	Approx 800 Sq Ft	15	14	\$6,000
1200	Pool Deck Pavers - Replace	Approx 4,400 Sq Ft	25	24	\$100,000
1208	Pool - Resurface	(1) Pool: ~255 LF	12	11	\$45,000
1212	Pool Lift - Replace	(1) Aqua Creek	12	11	\$10,000
1220	Pool Furniture - Replace	(72) Assorted Pieces	8	7	\$30,000
1222	Pool Lounge Cushions - Replace	(19) Cushions	4	3	\$5,000
1250	Pool Filters - Replace	(3) TR100C	15	14	\$8,200
1260	Pool Pump - Replace	(1) Whisper-Flo XF, 5-HP	12	11	\$5,000
1270	Pool Heaters - Replace	(2) MasterTemp 400	6	5	\$12,000

³⁶ Total Funded Components



#	Component	Current Cost Estimate	X	Effective Age	I	Useful Life	=	Fully Funded Balance
	GROUNDS							
103	Concrete/Pavers - Repair	\$4,000	Χ	1	/	5	=	\$800
315	Landscape Lights - Replace	\$80,000	Х	1	/	12	=	\$6,667
380	Mailboxes - Replace	\$110,000	Χ	1	/	18	=	\$6,111
385	Mailbox Roofs - Replace	\$5,000	Х	1	/	30	=	\$167
501	Block Walls - Repair	\$100,000	Χ	1	/	25	=	\$4,000
510	Wall Columns - Repaint	\$23,000	Χ	1	/	6	=	\$3,833
535	View Fence - Replace	\$275,000	Χ	1	/	30	=	\$9,167
550	Metal Surfaces - Repaint	\$32,000	Χ	1	1	6	=	\$5,333
701	Monuments - Remodel	\$15,000	Χ	1	1	20	=	\$750
705	Fountain - Remodel	\$12,000	Х	1	/	15	=	\$800
805	Irrigation Controllers - Replace	\$23,000	Х	1	/	15	=	\$1,533
820	Landscape Granite - Replenish	\$350,000	Х	1	/	10	=	\$35,000
840	Drywells - Inspect/Clean	\$14,000	Х	1	1	5	=	\$2,800
845	Drywells - Partial Replace	\$25,000	Х	1	/	30	=	\$833
	PARK AREAS							
405	Park Furniture - Replace	\$47,000	Х	1	/	15	=	\$3,133
410	Playground Equipment - Replace	\$125,000	Х	1	/	20	=	\$6,250
415	Shade Screens - Replace	\$4,000	Х	1	/	10	=	\$400
420	Playground Turf - Replace	\$48,000	Х	1	/	12	=	\$4,000
425	Playground Mulch - Replenish	\$9,000	Х	1	/	5	=	\$1,800
490	Ramada Roof - Replace	\$20,000	Х	0	/	25	=	\$0
	POOL AREA							
1120	Metal Fence - Replace	\$28,000	Х	1	/	25	=	\$1,120
1125	Keypads - Replace	\$4,000	Х	1	/	10	=	\$400
1130	Pool Area - Repaint	\$8,000	Х	1	/	6	=	\$1,333
1135	Doors + Windows - Replace	\$16,000	Х	1	1	30	=	\$533
1142	Drinking Fountains - Replace	\$4,000	Х	1	/	12	=	\$333
1145	Shower - Remodel	\$5,000	Х	1	/	15	=	\$333
1150	Restrooms - Remodel	\$20,000	Х	1	/	15	=	\$1,333
1190	Flat Roof - Replace	\$6,000	Х	1	/	15	=	\$400
1200	Pool Deck Pavers - Replace	\$100,000	Х	1	/	25	=	\$4,000
1208	Pool - Resurface	\$45,000	Х	1	/	12	=	\$3,750
1212	Pool Lift - Replace	\$10,000	Х	1	/	12	=	\$833
	Pool Furniture - Replace	\$30,000	Х	1	/	8	=	\$3,750
	Pool Lounge Cushions - Replace	\$5,000	Χ	1	/	4	=	\$1,250
	Pool Filters - Replace	\$8,200	Х	1	/	15	=	\$547
	Pool Pump - Replace	\$5,000	Х	1	1	12	=	\$417
	Pool Heaters - Replace	\$12,000	Х	1	1	6	=	\$2,000
		Ţ. <u>=</u> ,000	••	•	•			¢2,000

\$115,711





15	#	Component	Useful Life (yrs)	Current Cost Estimate	Deterioration Cost/Yr	Deterioration Significance
15		GROUNDS				
380 Mailboxes - Replace 18 \$110,000 \$6,111 \$2.5% 385 Mailbox Roofs - Replace 30 \$5,000 \$167 0.14% 501 Block Walls - Repair 25 \$100,000 \$4,000 3.43% 510 Wall Columns - Repaint 6 \$23,000 \$3,833 3.29 % 535 View Fence - Replace 30 \$275,000 \$9,167 7.87 % 550 Metal Surfaces - Repaint 6 \$32,000 \$5,333 4.58 % 705 Fountain - Remodel 20 \$15,000 \$750 0.64 % 705 Fountain - Remodel 15 \$12,000 \$800 0.69 % 805 Irrigation Controllers - Replace 15 \$23,000 \$1,533 1.32 % 805 Irrigation Expedicion 5 \$14,000 \$2,600 30.04 % 840 Drywells - Inspect/Clean 5 \$14,000 \$2,800 3.00 3.04 % 840 Drywells - Partial Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 15 \$47,000 \$3,133 2.69 %	103	Concrete/Pavers - Repair	5	\$4,000	\$800	0.69 %
385 Mailbox Roofs Replace 30 \$5,000 \$167 0.14 % 501 Block Walls - Repair 25 \$100,000 \$4,000 3.43 % 510 Wall Columns - Repairt 6 \$23,000 \$3,833 3.29 % 550 Metal Surfaces - Replace 30 \$275,000 \$9,167 7.87 % 550 Metal Surfaces - Repairt 6 \$32,000 \$5,333 4.58 % 701 Monuments - Remodel 20 \$15,000 \$750 0.64 % 705 Fountain - Remodel 15 \$12,000 \$800 0.69 % 805 Irrigation Controllers - Replace 15 \$23,000 \$1,533 1.32 % 820 Landscape Granite - Replace 16 \$350,000 \$35,000 3.04 % 845 Drywells - Inspect/Clean 5 \$14,000 \$2,500 \$3.13 2.69 % 45 Drywells - Partial Replace 15 \$47,000 \$3,133 2.69 % 45 Drywells - Partial Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 15 \$47,000 \$3,133	315	Landscape Lights - Replace	12	\$80,000	\$6,667	5.72 %
501 Block Walls - Repair 25 \$100,000 \$4,000 3.43 % 510 Well Columns - Repairet 6 \$23,000 \$3,833 3.29 % 535 View Fence - Replace 30 \$275,000 \$9,167 7.87 % 550 Metal Surfaces - Repairet 6 \$32,000 \$5,333 4.58 % 701 Monuments - Remodel 20 \$15,000 \$500 0.64 % 705 Fountain - Remodel 15 \$12,000 \$800 0.69 % 805 Irrigation Controllers - Replace 15 \$23,000 \$1,533 1.32 % 820 Landscape Granite - Replenish 10 \$350,000 \$35,000 30.04 % 840 Drywells - Inspect/Clean 5 \$14,000 \$2,800 2.40 % 845 Drywells - Partial Replace 30 \$25,000 \$833 0.72 % PARK AREAS 405 Park Furniture - Replace 15 \$47,000 \$3,133 2,69 % 410 Playground Equipment - Replace 15 \$47,000 \$3,00 3,4 % 410 Playground Equipment - Replace 15	380	Mailboxes - Replace	18	\$110,000	\$6,111	5.25 %
510 Wall Columns - Repaint 6 \$23,000 \$3,833 3.29 % 535 View Fence - Replace 30 \$275,000 \$9,167 7.87 % 550 Metal Surfaces - Repaint 6 \$32,000 \$5,333 4.58 % 701 Monuments - Remodel 20 \$15,000 \$750 0.64 % 705 Fountain - Remodel 15 \$12,000 \$800 0.69 % 805 Irrigation Controllers - Replace 15 \$23,000 \$1,533 1.32 % 820 Landscape Grantle - Replenish 10 \$350,000 \$35,000 30.04 % 840 Drywells - Partial Replace 5 \$14,000 \$2,800 2.40 % 845 Drywells - Partial Replace 15 \$47,000 \$3,133 2.69 % 45 Park Furniture - Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 15 \$47,000 \$3,133 2.69 % 415 Shade Screens - Replace 10 \$4,000 \$40.00 3.43 % 425 Playground Mulch - Replace 12 \$4,000 \$40.00 3.43 %	385	Mailbox Roofs - Replace	30	\$5,000	\$167	0.14 %
535 View Fence - Replace 30 \$275,000 \$9,167 7.87 % 550 Metal Surfaces - Repaint 6 \$32,000 \$5,333 4.68 % 701 Monuments - Remodel 20 \$15,000 \$750 0.64 % 705 Fountain - Remodel 15 \$12,000 \$800 0.69 % 805 Irrigation Controllers - Replace 15 \$23,000 \$1,533 1.32 % 820 Landscape Grantle - Replenish 10 \$350,000 \$35,000 30.04 % 840 Drywells - Inspect/Clean 5 \$14,000 \$2,800 2.00 % 845 Drywells - Partial Replace 5 \$14,000 \$2,800 2.00 % 845 Drywells - Partial Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 15 \$47,000 \$3,133 2.69 % 415 Shade Screens - Replace 10 \$4,000 \$4,000 \$3,43 % 425 Playground Mulch - Replace 12 \$48,000 \$4,000 \$4,000 420 Playground Mulch - Replace 25 \$20,000 \$800 0.69 %	501	Block Walls - Repair	25	\$100,000	\$4,000	3.43 %
550 Metal Surfaces - Repaint 6 \$32,000 \$5,333 4.58 % 701 Monuments - Remodel 20 \$15,000 \$750 0.64 % 705 Fountain - Remodel 15 \$12,000 \$800 0.69 % 805 Irrigation Controllers - Replace 15 \$23,000 \$1,533 1.32 % 820 Landscape Granite - Replenish 10 \$350,000 \$35,000 30.04 % 840 Drywells - Inspect/Clean 5 \$14,000 \$2,800 2.40 % 845 Drywells - Partial Replace 30 \$25,000 \$833 0.72 % PARK AREAS 405 Park Furniture - Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 10 \$4,000 \$6,250 5.56 % 415 Shade Screens - Replace 10 \$4,000 \$4,000 3.43 % 420 Playground Turf - Replace 12 \$48,000 \$4,000 3.43 % 425 Playground Mulch - Replenish 5 \$9,000 \$1,800 1.54 % 400 Ramada Roof - Replace 25	510	Wall Columns - Repaint	6	\$23,000	\$3,833	3.29 %
701 Monuments - Remodel 20 \$15,000 \$750 0.64 % 705 Fountain - Remodel 15 \$12,000 \$800 0.69 % 805 Irrigation Controllers - Replace 15 \$23,000 \$1,533 1.32 % 820 Landscape Granite - Replenish 10 \$35,000 \$35,000 30.04 % 840 Drywells - Inspect/Clean 5 \$14,000 \$2,800 2.40 % 845 Drywells - Partial Replace 30 \$25,000 \$833 0.72 % PARK AREAS 410 Playground Equipment - Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 10 \$4,000 \$0,250 5.36 % 415 Shade Screens - Replace 10 \$4,000 \$4,000 3.43 % 420 Playground Mulch - Replace 12 \$48,000 \$4,000 3.44 % 420 Playground Mulch - Replace 25 \$20,000 \$1,800 1.54 % 420 Ramada Roof - Replace 25 \$28,000 \$1,120 0.96 % 1120 Metal Fence - Replace 25	535	View Fence - Replace	30	\$275,000	\$9,167	7.87 %
705 Fountain - Remodel 15 \$12,000 \$800 0.69 % 805 Irrigation Controllers - Replace 15 \$23,000 \$1,533 1.32 % 820 Landscape Granite - Replenish 10 \$350,000 \$35,000 30.04 % 840 Drywells - Inspect/Clean 5 \$14,000 \$2,800 2.40 % 845 Drywells - Partial Replace 30 \$25,000 \$833 0.72 % PARK AREAS 410 Playground Equipment - Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 20 \$125,000 \$6,250 5.36 % 415 Shade Screens - Replace 10 \$4,000 \$400 0.34 % 420 Playground Turf - Replace 12 \$48,000 \$4,000 3.43 % 425 Playground Mulch - Replenish 5 \$9,000 \$1,800 1.54 % 425 Playground Mulch - Replace 25 \$20,000 \$800 0.69 % 120 Ramada Roof - Replace 25 \$28,000 \$1,120 0.96 % 125 Keypads - Replace 25	550	Metal Surfaces - Repaint	6	\$32,000	\$5,333	4.58 %
805 Irrigation Controllers - Replace 15 \$23,000 \$1,533 1.32 % 820 Landscape Granite - Replenish 10 \$350,000 \$35,000 30.04 % 840 Drywells - Inspect/Clean 5 \$14,000 \$2,800 2.40 % 845 Drywells - Partial Replace 30 \$25,000 \$833 0.72 % PARK AREAS 405 Park Furniture - Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 20 \$125,000 \$6,250 5.36 % 415 Shade Screens - Replace 10 \$4,000 \$400 0.34 % 420 Playground Turf - Replace 12 \$48,000 \$4,000 3.40 425 Playground Mulch - Replenish 5 \$9,000 \$1,800 1.54 % 490 Ramada Roof - Replace 25 \$20,000 \$800 0.69 % POOL AREA 1125 Keypads - Replace 25 \$28,000 \$1,120 0.96 % 1125 Keypads - Replace 10 \$4,000 \$40 0.34 %	701	Monuments - Remodel	20	\$15,000	\$750	0.64 %
820 Landscape Granite - Replenish 10 \$350,000 \$35,000 30.04 % 840 Drywells - Inspect/Clean 5 \$14,000 \$2,800 2.40 % 845 Drywells - Partial Replace 30 \$25,000 \$833 0.72 % PARK AREAS 405 Park Furniture - Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 20 \$125,000 \$6,250 5.36 % 415 Shade Screens - Replace 10 \$4,000 \$400 0.34 % 420 Playground Turf - Replace 12 \$48,000 \$4,000 34.00 425 Playground Mulch - Replenish 5 \$9,000 \$1,800 1.54 % 490 Ramada Roof - Replace 25 \$20,000 \$800 0.69 % POOL AREA 1120 Metal Fence - Replace 25 \$28,000 \$1,120 0.96 % 1125 Keypads - Replace 10 \$4,000 \$400 0.34 % 1130 Pool Area - Repaint 6 \$8,000 \$1,333 1.14 % 1130 Pool Area - Replace 12	705	Fountain - Remodel	15	\$12,000	\$800	0.69 %
840 Drywells - Inspect/Clean 5 \$14,000 \$2,800 2.40 % 845 Drywells - Partial Replace 30 \$25,000 \$833 0.72 % PARK AREAS 405 Park Furniture - Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 20 \$125,000 \$6,250 5.36 % 415 Shade Screens - Replace 10 \$4,000 \$400 0.34 % 420 Playground Mulch - Replenish 5 \$9,000 \$1,800 1.54 % 420 Ramada Roof - Replace 25 \$20,000 \$800 0.69 % POOL AREA ***	805	Irrigation Controllers - Replace	15	\$23,000	\$1,533	1.32 %
845 Drywells - Partial Replace 30 \$25,000 \$833 0.72 % PARK AREAS 405 Park Furniture - Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 20 \$125,000 \$6,250 5.36 % 415 Shade Screens - Replace 10 \$4,000 \$400 0.34 % 420 Playground Turf - Replace 12 \$48,000 \$4,000 3.40 % 425 Playground Mulch - Replenish 5 \$9,000 \$1,800 1.54 % 490 Ramada Roof - Replace 25 \$20,000 \$800 0.69 % POOL AREA 1120 Metal Fence - Replace 25 \$28,000 \$1,120 0.96 % 1125 Keypads - Replace 10 \$4,000 \$400 0.94 % 1125 Keypads - Replace 10 \$4,000 \$400 0.94 % 1125 Keypads - Replace 10 \$4,000 \$400 0.94 % 1125 Keypads - Replace 12 \$4,000 \$333 0.29 % 1126 Doil Area - Repaint 6 <td>820</td> <td>Landscape Granite - Replenish</td> <td>10</td> <td>\$350,000</td> <td>\$35,000</td> <td>30.04 %</td>	820	Landscape Granite - Replenish	10	\$350,000	\$35,000	30.04 %
PARK AREAS	840	Drywells - Inspect/Clean	5	\$14,000	\$2,800	2.40 %
405 Park Furniture - Replace 15 \$47,000 \$3,133 2.69 % 410 Playground Equipment - Replace 20 \$125,000 \$6,250 5.36 % 415 Shade Screens - Replace 10 \$4,000 \$400 0.34 % 420 Playground Turf - Replace 12 \$48,000 \$4,000 3.43 % 425 Playground Mulch - Replenish 5 \$9,000 \$1,800 1.54 % 490 Ramada Roof - Replace 25 \$20,000 \$800 0.69 % POOL AREA 1120 Metal Fence - Replace 25 \$28,000 \$1,120 0.96 % 1125 Keypads - Replace 10 \$4,000 \$400 0.34 % 1130 Doors + Windows - Replace 30 \$16,000 \$1,333 1.14 % 1142 Drinking Fountains - Replace 12 \$4,000 \$333 0.29 % 1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Replace 15 \$6,000 \$400 0.34 % 120 Pool Deck Pavers - Replace 15 \$	845	Drywells - Partial Replace	30	\$25,000	\$833	0.72 %
410 Playground Equipment - Replace 20 \$125,000 \$6,250 5.36 % 415 Shade Screens - Replace 10 \$4,000 \$400 0.34 % 420 Playground Turf - Replace 12 \$48,000 \$4,000 3.43 % 425 Playground Mulch - Replenish 5 \$9,000 \$1,800 1.54 % 490 Ramada Roof - Replace 25 \$20,000 \$800 0.69 % POOL AREA 1120 Metal Fence - Replace 25 \$28,000 \$1,120 0.96 % 1125 Keypads - Replace 10 \$4,000 \$400 0.34 % 1130 Pool Area - Repaint 6 \$8,000 \$1,333 1.14 % 1135 Doors + Windows - Replace 30 \$16,000 \$533 0.46 % 1142 Drinking Fountains - Replace 12 \$4,000 \$333 0.29 % 1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 120 Pool Deck Pavers - Replace 15 \$6,000 \$400 0.34 % 120 Pool Deck Pavers - Replace 25		PARK AREAS				
415 Shade Screens - Replace 10 \$4,000 \$400 0.34 % 420 Playground Turf - Replace 12 \$48,000 \$4,000 3.43 % 425 Playground Mulch - Replenish 5 \$9,000 \$1,800 1.54 % 490 Ramada Roof - Replace 25 \$20,000 \$800 0.69 % POOL AREA 1120 Metal Fence - Replace 25 \$28,000 \$1,120 0.96 % 1125 Keypads - Replace 10 \$4,000 \$400 0.34 % 1130 Pool Area - Repaint 6 \$8,000 \$1,333 1.14 % 1135 Doors + Windows - Replace 30 \$16,000 \$533 0.46 % 1142 Drinking Fountains - Replace 12 \$4,000 \$333 0.29 % 1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 1190 Flat Roof - Replace 15 \$6,000 \$400 0.34 % 1200 Pool Deck Pavers - Replace 15 \$6,000 \$4,000 3.43 % 1202 Pool Furniture - Replace 12 \$45,000	405	Park Furniture - Replace	15	\$47,000	\$3,133	2.69 %
420 Playground Turf - Replace 12 \$48,000 \$4,000 3.43 % 425 Playground Mulch - Replenish 5 \$9,000 \$1,800 1.54 % 490 Ramada Roof - Replace 25 \$20,000 \$800 0.69 % POOL AREA 1120 Metal Fence - Replace 25 \$28,000 \$1,120 0.96 % 1125 Keypads - Replace 10 \$4,000 \$400 0.34 % 1130 Pool Area - Repaint 6 \$8,000 \$1,333 1.14 % 1135 Doors + Windows - Replace 30 \$16,000 \$533 0.46 % 1142 Drinking Fountains - Replace 12 \$4,000 \$333 0.29 % 1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 1190 Flat Roof - Replace 15 \$6,000 \$400 0.34 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1202 Pool Lift - Replace 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 8 \$30,000	410	Playground Equipment - Replace	20	\$125,000	\$6,250	5.36 %
425 Playground Mulch - Replenish 5 \$9,000 \$1,800 1.54 % 490 Ramada Roof - Replace 25 \$20,000 \$800 0.69 % POOL AREA 1120 Metal Fence - Replace 25 \$28,000 \$1,120 0.96 % 1125 Keypads - Replace 10 \$4,000 \$400 0.34 % 1130 Pool Area - Repaint 6 \$8,000 \$1,333 1.14 % 1135 Doors + Windows - Replace 30 \$16,000 \$533 0.46 % 1142 Drinking Fountains - Replace 12 \$4,000 \$333 0.29 % 1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 1190 Flat Roof - Replace 15 \$6,000 \$400 0.34 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1200 Pool Deck Pavers - Replace 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 12 \$10,000 \$833	415	Shade Screens - Replace	10	\$4,000	\$400	0.34 %
490 Ramada Roof - Replace 25 \$20,000 \$800 0.69 % POOL AREA 1120 Metal Fence - Replace 25 \$28,000 \$1,120 0.96 % 1125 Keypads - Replace 10 \$4,000 \$400 0.34 % 1130 Pool Area - Repaint 6 \$8,000 \$1,333 1.14 % 1135 Doors + Windows - Replace 30 \$16,000 \$533 0.46 % 1142 Drinking Fountains - Replace 12 \$4,000 \$333 0.29 % 1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 1190 Flat Roof - Replace 15 \$6,000 \$333 0.29 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 0.34 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1202 Pool Furniture - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750	420	Playground Turf - Replace	12	\$48,000	\$4,000	3.43 %
POOL AREA	425	Playground Mulch - Replenish	5	\$9,000	\$1,800	1.54 %
1120 Metal Fence - Replace 25 \$28,000 \$1,120 0.96 % 1125 Keypads - Replace 10 \$4,000 \$400 0.34 % 1130 Pool Area - Repaint 6 \$8,000 \$1,333 1.14 % 1135 Doors + Windows - Replace 30 \$16,000 \$533 0.46 % 1142 Drinking Fountains - Replace 12 \$4,000 \$333 0.29 % 1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 1190 Flat Roof - Replace 15 \$6,000 \$400 0.34 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1208 Pool - Resurface 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1220 Pool Lift - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % <t< td=""><td>490</td><td>Ramada Roof - Replace</td><td>25</td><td>\$20,000</td><td>\$800</td><td>0.69 %</td></t<>	490	Ramada Roof - Replace	25	\$20,000	\$800	0.69 %
1125 Keypads - Replace 10 \$4,000 \$400 0.34 % 1130 Pool Area - Repaint 6 \$8,000 \$1,333 1.14 % 1135 Doors + Windows - Replace 30 \$16,000 \$533 0.46 % 1142 Drinking Fountains - Replace 12 \$4,000 \$333 0.29 % 1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 1190 Flat Roof - Replace 15 \$6,000 \$400 0.34 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1208 Pool - Resurface 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 6 \$12,000 \$2,000 1.72 % <td></td> <td>POOL AREA</td> <td></td> <td></td> <td></td> <td></td>		POOL AREA				
1130 Pool Area - Repaint 6 \$8,000 \$1,333 1.14 % 1135 Doors + Windows - Replace 30 \$16,000 \$533 0.46 % 1142 Drinking Fountains - Replace 12 \$4,000 \$333 0.29 % 1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 1190 Flat Roof - Replace 15 \$6,000 \$400 0.34 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1208 Pool - Resurface 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 6 \$12,000 \$2,000 1.72 %	1120	Metal Fence - Replace	25	\$28,000	\$1,120	0.96 %
1135 Doors + Windows - Replace 30 \$16,000 \$533 0.46 % 1142 Drinking Fountains - Replace 12 \$4,000 \$333 0.29 % 1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 1190 Flat Roof - Replace 15 \$6,000 \$400 0.34 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1208 Pool - Resurface 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1125	Keypads - Replace	10	\$4,000	\$400	0.34 %
1142 Drinking Fountains - Replace 12 \$4,000 \$333 0.29 % 1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 1190 Flat Roof - Replace 15 \$6,000 \$400 0.34 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1208 Pool - Resurface 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1130	Pool Area - Repaint	6	\$8,000	\$1,333	1.14 %
1145 Shower - Remodel 15 \$5,000 \$333 0.29 % 1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 1190 Flat Roof - Replace 15 \$6,000 \$400 0.34 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1208 Pool - Resurface 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1135	Doors + Windows - Replace	30	\$16,000	\$533	0.46 %
1150 Restrooms - Remodel 15 \$20,000 \$1,333 1.14 % 1190 Flat Roof - Replace 15 \$6,000 \$400 0.34 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1208 Pool - Resurface 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1142	Drinking Fountains - Replace	12	\$4,000	\$333	0.29 %
1190 Flat Roof - Replace 15 \$6,000 \$400 0.34 % 1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1208 Pool - Resurface 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1145	Shower - Remodel	15	\$5,000	\$333	0.29 %
1200 Pool Deck Pavers - Replace 25 \$100,000 \$4,000 3.43 % 1208 Pool - Resurface 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1150	Restrooms - Remodel	15	\$20,000	\$1,333	1.14 %
1208 Pool - Resurface 12 \$45,000 \$3,750 3.22 % 1212 Pool Lift - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1190	Flat Roof - Replace	15	\$6,000	\$400	0.34 %
1212 Pool Lift - Replace 12 \$10,000 \$833 0.72 % 1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1200	Pool Deck Pavers - Replace	25	\$100,000	\$4,000	3.43 %
1220 Pool Furniture - Replace 8 \$30,000 \$3,750 3.22 % 1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1208	Pool - Resurface	12	\$45,000	\$3,750	3.22 %
1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1212	Pool Lift - Replace	12	\$10,000	\$833	0.72 %
1222 Pool Lounge Cushions - Replace 4 \$5,000 \$1,250 1.07 % 1250 Pool Filters - Replace 15 \$8,200 \$547 0.47 % 1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1220	Pool Furniture - Replace	8	\$30,000	\$3,750	3.22 %
1260 Pool Pump - Replace 12 \$5,000 \$417 0.36 % 1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %			4	\$5,000	\$1,250	1.07 %
1270 Pool Heaters - Replace 6 \$12,000 \$2,000 1.72 %	1250	Pool Filters - Replace	15	\$8,200	\$547	0.47 %
	1260	Pool Pump - Replace	12	\$5,000	\$417	0.36 %
36 Total Funded Components \$116,511 100.00 %	1270	Pool Heaters - Replace	6	\$12,000	\$2,000	1.72 %
	36	Total Funded Components			\$116,511	100.00 %



30-Year Reserve Plan Summary

Fiscal Year Start: 2024 Interest: 0.50 % Inflation: 3.00 % Reserve Fund Strength: as-of Fiscal Year Start Date Projected Reserve Balance Changes

			<u> </u>						
	.				% Increase				
	Starting	Fully		Special			Loan or		
	Reserve	Funded	Percent	Assmt		Reserve	Special	Interest	Reserve
Year	Balance	Balance	Funded	Risk	Funding	Funding	Assmts	Income	Expenses
2024	\$112,210	\$115,711	97.0 %	Low	12.69 %	\$123,600	\$0	\$872	\$0
2025	\$236,682	\$239,189	99.0 %	Low	4.50 %	\$129,162	\$0	\$1,510	\$0
2026	\$367,354	\$369,971	99.3 %	Low	4.50 %	\$134,974	\$0	\$2,179	\$0
2027	\$504,507	\$508,385	99.2 %	Low	4.50 %	\$141,048	\$0	\$2,868	\$5,464
2028	\$642,960	\$649,143	99.0 %	Low	4.50 %	\$147,395	\$0	\$3,515	\$30,389
2029	\$763,482	\$772,386	98.8 %	Low	4.50 %	\$154,028	\$0	\$3,994	\$86,946
2030	\$834,559	\$845,124	98.7 %	Low	3.50 %	\$159,419	\$0	\$4,582	\$0
2031	\$998,559	\$1,013,771	98.5 %	Low	3.50 %	\$164,999	\$0	\$5,310	\$43,046
2032	\$1,125,822	\$1,147,440	98.1 %	Low	3.50 %	\$170,774	\$0	\$6,070	\$0
2033	\$1,302,666	\$1,333,884	97.7 %	Low	3.50 %	\$176,751	\$0	\$5,712	\$502,338
2034	\$982,792	\$1,013,074	97.0 %	Low	3.50 %	\$182,937	\$0	\$5,384	\$0
2035	\$1,171,112	\$1,204,745	97.2 %	Low	3.50 %	\$189,340	\$0	\$5,400	\$376,512
2036	\$989,341	\$1,019,197	97.1 %	Low	3.50 %	\$195,967	\$0	\$5,449	\$0
2037	\$1,190,756	\$1,220,874	97.5 %	Low	3.50 %	\$202,826	\$0	\$6,476	\$0
2038	\$1,400,058	\$1,433,733	97.7 %	Low	3.50 %	\$209,924	\$0	\$6,981	\$224,166
2039	\$1,392,797	\$1,427,375	97.6 %	Low	3.50 %	\$217,272	\$0	\$7,388	\$54,529
2040	\$1,562,928	\$1,600,998	97.6 %	Low	3.50 %	\$224,876	\$0	\$8,396	\$0
2041	\$1,796,200	\$1,841,603	97.5 %	Low	3.50 %	\$232,747	\$0	\$8,819	\$305,777
2042	\$1,731,989	\$1,780,253	97.3 %	Low	3.50 %	\$240,893	\$0	\$9,283	\$0
2043	\$1,982,166	\$2,037,964	97.3 %	Low	3.50 %	\$249,324	\$0	\$8,230	\$929,358
2044	\$1,310,361	\$1,352,296	96.9 %	Low	3.50 %	\$258,051	\$0	\$7,213	\$0
2045	\$1,575,626	\$1,609,610	97.9 %	Low	3.50 %	\$267,083	\$0	\$8,565	\$0
2046	\$1,851,274	\$1,881,145	98.4 %	Low	3.50 %	\$276,430	\$0	\$9,970	\$0
2047	\$2,137,674	\$2,167,524	98.6 %	Low	3.50 %	\$286,106	\$0	\$9,936	\$596,023
2048	\$1,837,693	\$1,855,489	99.0 %	Low	3.50 %	\$296,119	\$0	\$8,653	\$518,362
2049	\$1,624,102	\$1,621,189	100.2 %	Low	3.50 %	\$306,483	\$0	\$8,802	\$41,876
2050	\$1,897,512	\$1,877,960	101.0 %	Low	3.50 %	\$317,210	\$0	\$10,304	\$0
2051	\$2,225,027	\$2,193,103	101.5 %	Low	3.50 %	\$328,313	\$0	\$11,946	\$11,106
2052	\$2,554,179	\$2,514,026	101.6 %	Low	3.50 %	\$339,804	\$0	\$13,652	\$0
2053	\$2,907,634	\$2,864,013	101.5 %	Low	3.50 %	\$351,697	\$0	\$10,125	\$2,126,093

30-Year Income/Expense Detail

Report # 47818-0 Full

	Fiscal Year	2024	2025	2026	2027	2028
	Starting Reserve Balance	\$112,210	\$236,682	\$367,354	\$504,507	\$642,960
	Annual Reserve Funding	\$123,600	\$129,162	\$134,974	\$141,048	\$147,395
	Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
	Interest Earnings	\$872	\$1,510	\$2,179	\$2,868	\$3,515
•	Total Income	\$236,682	\$367,354	\$504,507	\$648,424	\$793,871
#	Component					
	GROUNDS					
103	Concrete/Pavers - Repair	\$0	\$0	\$0	\$0	\$4,502
	Landscape Lights - Replace	\$0	\$0	\$0	\$0	\$0
	Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
	Mailbox Roofs - Replace	\$0	\$0	\$0	\$0	\$0
	Block Walls - Repair	\$0	\$0	\$0	\$0	\$0
	Wall Columns - Repaint	\$0	\$0	\$0	\$0	\$0
	View Fence - Replace	\$0	\$0	\$0	\$0	\$0
	Metal Surfaces - Repaint	\$0	\$0	\$0	\$0	\$0
	Monuments - Remodel	\$0	\$0	\$0	\$0	\$0
	Fountain - Remodel	\$0	\$0	\$0	\$0	\$0
	Irrigation Controllers - Replace	\$0 \$0	\$0	\$0	\$0	\$0
	Landscape Granite - Replace	\$0 \$0	\$0	\$0 \$0	\$0	\$0
	Drywells - Inspect/Clean	\$0 \$0	\$0 \$0	\$0 \$0	\$0	
	·					\$15,757
845	Drywells - Partial Replace	\$0	\$0	\$0	\$0	\$0
405	PARK AREAS	# 0	20	20		00
	Park Furniture - Replace	\$0	\$0	\$0	\$0	\$0
	Playground Equipment - Replace	\$0	\$0	\$0	\$0	\$0
	Shade Screens - Replace	\$0	\$0	\$0	\$0	\$0
	Playground Turf - Replace	\$0	\$0	\$0	\$0	\$0
	Playground Mulch - Replenish	\$0	\$0	\$0	\$0	\$10,130
490	Ramada Roof - Replace	\$0	\$0	\$0	\$0	\$0
	POOL AREA					
1120	Metal Fence - Replace	\$0	\$0	\$0	\$0	\$0
1125	Keypads - Replace	\$0	\$0	\$0	\$0	\$0
1130	Pool Area - Repaint	\$0	\$0	\$0	\$0	\$0
1135	Doors + Windows - Replace	\$0	\$0	\$0	\$0	\$0
1142	Drinking Fountains - Replace	\$0	\$0	\$0	\$0	\$0
1145	Shower - Remodel	\$0	\$0	\$0	\$0	\$0
1150	Restrooms - Remodel	\$0	\$0	\$0	\$0	\$0
1190	Flat Roof - Replace	\$0	\$0	\$0	\$0	\$0
1200	Pool Deck Pavers - Replace	\$0	\$0	\$0	\$0	\$0
1208	Pool - Resurface	\$0	\$0	\$0	\$0	\$0
1212	Pool Lift - Replace	\$0	\$0	\$0	\$0	\$0
1220	Pool Furniture - Replace	\$0	\$0	\$0	\$0	\$0
1222	Pool Lounge Cushions - Replace	\$0	\$0	\$0	\$5,464	\$0
1250	Pool Filters - Replace	\$0	\$0	\$0	\$0	\$0
1260	Pool Pump - Replace	\$0	\$0	\$0	\$0	\$0
	Pool Heaters - Replace	\$0	\$0	\$0	\$0	\$0
•	Total Expenses	\$0	\$0	\$0	\$5,464	\$30,389
	Ending Reserve Balance	\$236,682	\$367,354	\$504,507	\$642,960	\$763,482

	Fiscal Year	2029	2030	2031	2032	2033
	Starting Reserve Balance	\$763,482	\$834,559	\$998,559	\$1,125,822	\$1,302,666
	Annual Reserve Funding	\$154,028	\$159,419	\$164,999	\$170,774	\$176,751
	Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
	Interest Earnings	\$3,994	\$4,582	\$5,310	\$6,070	\$5,712
	Total Income	\$921,504	\$998,559	\$1,168,868	\$1,302,666	\$1,485,129
#	Component					
#	GROUNDS					
103	Concrete/Pavers - Repair	\$0	\$0	\$0	\$0	\$5,219
	Landscape Lights - Replace	\$0	\$0	\$0	\$0	\$0
	Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
	Mailbox Roofs - Replace	\$0	\$0	\$0	\$0	\$0
	Block Walls - Repair	\$0	\$0	\$0	\$0	\$0
	Wall Columns - Repaint	\$26,663	\$0	\$0	\$0	\$0
	View Fence - Replace	\$0	\$0	\$0	\$0	\$0
	Metal Surfaces - Repaint	\$37,097	\$0	\$0	\$0	\$0
	Monuments - Remodel	\$0	\$0	\$0	\$0	\$0
	Fountain - Remodel	\$0	\$0	\$0	\$0	\$0
	Irrigation Controllers - Replace	\$0	\$0	\$0	\$0	\$0
	Landscape Granite - Replenish	\$0	\$0	\$0	\$0	\$456,671
	Drywells - Inspect/Clean	\$0	\$0	\$0	\$0	\$18,267
	Drywells - Partial Replace	\$0	\$0	\$0	\$0	\$0
043	PARK AREAS	ΨΟ	ΨΟ	ΨΟ	ΨΟ	φυ
405	Park Furniture - Replace	\$0	\$0	\$0	\$0	\$0
	Playground Equipment - Replace	\$0	\$0	\$0	\$0	\$0
	Shade Screens - Replace	\$0	\$0	\$0	\$0	\$5,219
	Playground Turf - Replace	\$0	\$0	\$0	\$0	\$0
	Playground Mulch - Replenish	\$0	\$0	\$0	\$0	\$11,743
	Ramada Roof - Replace	\$0	\$0	\$0	\$0	\$0
	POOL AREA		, ,			
1120	Metal Fence - Replace	\$0	\$0	\$0	\$0	\$0
	Keypads - Replace	\$0	\$0	\$0	\$0	\$5,219
	Pool Area - Repaint	\$9,274	\$0	\$0	\$0	\$0
	Doors + Windows - Replace	\$0	\$0	\$0	\$0	\$0
1142	Drinking Fountains - Replace	\$0	\$0	\$0	\$0	\$0
	Shower - Remodel	\$0	\$0	\$0	\$0	\$0
1150	Restrooms - Remodel	\$0	\$0	\$0	\$0	\$0
1190	Flat Roof - Replace	\$0	\$0	\$0	\$0	\$0
1200	Pool Deck Pavers - Replace	\$0	\$0	\$0	\$0	\$0
1208	Pool - Resurface	\$0	\$0	\$0	\$0	\$0
1212	Pool Lift - Replace	\$0	\$0	\$0	\$0	\$0
1220	Pool Furniture - Replace	\$0	\$0	\$36,896	\$0	\$0
	Pool Lounge Cushions - Replace	\$0	\$0	\$6,149	\$0	\$0
	Pool Filters - Replace	\$0	\$0	\$0	\$0	\$0
	Pool Pump - Replace	\$0	\$0	\$0	\$0	\$0
	Pool Heaters - Replace	\$13,911	\$0	\$0	\$0	\$0
	Total Expenses	\$86,946	\$0	\$43,046	\$0	\$502,338
	Ending Reserve Balance	\$834,559	\$998,559	\$1,125,822	\$1,302,666	\$982,792
	Lituing Neselve Dalance	\$004,009	φ590,559	φ1,125,022	φ1,302,000	φ902,192

	Fiscal Year	2034	2035	2036	2037	2038
	Starting Reserve Balance	\$982,792	\$1,171,112	\$989,341	\$1,190,756	\$1,400,058
	Annual Reserve Funding	\$182,937	\$189,340	\$195,967	\$202,826	\$209,924
	Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
	Interest Earnings	\$5,384	\$5,400	\$5,449	\$6,476	\$6,981
'	Total Income	\$1,171,112	\$1,365,852	\$1,190,756	\$1,400,058	\$1,616,963
#	Component					
#	GROUNDS					
103	Concrete/Pavers - Repair	\$0	\$0	\$0	\$0	\$6,050
	Landscape Lights - Replace	\$0	\$110,739	\$0	\$0	\$0
	Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
	Mailbox Roofs - Replace	\$0	\$0	\$0	\$0	\$0
	Block Walls - Repair	\$0	\$0	\$0	\$0	\$0
	Wall Columns - Repaint	\$0	\$31,837	\$0	\$0	\$0
	View Fence - Replace	\$0	\$0	\$0	\$0	\$0
	Metal Surfaces - Repaint	\$0	\$44,295	\$0	\$0	\$0
	Monuments - Remodel	\$0	\$0	\$0	\$0	\$0
	Fountain - Remodel	\$0	\$0	\$0	\$0	\$18,151
	Irrigation Controllers - Replace	\$0	\$0	\$0	\$0	\$34,790
	Landscape Granite - Replenish	\$0	\$0	\$0	\$0	\$0
	Drywells - Inspect/Clean	\$0	\$0	\$0	\$0	\$21,176
	Drywells - Partial Replace	\$0	\$0	\$0	\$0	\$0
043	PARK AREAS	\$0	ΨΟ	ΨΟ	ΨΟ	φυ
405	Park Furniture - Replace	\$0	\$0	\$0	\$0	\$71,092
	Playground Equipment - Replace	\$0	\$0	\$0	\$0	\$0
	Shade Screens - Replace	\$0	\$0	\$0	\$0	\$0
	Playground Turf - Replace	\$0	\$66,443	\$0	\$0	\$0
	Playground Mulch - Replenish	\$0	\$0	\$0	\$0	\$13,613
	Ramada Roof - Replace	\$0	\$0	\$0	\$0	\$0
	POOL AREA					
1120	Metal Fence - Replace	\$0	\$0	\$0	\$0	\$0
1125	Keypads - Replace	\$0	\$0	\$0	\$0	\$0
	Pool Area - Repaint	\$0	\$11,074	\$0	\$0	\$0
1135	Doors + Windows - Replace	\$0	\$0	\$0	\$0	\$0
1142	Drinking Fountains - Replace	\$0	\$5,537	\$0	\$0	\$0
	Shower - Remodel	\$0	\$0	\$0	\$0	\$7,563
1150	Restrooms - Remodel	\$0	\$0	\$0	\$0	\$30,252
	Flat Roof - Replace	\$0	\$0	\$0	\$0	\$9,076
	Pool Deck Pavers - Replace	\$0	\$0	\$0	\$0	\$0
	Pool - Resurface	\$0	\$62,291	\$0	\$0	\$0
	Pool Lift - Replace	\$0	\$13,842	\$0	\$0	\$0
	Pool Furniture - Replace	\$0	\$0	\$0	\$0	\$0
	Pool Lounge Cushions - Replace	\$0	\$6,921	\$0	\$0	\$0
	Pool Filters - Replace	\$0	\$0	\$0	\$0	\$12,403
	Pool Pump - Replace	\$0	\$6,921	\$0	\$0	\$0
	Pool Heaters - Replace	\$0	\$16,611	\$0	\$0	\$0
	Total Expenses	\$0	\$376,512	\$0	\$0	\$224,166
	·	P4 474 440	0000 04:	04.400.753	£4.400.050	04 000 707
	Ending Reserve Balance	\$1,171,112	\$989,341	\$1,190,756	\$1,400,058	\$1,392,797

	Fiscal Year	2039	2040	2041	2042	2043
	Starting Reserve Balance	\$1,392,797	\$1,562,928	\$1,796,200	\$1,731,989	\$1,982,166
	Annual Reserve Funding	\$217,272	\$224,876	\$232,747	\$240,893	\$249,324
	Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
	Interest Earnings	\$7,388	\$8,396	\$8,819	\$9,283	\$8,230
	Total Income	\$1,617,457	\$1,796,200	\$2,037,766	\$1,982,166	\$2,239,720
#	Component					
	GROUNDS					
103	Concrete/Pavers - Repair	\$0	\$0	\$0	\$0	\$7,014
315	Landscape Lights - Replace	\$0	\$0	\$0	\$0	\$0
380	Mailboxes - Replace	\$0	\$0	\$181,813	\$0	\$0
385	Mailbox Roofs - Replace	\$0	\$0	\$0	\$0	\$0
501	Block Walls - Repair	\$0	\$0	\$0	\$0	\$0
510	Wall Columns - Repaint	\$0	\$0	\$38,015	\$0	\$0
535	View Fence - Replace	\$0	\$0	\$0	\$0	\$0
550	Metal Surfaces - Repaint	\$0	\$0	\$52,891	\$0	\$0
701	Monuments - Remodel	\$0	\$0	\$0	\$0	\$26,303
705	Fountain - Remodel	\$0	\$0	\$0	\$0	\$0
805	Irrigation Controllers - Replace	\$0	\$0	\$0	\$0	\$0
820	Landscape Granite - Replenish	\$0	\$0	\$0	\$0	\$613,727
840	Drywells - Inspect/Clean	\$0	\$0	\$0	\$0	\$24,549
845	Drywells - Partial Replace	\$0	\$0	\$0	\$0	\$0
	PARK AREAS					
	Park Furniture - Replace	\$0	\$0	\$0	\$0	\$0
	Playground Equipment - Replace	\$0	\$0	\$0	\$0	\$219,188
	Shade Screens - Replace	\$0	\$0	\$0	\$0	\$7,014
	Playground Turf - Replace	\$0	\$0	\$0	\$0	\$0
	Playground Mulch - Replenish	\$0	\$0	\$0	\$0	\$15,782
490	Ramada Roof - Replace	\$0	\$0	\$0	\$0	\$0
	POOL AREA					
	Metal Fence - Replace	\$0	\$0	\$0	\$0	\$0
	Keypads - Replace	\$0	\$0	\$0	\$0	\$7,014
	Pool Area - Repaint	\$0	\$0	\$13,223	\$0	\$0
	Doors + Windows - Replace	\$0	\$0	\$0	\$0	\$0
	Drinking Fountains - Replace	\$0	\$0	\$0	\$0	\$0
	Shower - Remodel	\$0	\$0	\$0	\$0	\$0
	Restrooms - Remodel	\$0	\$0	\$0	\$0	\$0
	Flat Roof - Replace	\$0	\$0	\$0	\$0	\$0
	Pool Deck Pavers - Replace	\$0	\$0	\$0	\$0	\$0
	Pool - Resurface	\$0	\$0	\$0	\$0	\$0
	Pool Lift - Replace	\$0	\$0	\$0	\$0	\$0
	Pool Furniture - Replace	\$46,739	\$0	\$0	\$0	\$0
	Pool Lounge Cushions - Replace	\$7,790	\$0	\$0	\$0	\$8,768
	Pool Filters - Replace	\$0	\$0	\$0	\$0	\$0
	Pool Pump - Replace	\$0	\$0	\$0	\$0	\$0
1270	Pool Heaters - Replace	\$0	\$0	\$19,834	\$0	\$0
	Total Expenses	\$54,529	\$0	\$305,777	\$0	\$929,358
	Ending Reserve Balance	\$1,562,928	\$1,796,200	\$1,731,989	\$1,982,166	\$1,310,361

	Fiscal Year	2044	2045	2046	2047	2048
	Starting Reserve Balance	\$1,310,361	\$1,575,626	\$1,851,274	\$2,137,674	\$1,837,693
	Annual Reserve Funding	\$258,051	\$267,083	\$276,430	\$286,106	\$296,119
	Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
	Interest Earnings	\$7,213	\$8,565	\$9,970	\$9,936	\$8,653
•	Total Income	\$1,575,626	\$1,851,274	\$2,137,674	\$2,433,716	\$2,142,465
#	Component					
"	GROUNDS					
103	Concrete/Pavers - Repair	\$0	\$0	\$0	\$0	\$8,131
	Landscape Lights - Replace	\$0	\$0	\$0	\$157,887	\$0
	Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
	Mailbox Roofs - Replace	\$0	\$0	\$0	\$0	\$0
	Block Walls - Repair	\$0	\$0	\$0	\$0	\$203,279
	Wall Columns - Repaint	\$0	\$0	\$0	\$45,392	\$0
	View Fence - Replace	\$0	\$0	\$0	\$0	\$0
	Metal Surfaces - Repaint	\$0	\$0	\$0	\$63,155	\$0
	Monuments - Remodel	\$0	\$0	\$0	\$0	\$0
	Fountain - Remodel	\$0	\$0	\$0	\$0	\$0
	Irrigation Controllers - Replace	\$0	\$0	\$0	\$0	\$0
	Landscape Granite - Replenish	\$0	\$0	\$0	\$0	\$0
	Drywells - Inspect/Clean	\$0	\$0	\$0	\$0	\$28,459
	Drywells - Partial Replace	\$0	\$0	\$0	\$0	\$0
0.10	PARK AREAS	Ψ	ţ.	40	ţ.	+
405	Park Furniture - Replace	\$0	\$0	\$0	\$0	\$0
	Playground Equipment - Replace	\$0	\$0	\$0	\$0	\$0
	Shade Screens - Replace	\$0	\$0	\$0	\$0	\$0
	Playground Turf - Replace	\$0	\$0	\$0	\$94,732	\$0
	Playground Mulch - Replenish	\$0	\$0	\$0	\$0	\$18,295
	Ramada Roof - Replace	\$0	\$0	\$0	\$0	\$0
	POOL AREA					
1120	Metal Fence - Replace	\$0	\$0	\$0	\$0	\$56,918
1125	Keypads - Replace	\$0	\$0	\$0	\$0	\$0
1130	Pool Area - Repaint	\$0	\$0	\$0	\$15,789	\$0
1135	Doors + Windows - Replace	\$0	\$0	\$0	\$0	\$0
1142	Drinking Fountains - Replace	\$0	\$0	\$0	\$7,894	\$0
1145	Shower - Remodel	\$0	\$0	\$0	\$0	\$0
1150	Restrooms - Remodel	\$0	\$0	\$0	\$0	\$0
1190	Flat Roof - Replace	\$0	\$0	\$0	\$0	\$0
1200	Pool Deck Pavers - Replace	\$0	\$0	\$0	\$0	\$203,279
4000						PO
1208	Pool - Resurface	\$0	\$0	\$0	\$88,811	\$0
	Pool - Resurface Pool Lift - Replace	\$0 \$0	\$0 \$0	\$0 \$0	\$88,811 \$19,736	\$0 \$0
1212		·				
1212 1220	Pool Lift - Replace	\$0	\$0	\$0	\$19,736	\$0
1212 1220 1222	Pool Lift - Replace Pool Furniture - Replace	\$0 \$0	\$0 \$0	\$0 \$0	\$19,736 \$59,208	\$0 \$0
1212 1220 1222 1250	Pool Lift - Replace Pool Furniture - Replace Pool Lounge Cushions - Replace	\$0 \$0 \$0	\$0 \$0 \$0	\$0 \$0 \$0	\$19,736 \$59,208 \$9,868	\$0 \$0 \$0
1212 1220 1222 1250 1260	Pool Lift - Replace Pool Furniture - Replace Pool Lounge Cushions - Replace Pool Filters - Replace	\$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0	\$19,736 \$59,208 \$9,868 \$0	\$0 \$0 \$0 \$0
1212 1220 1222 1250 1260	Pool Lift - Replace Pool Furniture - Replace Pool Lounge Cushions - Replace Pool Filters - Replace Pool Pump - Replace	\$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0	\$19,736 \$59,208 \$9,868 \$0 \$9,868	\$0 \$0 \$0 \$0 \$0

	Fiscal Year	2049	2050	2051	2052	2053
	Starting Reserve Balance	\$1,624,102	\$1,897,512	\$2,225,027	\$2,554,179	\$2,907,634
	Annual Reserve Funding	\$306,483	\$317,210	\$328,313	\$339,804	\$351,697
	Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
	Interest Earnings	\$8,802	\$10,304	\$11,946	\$13,652	\$10,125
•	Total Income	\$1,939,388	\$2,225,027	\$2,565,285	\$2,907,634	\$3,269,456
#	Component					
"	GROUNDS					
103	Concrete/Pavers - Repair	\$0	\$0	\$0	\$0	\$9,426
	Landscape Lights - Replace	\$0	\$0	\$0	\$0	\$0
	Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
	Mailbox Roofs - Replace	\$0	\$0	\$0	\$0	\$11,783
	Block Walls - Repair	\$0	\$0	\$0	\$0	\$0
	Wall Columns - Repaint	\$0	\$0	\$0	\$0	\$54,201
	View Fence - Replace	\$0	\$0	\$0	\$0	\$648,056
	Metal Surfaces - Repaint	\$0	\$0	\$0	\$0	\$75,410
	Monuments - Remodel	\$0	\$0	\$0	\$0	\$0
	Fountain - Remodel	\$0	\$0	\$0	\$0	\$28,279
	Irrigation Controllers - Replace	\$0	\$0	\$0	\$0	\$54,201
	Landscape Granite - Replenish	\$0	\$0	\$0	\$0	\$824,798
	Drywells - Inspect/Clean	\$0	\$0	\$0	\$0	\$32,992
	Drywells - Partial Replace	\$0	\$0	\$0	\$0	\$58,914
0.10	PARK AREAS	Ψ	ţ.	ţ.	ţ.	φοσ,σ τ τ
405	Park Furniture - Replace	\$0	\$0	\$0	\$0	\$110,759
	Playground Equipment - Replace	\$0	\$0	\$0	\$0	\$0
	Shade Screens - Replace	\$0	\$0	\$0	\$0	\$9,426
	Playground Turf - Replace	\$0	\$0	\$0	\$0	\$0
	Playground Mulch - Replenish	\$0	\$0	\$0	\$0	\$21,209
	Ramada Roof - Replace	\$41,876	\$0	\$0	\$0	\$0
	POOL AREA	, ,				
1120	Metal Fence - Replace	\$0	\$0	\$0	\$0	\$0
1125	Keypads - Replace	\$0	\$0	\$0	\$0	\$9,426
1130	Pool Area - Repaint	\$0	\$0	\$0	\$0	\$18,853
1135	Doors + Windows - Replace	\$0	\$0	\$0	\$0	\$37,705
1142	Drinking Fountains - Replace	\$0	\$0	\$0	\$0	\$0
1145	Shower - Remodel	\$0	\$0	\$0	\$0	\$11,783
1150	Restrooms - Remodel	\$0	\$0	\$0	\$0	\$47,131
1190	Flat Roof - Replace	\$0	\$0	\$0	\$0	\$14,139
1200	Pool Deck Pavers - Replace	\$0	\$0	\$0	\$0	\$0
1208	Pool - Resurface	\$0	\$0	\$0	\$0	\$0
1212	Pool Lift - Replace	\$0	\$0	\$0	\$0	\$0
1220	Pool Furniture - Replace	\$0	\$0	\$0	\$0	\$0
1222	Pool Lounge Cushions - Replace	\$0	\$0	\$11,106	\$0	\$0
	Pool Filters - Replace	\$0	\$0	\$0	\$0	\$19,324
	Pool Pump - Replace	\$0	\$0	\$0	\$0	\$0
	Pool Heaters - Replace	\$0	\$0	\$0	\$0	\$28,279
•	Total Expenses	\$41,876	\$0	\$11,106	\$0	\$2,126,093
	Ending Reserve Balance	\$1,897,512	\$2,225,027	\$2,554,179	\$2,907,634	\$1,143,362

Accuracy, Limitations, and Disclosures

Association Reserves and its employees have no ownership, management, or other business relationships with the client other than this Reserve Study engagement. DJ Vlaming, R.S., company president, is a credentialed Reserve Specialist (#61). All work done by Association Reserves is performed under his Responsible Charge and is performed in accordance with National Reserve Study Standards (NRSS). There are no material issues to our knowledge that have not been disclosed to the client that would cause a distortion of the client's situation.

Per NRSS, information provided by official representative(s) of the client, vendors, and suppliers regarding financial details, component physical details and/or quantities, or historical issues/conditions will be deemed reliable, and is not intended to be used for the purpose of any type of audit, quality/forensic analysis, or background checks of historical records. As such, information provided to us has not been audited or independently verified.

Estimates for interest and inflation have been included, because including such estimates are more accurate than ignoring them completely. When we are hired to prepare Update reports, the client is considered to have deemed those previously developed component quantities as accurate and reliable, whether established by our firm or other individuals/firms (unless specifically mentioned in our Site Inspection Notes). During inspections our company standard is to establish measurements within 5% accuracy, and our scope includes visual inspection of accessible areas and components and does not include any destructive or other testing. Our work is done only for budget purposes. Uses or expectations outside our expertise and scope of work include, but are not limited to, project audit, quality inspection, and the identification of construction defects, hazardous materials, or dangerous conditions. Identifying hidden issues such as but not limited to plumbing or electrical problems are also outside our scope of work. Our estimates assume proper original installation & construction, adherence to recommended preventive maintenance, a stable economic environment, and do not consider frequency or severity of natural disasters. Our opinions of component Useful Life, Remaining Useful Life, and current or future cost estimates are not a warranty or guarantee of actual costs or timing.

Because the physical and financial status of the property, legislation, the economy, weather, owner expectations, and usage are all in a continual state of change over which we have no control, we do not expect that the events projected in this document will all occur exactly as planned. This Reserve Study is by nature a "one-year" document in need of being updated annually so that more accurate estimates can be incorporated. It is only because a long-term perspective improves the accuracy of near-term planning that this Report projects expenses into the future. We fully expect a number of adjustments will be necessary through the interim years to the cost and timing of expense projections and the funding necessary to prepare for those estimated expenses.

In this engagement our compensation is not contingent upon our conclusions, and our liability in any matter involving this Reserve Study is limited to our fee for services rendered.



Terms and Definitions

BTU British Thermal Unit (a standard unit of energy)

DIA Diameter

GSF Gross Square Feet (area). Equivalent to Square Feet

GSY Gross Square Yards (area). Equivalent to Square Yards

HP Horsepower

LF Linear Feet (length)

Effective Age The difference between Useful Life and Remaining Useful Life.

Note that this is not necessarily equivalent to the chronological

age of the component.

Fully Funded Balance (FFB) The value of the deterioration of the Reserve Components.

This is the fraction of life "used up" of each component multiplied by its estimated Current Replacement. While calculated for each component, it is summed together for an

association total.

Inflation Cost factors are adjusted for inflation at the rate defined in the

Executive Summary and compounded annually. These

increasing costs can be seen as you follow the recurring cycles of a component on the "30-yr Income/Expense Detail" table.

Interest earnings on Reserve Funds are calculated using the

average balance for the year (taking into account income and expenses through the year) and compounded monthly using the rate defined in the Executive Summary. Annual interest earning assumption appears in the Executive Summary.

Percent Funded The ratio, at a particular point in time (the first day of the Fiscal

Year), of the actual (or projected) Reserve Balance to the Fully

Funded Balance, expressed as a percentage.

Remaining Useful Life (RUL) The estimated time, in years, that a common area component

can be expected to continue to serve its intended function.

Useful Life (UL) The estimated time, in years, that a common area component

can be expected to serve its intended function.

Component Details

The primary purpose of the Component Details appendix is to provide the reader with the basis of our funding assumptions resulting from the physical analysis and subsequent research. The information presented here represents a wide range of components that were observed and measured against National Reserve Study Standards to determine if they meet the criteria for reserve funding:

- 1) Common area repair & replacement responsibility
- 2) Component must have a limited useful life
- 3) Life limit must be predictable
- 4) Above a minimum threshold cost (board's discretion typically ½ to 1% of Annual operating expenses).

Not all of your components may have been found appropriate for reserve funding. In our judgment, the components meeting the above four criteria are shown with the Useful Life (how often the project is expected to occur), Remaining Useful Life (when the next instance of the expense will be) and representative market cost range termed "Best Cost" and "Worst Cost". There are many factors that can result in a wide variety of potential costs, and we have attempted to present the cost range in which your actual expense will occur.

Where no Useful Life, Remaining Useful Life, or pricing exists, the component was deemed inappropriate for Reserve Funding.

GROUNDS

Quantity: Numerous Sq Ft

Quantity: Numerous Sq Ft

Comp #: 103 Concrete/Pavers - Repair

Location: Common walkways; Landscape curbing

Funded?: Yes.

History: Primarily installed in 2023.

Comments: There is no expectancy to completely replace the concrete or walkway pavers. This component funds an allowance

for periodic repairs and partial replacements as needed.

Useful Life: 5 years

Remaining Life: 4 years



Best Case: \$ 4,000 Worst Case: \$ 4,000

Cost Source: AR Cost Allowance

Comp #: 201 Asphalt - Repave

Location: Streets throughout community

Funded?: No. Streets are public and not the responsibility of the HOA to maintain.

History: Primarily installed in 2023.

Comments:

Useful Life:

Remaining Life:



Best Case: Worst Case:

Cost Source:

Comp #: 260 Street Lights - Replace

Location: Adjacent to streets throughout community

Funded?: No. We assume the street lights are owned and maintained by the city or power company, not the HOA. Should the

Quantity: Numerous Street Lights

Quantity: Approx (270) Fixtures

HOA notify us otherwise, Reserve funding can be added for the street lights.

History: Primarily installed in 2023.

Comments:

Useful Life:

Remaining Life:



Best Case: Worst Case:

Cost Source:

Comp #: 315 Landscape Lights - Replace

Location: Common areas throughout community, including the pool area

Funded?: Yes.

History: Primarily installed in 2023.

Comments: Complete replacement should be expected eventually to update the appearance and maintain uniformity.

Useful Life: 12 years

Remaining Life: 11 years



Best Case: \$80,000 Worst Case: \$80,000

Cost Source: AR Cost Database

Comp #: 380 Mailboxes - Replace

Location: Adjacent to streets throughout community

Funded?: Yes.

History: Primarily installed in 2023.

Comments: Manufactured by Florence Corporation. We located (14) 17-box clusters during our inspection in 2023. We assume another approximately (10) more clusters will be installed during 2023-2024. Model: 4C15D-17, Mfg. Date: 10/2021.

Quantity: Approx (24) Clusters

Quantity: (3) Roofs: ~250 Sq Ft

Useful Life: 18 years

Remaining Life: 17 years



Best Case: \$ 110,000 Worst Case: \$ 110,000

Cost Source: Research at www.FlorenceMailboxes.com

Comp #: 385 Mailbox Roofs - Replace

Location: Adjacent to streets throughout community - Mailbox kiosk rooftops

Funded?: Yes

History: Primarily installed in 2023.

Comments: These metal roofs have a long life span anticipated under normal circumstances. It would still be prudent to plan for

replacement at some point.

Useful Life: 30 years

Remaining Life: 29 years



Best Case: \$5,000 Worst Case: \$5,000

Cost Source: AR Cost Database

Comp #: 501 Block Walls - Repair

Location: Bordering common areas throughout community, including mailbox kiosks

Funded?: Yes.

History: Installation began in 2022 and will be completed during 2023-2024.

Comments: Walls are expected to last the life of the community under normal circumstances. This component funds an allowance

Quantity: Approx 90,000 Sq Ft

Quantity: Approx 90,000 Sq Ft

for repairs and/or partial replacement due to excessive settling or other sources of damage.

Useful Life: 25 years

Remaining Life: 24 years



Best Case: \$ 100,000 Worst Case: \$ 100,000

Cost Source: AR Cost Database

Comp #: 505 Block Walls - Repaint

Location: Bordering common areas throughout community, including mailbox kiosks

Funded?: No. These are unpainted block walls. No Reserve funding has been allocated to paint them.

History: Comments:

Useful Life:

Remaining Life:



Best Case: Worst Case:

Cost Source:

Comp #: 510 Wall Columns - Repaint

Location: Bordering common areas throughout community

Funded?: Yes.

History: Installation began in 2022 and will be completed during 2023-2024.

Comments: There are approximately (158) stucco wall columns and (54) columns with 2 decorative metal panels mounted to each

Quantity: Approx (212) Columns

Quantity: Approx 3,200 LF

of them. Periodic repainting should be anticipated to maintain the appearance and to keep the surfaces properly sealed.

Useful Life: 6 years

Remaining Life: 5 years



Best Case: \$ 23,000 Worst Case: \$ 23,000

Cost Source: AR Cost Database

Comp #: 535 View Fence - Replace

Location: Bordering common areas throughout community

Funded?: Yes.

History: Installation began in 2022 and will be completed during 2023-2024.

Comments: This view fence is approximately 6' tall and mounted in-ground. This component funds for complete replacement

eventually.

Useful Life: 30 years

Remaining Life: 29 years



Best Case: \$ 275,000 Worst Case: \$ 275,000

Cost Source: AR Cost Database

Comp #: 550 Metal Surfaces - Repaint

Location: Common areas throughout community - View fence, culvert rails, metal pergolas & panels at community monuments, ramada

Quantity: Numerous Sq Ft

Quantity: (2) Monuments

Funded?: Yes.

History: Installation began in 2022 and will be completed during 2023-2024.

Comments: Repaint periodically to inhibit rusting and maintain the appearance and to inhibit rust.

Useful Life: 6 years

Remaining Life: 5 years



Best Case: \$ 32,000 Worst Case: \$ 32,000

Cost Source: AR Cost Database

Comp #: 701 Monuments - Remodel

Location: North entrance to community - Off E Germann Rd

Funded?: Yes.

History: Installed in 2023.

Comments: There are (2) backlit monument signs. Observed to be modern and in nice shape. Remodel should be expected eventually to update and modernize the appearance.

Useful Life: 20 years

Remaining Life: 19 years



Best Case: \$ 15,000 Worst Case: \$ 15,000

Cost Source: AR Cost Database

Comp #: 705 Fountain - Remodel

Location: North entrance to community - Off E Germann Rd

Funded?: Yes.

History: Installed in 2023.

Comments: This component funds to eventually remodel the fountain. This would include replacing the tile surfaces, light, and metal spillway. Observed to be in nice shape. The submerged pump is inexpensive and should be replaced as an Operating

Quantity: (1) Fountain: ~50 LF

Quantity: Lines, Valves, Sprinklers

expense when needed.

Useful Life: 15 years

Remaining Life: 14 years



Best Case: \$ 12,000 Worst Case: \$ 12,000

Cost Source: AR Cost Database

Comp #: 801 Irrigation System - Replace

Location: Common areas throughout community

Funded?: No. We assume system will be repaired as-needed using Operating funds.

History: Primarily installed in 2023.

Comments: It is beyond the scope of this Reserve Study to quantify and assess conditions of the irrigation system components. Funding for replacement of the system can be added to this study at the HOA's request, but we would need to be provided with cost and timing estimates.

Useful Life:

Remaining Life:



Best Case: Worst Case:

Cost Source:

Comp #: 805 Irrigation Controllers - Replace

Location: Common areas throughout community

Funded?: Yes.

History: Primarily installed in 2023.

Comments: We located (2) WeatherTrak Pro3 controllers during our inspection in 2023. We assume (1) more controller will be

Quantity: (3) WeatherTrak Pro3

Quantity: Approx (4) Valves

installed during 2023-2024. Future replacement should be anticipated.

Useful Life: 15 years

Remaining Life: 14 years



Best Case: \$ 23,000 Worst Case: \$ 23,000

Cost Source: AR Cost Database

Comp #: 808 Backflow Valves - Replace

Location: Common areas throughout community

Funded?: No. Individual replacement cost is under the Reserve threshold.

History: Primarily installed in 2023.

Comments: We located (3) backflow valves during our inspection in 2023. We assume (1) more valve will be installed during

2023-2024.

Useful Life:

Remaining Life:



Best Case: Worst Case:

Cost Source:

Comp #: 820 Landscape Granite - Replenish

Location: Common areas throughout community, including streetscapes

Funded?: Yes.

History: Primarily installed in 2023.

Comments: There is no expectancy for complete replacement. Funding is provided to eventually top-dress with a new 1" layer.

Quantity: Approx 4,300 Tons

Quantity: Numerous Trees

Useful Life: 10 years

Remaining Life: 9 years



Best Case: \$ 350,000 Worst Case: \$ 350,000

Cost Source: AR Cost Database

Comp #: 830 Trees - Trim/Replace

Location: Common areas throughout community

Funded?: No. Trees should be trimmed and maintained as part of the annual landscape Operating budget.

History: Primarily installed in 2023.

Comments:

Useful Life:

Remaining Life:



Best Case: Worst Case:

Cost Source:

Comp #: 840 Drywells - Inspect/Clean

Location: Drainage areas throughout community

Funded?: Yes.

History: Primarily installed in 2023.

Comments: We located (21) drywells during our inspection in 2023. We assume another approximately (7) more drywells will be installed during 2023-2024. Periodic inspection and cleaning should be anticipated to ensure proper function and longevity.

Quantity: Approx (28) Drywells

Quantity: Approx (28) Drywells

Useful Life: 5 years

Remaining Life: 4 years



Best Case: \$ 14,000 Worst Case: \$ 14,000

Cost Source: AR Cost Database

Comp #: 845 Drywells - Partial Replace

Location: Drainage areas throughout community

Funded?: Yes.

History: Primarily installed in 2023.

Comments: There is no expectancy to replace drywells under normal circumstances. Replacement is usually the result of improper

 $installation\ or\ neglect.\ This\ component\ provides\ an\ allowance\ for\ partial\ replacement\ in\ the\ \underline{e}vent\ failure\ does\ occur.$

Useful Life: 30 years

Remaining Life: 29 years



Best Case: \$ 25,000 Worst Case: \$ 25,000

Cost reflects replacing (1) drywell

PARK AREAS

Comp #: 405 Park Furniture - Replace

Location: Playground area - Southeast of the pool; Common tract at southeast portion of community; Adjacent to the community

Quantity: (17) Assorted Pieces

Quantity: (12) Assorted Pieces

monuments; Pool area

Funded?: Yes.

History: Primarily installed in 2023.

Comments: Manufactured by Wabash Valley. Pieces include (8) picnic tables, (4) benches, and (5) trash receptacles. Good conditions noted. Future replacement should be anticipated.

Useful Life: 15 years

Remaining Life: 14 years



Best Case: \$ 47,000 Worst Case: \$ 47,000

Cost Source: AR Cost Database

Comp #: 410 Playground Equipment - Replace

Location: Playground area - Southeast of the pool

Funded?: Yes.

History: Installed in 2023.

Comments: Manufactured by Landscape Structures. Pieces include (1) playstructure, (1) zip line, (1) single seat swingset, (1) teeter-totter, (1) 3-arc piece, and (7) climbing balls. Good conditions noted. Future replacement should be anticipated.

Useful Life:

20 years

Remaining Life: 19 years



Best Case: \$ 125,000 Worst Case: \$ 125,000

Comp #: 415 Shade Screens - Replace

Location: Playground area - Southeast of the pool

Funded?: Yes.

History: Installed in 2023.


Comments: Observed to be intact and in nice shape. This component funds for future replacement of the shade screen fabric.

Quantity: (2) Screens: ~500 Sq Ft

Quantity: Approx 1,600 Sq Ft

Useful Life: 10 years

Remaining Life: 9 years



Best Case: \$ 4,000 Worst Case: \$ 4,000

Cost Source: AR Cost Database

Comp #: 420 Playground Turf - Replace

Location: Playground area - Southeast of the pool

Funded?: Yes.

History: Installed in 2023.

Comments: Rubberized turf appears intact and in good shape. This component funds for future replacement.

Useful Life: 12 years

Remaining Life: 11 years



Best Case: \$48,000 Worst Case: \$48,000

Comp #: 425 Playground Mulch - Replenish

Location: Playground area - Southeast of the pool

Funded?: Yes.

History: Installed in 2023.

Comments: There is no expectancy to completely replace the wood mulch surface. HOA should expect to top dress/replenish it

Quantity: Approx 3,500 Sq Ft

Quantity: (1) Roof: ~1,000 Sq Ft

periodically to maintain proper surfacing depths.

Useful Life: 5 years

Remaining Life: 4 years



Best Case: \$ 9,000 Worst Case: \$ 9,000

Cost Source: AR Cost Database

Comp #: 490 Ramada Roof - Replace

Location: Common tract at southeast portion of community

Funded?: Yes.

History: Installation is expected to be completed during 2023-2024.

No Photo Available

Comments: Ramada was not installed as-of our inspection in 2023. Long life component under normal circumstances. It would still

be prudent to plan for replacement eventually.

Useful Life: 25 years

Remaining Life: 25 years

Best Case: \$ 20,000 Worst Case: \$ 20,000

POOL AREA

Quantity: Approx 275 LF

Quantity: (4) Keypads

Comp #: 1120 Metal Fence - Replace

Location: Pool area Funded?: Yes.

History: Installed in 2023.

Comments: Observed to be stable and secure. This component funds for future replacement.

Useful Life: 25 years

Remaining Life: 24 years



Best Case: \$ 28,000 Worst Case: \$ 28,000

Cost Source: AR Cost Database

Comp #: 1125 Keypads - Replace

Location: Pool area - (2) metal fence & (2) pool building exterior

Funded?: Yes.

History: Installed in 2023.

Comments: Observed to be functional and in good shape. Future replacement should be anticipated.

Useful Life: 10 years

Remaining Life: 9 years



Best Case: \$ 4,000 Worst Case: \$ 4,000

Comp #: 1130 Pool Area - Repaint

Location: Pool area - Metal fence, metal pergola, pool building stucco

Funded?: Yes.

History: Surfaces are original from 2023.

Comments: Surfaces appear uniform and in good shape. Repaint periodically to maintain the appearance and to keep the

Quantity: Fence, Pergola, Stucco

Quantity: (3) Doors, (10) Windows

surfaces properly sealed.

Useful Life: 6 years

Remaining Life: 5 years



Best Case: \$ 8,000 Worst Case: \$ 8,000

Cost Source: AR Cost Database

Comp #: 1135 Doors + Windows - Replace

Location: Pool area - Pool building exterior

Funded?: Yes.

History: Installed in 2023.

Comments: Long life expectancy anticipated under normal circumstances. It would still be prudent to plan for replacement at some

point.

Useful Life: 30 years

Remaining Life: 29 years



Best Case: \$ 16,000 Worst Case: \$ 16,000

Comp #: 1142 Drinking Fountains - Replace

Location: Pool area - Pool building exterior

Funded?: Yes.

History: Installed in 2023.

Comments: Good conditions noted. Future replacement should be anticipated. Model: F140PM-001, Serial: 2240001129 &

Quantity: (2) Oasis

Quantity: (1) Dual Shower

2240001130.

Useful Life: 12 years

Remaining Life: 11 years



Best Case: \$ 4,000 Worst Case: \$ 4,000

Cost Source: AR Cost Database

Comp #: 1145 Shower - Remodel

Location: Pool area - Pool building exterior

Funded?: Yes.

History: Installed in 2023.

Comments: This component funds to eventually remodel the dual shower by replacing the wall tiles, bench, and fixtures.

Observed to be modern and in nice shape.

Useful Life: 15 years

Remaining Life: 14 years



Best Case: \$5,000 Worst Case: \$5,000

Comp #: 1150 Restrooms - Remodel

Location: Pool area - Pool building interior

Funded?: Yes.

History: Installed in 2023.

Comments: This component funds to eventually remodel the restrooms by replacing the tile surfaces, fixtures, lights, paint, etc.

Quantity: (2) Restrooms: ~250 Sq Ft

Quantity: (1) RUUD

Observed to be modern and in nice shape.

Useful Life: 15 years

Remaining Life: 14 years



Best Case: \$ 20,000 Worst Case: \$ 20,000

Cost Source: AR Cost Database

Comp #: 1155 Water Heater - Replace

Location: Pool area - Pool building interior (pool equipment room) Funded?: No. Replacement cost is under the Reserve threshold.

History: Installed in 2023.

Comments:

Useful Life:

Remaining Life:



Best Case: Worst Case:

Cost Source:

Comp #: 1190 Flat Roof - Replace

Location: Pool area - Pool building rooftop

Funded?: Yes.

History: Installed in 2023.

Comments: Good conditions noted. Roof appears intact and free of debris. Future replacement should be anticipated.

Quantity: Approx 800 Sq Ft

Quantity: Approx 4,400 Sq Ft

Useful Life: 15 years

Remaining Life: 14 years



Best Case: \$ 6,000 Worst Case: \$ 6,000

Cost Source: AR Cost Database

Comp #: 1200 Pool Deck Pavers - Replace


Location: Pool area Funded?: Yes.

History: Installed in 2023.

Comments: This component funds to eventually replace the pool deck pavers, including the pool coping. Observed to be intact and in nice shape. Long life component under normal circumstances, however future replacement should still be anticipated.

Useful Life: 25 years

Remaining Life: 24 years



Best Case: \$ 100,000 Worst Case: \$ 100,000

Comp #: 1208 Pool - Resurface

Location: Pool area Funded?: Yes.

History: Installed in 2023.

Comments: Surfaces are pebble sheen with waterline tiles. Observed to be in good shape. Expect to resurface and retile the pool

Quantity: (1) Pool: ~255 LF

Quantity: (1) Aqua Creek

in the future.

Useful Life: 12 years

Remaining Life: 11 years



Best Case: \$45,000 Worst Case: \$45,000

Cost Source: AR Cost Database

Comp #: 1212 Pool Lift - Replace

Location: Pool area Funded?: Yes.

History: Installed in 2023.

Comments: Assumed to be functional and in good shape. Scout Excel, Model: F-SCTXL-C, Serial: 43772, Mfg. Date: 08/2022.

Useful Life: 12 years

Remaining Life: 11 years



Best Case: \$ 10,000 Worst Case: \$ 10,000

Comp #: 1220 Pool Furniture - Replace

Location: Pool area Funded?: Yes.

History: Installed in 2023.

Comments: Pieces include (19) lounges, (32) chairs, (8) dining tables, (10) tea tables, and (3) umbrellas. Good conditions noted.

Quantity: (72) Assorted Pieces

Quantity: (19) Cushions

Future replacement should be anticipated.

Useful Life: 8 years

Remaining Life: 7 years



Best Case: \$ 30,000 Worst Case: \$ 30,000

Add lounge cushions cost for total

Cost Source: AR Cost Database

Comp #: 1222 Pool Lounge Cushions - Replace

Location: Pool area Funded?: Yes.

History: Installed in 2023.

Comments: This component funds for periodic replacement of the lounge cushions.

Useful Life: 4 years

Remaining Life: 3 years



Best Case: \$5,000 Worst Case: \$5,000

Comp #: 1250 Pool Filters - Replace

Location: Pool area - Pool building interior

Funded?: Yes.

History: Installed in 2023.

Comments: Appear clean and well protected. Future replacement should be anticipated. Mfg. Date: 08/2022.

Useful Life: 15 years

Remaining Life: 14 years



Quantity: (3) TR100C

Quantity: (1) Whisper-Flo XF, 5-HP

Best Case: \$ 8,200 Worst Case: \$ 8,200

Cost Source: AR Cost Database

Comp #: 1260 Pool Pump - Replace

Location: Pool area - Pool building interior

Funded?: Yes.

History: Installed in 2023.

 $Comments: Appears \ functional \ and \ in \ good \ shape. \ This \ component \ funds \ for \ future \ replacement. \ P/N: \ 022035, \ Serial:$

0342199220012Y, Mfg. Date: 07/2022.

Useful Life: 12 years

Remaining Life: 11 years



Best Case: \$ 5,000 Worst Case: \$ 5,000

Comp #: 1270 Pool Heaters - Replace

Location: Pool area - Pool building interior

Funded?: Yes.

History: Installed in 2023.

Comments: Appear clean and functional. Future replacement should be anticipated. P/N: 461021, Mfg. Date: 08/2022.

Quantity: (2) MasterTemp 400

Useful Life: 6 years

Remaining Life: 5 years



Best Case: \$ 12,000 Worst Case: \$ 12,000