MCU

File: STM32G474.kicad_sch

SX1262 and Peripherals

File: SX1262-Perip.kicad_sch


Motor controller


File: motor controller.kicad_sch

Power supply


File: PS.kicad_sch


Sheet: /
File: clarnex123.kicad_sch
Title:
Size: A1 | Date: | Rev:
KiCad E.D.A. 9.0.6 | Id: 1/5






Sheets: /Power supply/		
File: PS.kicad_sch		
Title:		
Size: A1	Date:	**Rev:**
KiCad E.D.A. 9.0.6		Id: 2/5









Sheet: /MCU/		
File: STM32G474.kicad_sch		
Title:		
Size: A1	Date:	**Rev:**
KiCad E.D.A. 9.0.6		Id: 3/5

Therefore a low cycle of at least 3µs has to be applied after fault condition is removed to one or both of the ENx pins. entrambi i pin hanno già pull down interni



Sheet: /Motor controller/		
File: motor controller.kicad_sch		
Title:		
Size: A1	Date:	Rev:
KiCad E.D.A. 9.0.6		Id: 3/5



Sheets: /SX1262 and Peripherals/		
File: SX1262-Perip.kicad_sch		
Title:		
Size: A1	Date:	**Rev:**
KiCad E.D.A. 9.0.6		Id: 4/5