


1 2 3 4 5 6 7 8

Assembly stack height schematic diagram




HOW TO MATE AND EXTRACT

MATE: ① → ④

EXTRACT: ⑤ → ⑥

NOTE: Mating force will generate from step 3 to step 4.



GENERAL TOLERANCES UNLESS SPECIFIED		PART NO.	SEE TABLE
X± 0.03	X°± 3°		Lian Xin Technology
XX± 0.25	X°± 2°	AP-PC1017	

连欣科技
Lian Xin Technology
0.5 PITCH M.2 H4.2 (KEY M)

CUSTOMER DRAWING	CHECKED BY	DRAWN BY	DWG NO.
A4 MM[英寸]	Vito 11/17/14	11/17/14	AP-PC1017

A

B


C

D

E

F

1 2 3 4 5 6 7 8






1 | 2 | 3 | 4 | 5 | 6 | 7 | 8




PULL OUT DIRECTION →

PEELING ANGLE
165°~180°

WEEDING
THE COVER TAPE



PULL OUT DIRECTION



GENERAL TOLERANCES UNLESS SPECIFIED		PART NO.	
X ±	0.05	X ±	3°
JXX ± 0.25	X ± 2°	APPROVED BY	TITLE
JXX ± 0.15	X ± 1°	Barney	0.6 PITCH M2H4.2(KEY M)
CUSTOMER DRAWING	CHECKED BY	DWG NO.	AP-APCI0107
A4	Vito	11/17/14	
SIZE	UNITS	DRAWN BY	
A4	MM [INCH]	Lxh	
6		11/17/14	
7			
8			