Types of impurities	on the basis	of number	of valance e	electrons u	sed to dope	extrinsic
semi conductors						

- Tri valent
- Penta valent

# Cause of doping of extrinsic semi conductors in

Increase electrical conductivity

#### **Extrinsic semi conductors**

Pure semi conductors doped with tri valent or penta valent impurities

### Source for formation of extrinsic semi conductors

Pure semiconductors

# **Doping in semi conductors**

Add impurity atom in pure semi conductor

# Ratio of impurity atom to semi conductor atoms in extrinsic semi conductors

 $1:10^{8}$ 

#### Basis of division of extrinsic semi conductors

Nature of impurity

#### List of division of extrinsic semi conductors

- N type
- P type