WindGauge (stepper edition): wiring for the ESP32-C3 Super Mini

Same pins as the pressure and temperature gauges: motor GPIO4 / 3 / 1 / 0, hall sensor GPIO7, LEDs GPIO10. Everything runs from the 5V pin (USB power), all grounds common.



84 LEDs in the sketch (NUM_LEDS). GPIO2, 8 and 9 are strapping pins: left free. Optional: KY-003 + to GPIO5 instead of 5V, so it is powered only while homing.