




# 1. Scissors Robot



## Scissors Robot



1



X 1




X 1

DC Shaft X 1



Note the assembly position.



2




X 1



DC Shaft X 1




X 1




3




(S) X 2




4



5



6



7




8



X 1




X 1



9




X 1



10



X 2




11



X 1



X 1



12




X 1



X 1




(S) X 1



13




(S) X 2



14



X 1



15




X 2



X 1




X 1



16




X 1



18



X 1



17



X 1




X 2



X 1




X 1




19



X 2



(S) X 2



ucrobot@ucrobot.com

20

300000C X 2


3000C X 2

Screw (L) X 2

Nut X 1


Nut X 2

Nut X 1



Note the frame's positions.  
Do not fasten tightly for free rotation.

22




21

300000C X 1



23

Screw (L) X 1



Do not fasten tightly for free rotation.

ucrobot@ucrobot.com

24

30000OC X 2

3000OC X 2

30000C X 1

Screw (L) X 2

Screw X 1


Nut X 1

Nut (L) X 2




Note the frame's positions.  
Do not fasten tightly for free rotation.

26



25

Screw (L) X 1



Do not fasten tightly for free rotation.


27




Buzzer X 1




IR-PTR X 2



Finish



## Part List



X 1



X 2



X 2



X 1



X 4




X 4



X 2



X 2



X 4



X 2



X 2



X 2



X 4



X 4



X 2



DC Shaft X 2



X 2



X 4



Buzzer X 1



IR-PTR X 2



X 4



(L) X 6



(S) X 12



X 4



X 2