

#27

CSETI
COPY

PERSONNEL STATEMENT

FEDERAL AVIATION ADMINISTRATION
Anchorage Air Route Traffic Control Center

January 6, 1987

The following is a report concerning the incident to Japan Airlines Flight 1628 (JL1628) North of Fairbanks, Alaska on November 18, 1986 at 0218 UTC.

My name is [REDACTED] (HC). I am employed as an Air Traffic Control Specialist by the Federal Aviation Administration at the Anchorage Air Route Traffic Control Center (ARTCC), Anchorage, Alaska.

During the period of 2030 UTC, November 18, 1986, to 0430 UTC, November 18, 1986 I was on duty in the Anchorage ARTCC. I was working the R/D15 position from 0156 UTC, November 18, 1986 to 0230 UTC, and the R15 position from 0230 UTC, November 18, 1986 to 0258 UTC, November 18, 1986.

I am making this statement to clarify certain points in my original statement dated November 19, 1986.

Ref paragraph 4:

I stated in paragraph four that several times I had several primary returns where JL1628 reported traffic; in actuality I observed three types of targets. I saw tentative radar targets which showed up as a (-) symbols. I saw (+) symbols that indicate radar only tracks. I also saw non run length targets which show up as a (.) symbols.

Additionally, I stated the traffic stayed with JL1628 through turns and descent, this information was what I received from JL 1628.



Air Traffic Control Specialist
Anchorage ARTCC

PERSONNEL STATEMENT

FEDERAL AVIATION ADMINISTRATION

Anchorage Air Route Traffic Control Center

The following is a report concerning the incident to aircraft JLI628 on November 18, 1986 at 0230 UTC.

My name is Carl E. Henley (HC) I am employed as an Air Traffic Control Specialist by the Federal Aviation Administration at the Anchorage Air Route Traffic Control Center, Anchorage, Alaska.

During the period of 2030 UTC, November 17, 1986, to 0430 UTC, November 18, 1986 I was on duty in the Anchorage ARTCC. I was working the D15 position from 0156 UTC, November 18, 1986 to 0230 UTC, November 18, 1986.

At approximately 0225Z while monitoring JLI628 on Sector 15 radar, the aircraft requested traffic information. I advised no traffic in his vicinity. The aircraft advised he had traffic 12 o'clock same altitude. I asked JLI628 if he would like higher/lower altitude and the pilot replied, negative. I checked with ROCC to see if they had military traffic in the area and to see if they had primary targets in the area. ROCC did have primary target in the same position JLI628 reported. Several times I had single primary returns where JLI628 reported traffic. JLI628 later requested a turn to heading 210°, I approved JLI628 to make deviations as necessary for traffic. The traffic stayed with JLI628 through turns and decent in the vicinity of FAI I requested JLI628 to make a right 360° turn to see if he could identify the aircraft, he lost contact momentarily, at which time I observed a primary target in the 6 o'clock position 5 miles. I then vectored UA69 northbound to FAI from ANC with his approval to see if he could identify the aircraft, he had contact with the JLI628 flight but reported no other traffic, by this time JLI628 had lost contact with the traffic. Also a military C-130 southbound to EDF from EIL advised he had plenty of fuel and would take a look, I vectored him toward the flight and climbed him to FL240, he also had no contact.

Note: I requested JLI628 to identify the type or markings of the aircraft. He could not identify but reported white and yellow strobes. I requested the JLI628 to say flight conditions, he reported clear and no clouds.



November 19, 1986

INSPECTION AND SURVEILLANCE RECORD

1. WORK ACTIVITY INCIDENT		2. UNITS	3. HOURS
4. NAME AND ADDRESS OF CARRIER, OPERATOR, AIRPORT, AGENCY, OR AIRMAN	5. CERTIFICATE NO. OR AIRCRAFT REGISTRATION MARK (No.)	6. RESULTS	
		7. FURTHER ACTION REQ.	
		SATISFACTORY	NO
		UNSATISFACTORY (Explain in Item 8)	YES (Explain action in Item 8)

8. FINDINGS/RECOMMENDATIONS

J.A.L. B-747 CARGO FLT 1628 FROM ICELAND TO ANCHORAGE. CAPT. KENJU TERAUCHI. SPEED .84 MACH.

I RECEIVED A CALL FROM DICK POWERS CONCERNING A JAL FLT WHICH THE CAPT. HAD STATED HE WAS BEING FOLLOWED OR SHADOWED.

I OBSERVED THE A/C LAND ON R/W 6R AT 1820 HOURS NO OTHER A/C WAS NOTED. THE B-747 TAXIED TO INTL RAMP AREA. I INTERVIEWED CAPT. TERAUCHI & CREW OF TWO (F/O & F/E) THE CAPT. STATED THAT THIS WAS THE 1ST TIME ANYTHING LIKE THIS HAD HAPPENED TO HIM. HE STATED THAT APPROX. 5NM AFTER PASSING THE CANADIAN/ALASKAN BORDER AT 35,000' SOMETHING APPEARED 5 TO 7 NM IN FRONT OF THE A/C IT HAD LIGHTS 4 OR 5 IN A LINE (SEE DRAWINGS) AND HE SAID IT WAS BIGGER THAN THEY WERE (B-747). AT TIMES THIS OBJECT WOULD BE TO THE CAPT SIDE OF THE A/C (LEFT) NEVER THE OTHER SIDE (RIGHT). HE REFERRED TO THE DARK SIDE. - AFTER PASSING THE FAE AREA HE REQUESTED TO FLY PARALLEL TO COURSE AND THIS WAS GRANTED. ~~SEE~~ page 2

(If more space is required, use reverse side)

OPERATIONS	DATE	REGION AND DISTRICT OFFICE	INSPECTOR'S SIGNATURE
MAINTENANCE	11/17/86	AAL-FSDO-63	<i>[Signature]</i>
X AVIONICS			

INSPECTION AND SURVEILLANCE RECORD

1. WORK ACTIVITY		2. UNITS		3. HOURS	
4. NAME AND ADDRESS OF CARRIER, OPERATOR, AIRPORT, AGENCY, OR AIRMAN		5. CERTIFICATE NO. OR AIRCRAFT REGISTRATION MARK (No.)		6. RESULTS	
				7. FURTHER ACTION REQ.	
				Satisfactory	
				NO	
		UNSATISFACTORY (Explain in Item 8)		YES (Explain action in Item 8)	

FINDINGS/RECOMMENDATIONS

Page 2

when he turned to the right and flew parallel the object was gone. [IN ALL CASES the weather RADAR WAS ALSO USED to identify the object. and the 5 to 7 NM distance was taken from the radar display (20NM range)]. They returned to course and the CAPT SAID "There it WAS, AS IF IT WAS WAITING for me." At Approx. TALKETNA Area the object took off to the east and was gone. A UNITED FLT departed from ANC & WAS REQUESTED to check if they could see anything but it was gone before United got there. NOTHING ~~different~~ different WITH the CAPT EXCEPT SOME EXPENSIVE wine. The CAPT. & Crew were shook-up but professional. JAMES DERRY INTERVIEWED THE CREW AT JAL Operations. CAPT. TERAUCHI had asked ATC if they were picking up two targets and was told "just one". THE TOTAL TIME WAS APPROX. 55 MINUTES. A New crew took the flight SA TO TOKYO. CAPT TERAUCHI & crew were to be in

(Page 3)

OPERATIONS		DATE		(If more space is required, use reverse side)	
MAINTENANCE		REGION AND DISTRICT OFFICE		INSPECTOR'S SIGNATURE	
AVIONICS					

INSPECTION AND SURVEILLANCE RECORD

1. WORK ACTIVITY		2. UNITS	3. HOURS
4. NAME AND ADDRESS OF CARRIER, OPERATOR, AIRPORT, AGENCY, OR AIRMAN	5. CERTIFICATE NO. OR AIRCRAFT REGISTRATION MARK (No.)	6. RESULTS	
		7. FURTHER ACTION REQ.	
		☐ SATISFACTORY ☐ UNSATISFACTORY (Explain in Item 8)	☐ NO ☐ YES (Explain action in Item 8)

8. FINDINGS/RECOMMENDATIONS

Anchorage for 3 days before any additional flights.

James Derry requested the tapes AND ANY OTHER INFO be saved.

(If more space is required, use reverse side)

☐ OPERATIONS ☐ MAINTENANCE	DATE	REGION AND DISTRICT OFFICE	INSPECTOR'S SIGNATURE
---	------	----------------------------	-----------------------