

# Electronics Guide










[EN] Make sure all cables and connectors are labeled!


[DE] Alle Kabel und Stecker müssen gekennzeichnet sein!

Laser E001












Coil E003






E004


## Motors







### Infrared Sensor

E005





EN] Sensor has to be aligned with tube end [DE] Sensor muss mit Rohrende bündig sein







#### Laser Door














## Endstops overview




















## Power Connection - Overview

E010






## Power Connection - Detail A




## Power Connection - Detail B




E010

Power Connection - Detail C




### Power Connection - Detail D


E010




## Power Connection - Detail E



#### Power Connection - Detail F





#### Power Connection - Detail G





[EN] Proceed to Hat Assembly Guide (H020).


[DE] Fahren Sie mit der "Hat" Anleitung weiter (H020).















[EN] Proceed with Initial Commisioning Guide (IC01).

[DE] Fahren Sie mit der Initial Commisioning Guide weiter (IC01).



[DE] Diesen Schritt erst nach dem Kalibrieren ausführen [EN]Do this step after Initial Commisioning