

Asbestos Clearance Certificate Inspection

Inspection Date: Wed, 19 Apr 2017

Property Address: 43 Baker St, Oatley NSW 2223, Australia



Contents

The parties

Section A Results of inspection - summary

Section B General

Section C Accessibility

Section D Significant items

Section E Additional comments

Section F Annexures to this report

Definitions to help you better understand this report

Terms on which this report was prepared

Special conditions or instructions

If you have any queries with this report or require further information, please do not hesitate to contact the person who carried out the inspection.

This Report contains reference to material that is the copyright of Standards Australia. That content is reproduced under agreement with SAI Global to Jim's Building Inspections (Australia).

The Parties

Name of Client:	Daniel Woo
Traine of ellerni	
Name of Principal (if applicable):	
Job Address:	43 Baker St, Oatley NSW 2223, Australia
Client's Email Address:	woo.daniel@gmail.com
Client's Phone Number:	
Consultant:	Leon Carnevale Ph: 0451 308 020 Email: fivedock@jimsbuildinginspections.com.au
	HGL7525/HPl5139
Company Name:	Jim's Building Inspections (Five Dock)
Company Address and Postcode:	Botany NSW 2019
Company Email:	fivedock@jimsbuildinginspections.com.au
Company Contact Numbers:	0451 308 020

Special conditions or instructions

A report may be conditional on information provided by the person, agents or employees of the person requesting the report, apparent concealment of possible defects and a range of other factors.

The following apply: - It was noted at the time of inspection that connection to flute was exposed, builder has advised that it will be filled on 20/4/17.

Section A Results of inspection - summary

A summary of your inspection is outlined below; please also refer to the Report.

	Found	Not Found
ACM - Residual Dust - Low Risk		✓
ACM - Residual Dust - High Risk		✓
ACM - Still Present		/

Additional specialist inspections: Not Applicable

In summary the building, compared to others of similar age and construction is in good condition with no identifiable Asbestos (ACM or ACD) suspected to be present.

Section B General

General description of the property

Building Type:	Residential
Number of Storeys:	Double
Main building – floor construction:	N/A
Main building – wall construction:	Full Brick
Main building – roof construction:	Tiled
Other timber building elements:	N/A
Other building elements:	Driveway, Garage
Occupancy status:	Occupied
Furnished:	Furnished
Strata or company title properties:	No
Orientation (to establish the way the property was viewed):	North West
Prevailing weather conditions at the time of inspection:	Fine

Section C Accessibility

Areas Inspected

The following areas were inspected. As documented in your Pre-Inspection Agreement, obstructions and limitations to the accessible areas for inspection are to be expected in any inspection. Refer also to our listing of obstructions and limitations.

- Exterior

The inspection excludes areas which are affected by obstructions or where access is limited or unsafe. We do not move obstructions and the presence of Asbestos or Asbestos Containing Materials or Dust may not be obvious until removed or access provided.

The following areas were inaccessible:

- Not Applicable

Inaccessible areas were excluded from this inspection. Inaccessible areas have not been assessed for the presence of Asbestos or Asbestos Containing Materials Dust. The client is strongly advised to make these areas accessible for re-inspection.

Obstructions and Limitations

Asbestos, Asbestos Containing Materials and / or Asbestos Containing Dust may be concealed by the following obstructions which prevented full inspection:

- Not Applicable

The presence of obstructions increases the risk of undetected Asbestos, Asbestos Containing Materials and Dust. The client should make arrangement to remove obstructions where ever possible and re-inspect these areas as a matter of urgency.

Undetected defect risk

A risk rating is provided to help you understand the degree to which accessibility issues and the presence of obstructions have limited the scope of the inspection.

The risk of undetected defects is: Low

When the risk of undetected defects is high we strongly recommend further inspection once access is provided or if the obstruction can be removed. Contact us for further advice.

Section D Significant Items

ACM - Residual Dust - Low Risk

No evidence was found.

ACM - Residual Dust - High Risk

No evidence was found.

ACM - Still Present

No evidence was found.

D4 Further Inspections

We advise that you seek additional specialist inspections from a qualified and, where appropriate, licensed -

- Not Applicable

Jim's Building Inspections can put you in contact with qualified and licensed providers of these and other trades services. Please contact your inspector for recommendations, or visit www.jims.net.

D5 Conclusion - Assessment of overall condition of property

I affirm that:

- the former enclosure, asbestos removal work area and the surrounding area are free from any visible asbestos
- the clearance certificate is a visual examination only. Although no visible asbestos residue was identified, the certificate is issued on the basis that it applies strictly within the limitations of the examination and does not include any inaccessible areas of the surveyed premises
- it also makes no allowance for the potential existence of asbestos material either as a contaminant of, or buried in the soil
- Jim's Building Inspections accepts no responsibility for unidentified material nor is it liable for any omissions outside the scope of natural visual detection
- the transit route and waste routes are free from any asbestos

- all asbestos in the scope of the removal work has been removed and any known asbestos is intact.

For further information, advice and clarification please contact Leon Carnevale on 0451 308 020

Section E Attachments and Further Comments

The following items were noted as - ACM - Visually Clear

Noted Item

Building: Garage Location: Yard - Side

Finding: Enclosure and surrounding area clear

Information: The area within the enclosure and the area immediately surrounding the enclosure was

inspected and no visible asbestos was found.





Section E Attachments and Further Comments









An opening in flooring or ceiling or other part of a structure (such as service hatch, removable Access hole (cover)

panel) to allow for entry to carry out an inspection, maintenance or repair.

Accessible area An area of the site where sufficient, safe and reasonable access is available to allow inspection

within the scope of the inspection.

Appearance defect Fault or deviation from the intended appearance of a building element.

Asbestos Asbestos means the asbestiform varieties of mineral silicates belonging to the serpentine or amphibole

groups of rock forming minerals including the following:

actinolite asbestos (a)

(b) grunerite (or amosite) asbestos (brown)

and is, or is assumed to be, contaminated with asbestos.

(c) anthophyllite asbestos

(d) chrysotile asbestos (white)

(e) crocidolite asbestos (blue)

(f) tremolite asbestos

(g)a mixture that contains 1 or more of the minerals referred to in paragraphs (a) to (f).

Asbestos Containing Dust or Debris (ACD) Asbestos-contaminated dust or debris (ACD) means dust or debris that has settled within a workplace

Asbestos Containing Material (ACM)

Asbestos containing material (ACM) means any material or thing that, as part of its design, contains asbestos.

Asbestos Related Work

Asbestos-related work means work involving asbestos (other than asbestos removal work) that is permitted under the exceptions set out in regulation 419(3), (4) and (5).

Asbestos Removal Licence

Asbestos removal licence means a Class A asbestos removal licence or a Class B asbestos removal licence under WHS Regulations Chapter 8.

Asbestos Removal

Asbestos removal work means:

Work

- work involving the removal of asbestos or ACM or (a)
- in Part 8.10, Class A asbestos removal work or Class B asbestos removal work. (b)

Asbestos Removalist

Asbestos removalist means a person conducting a business or undertaking who carries out asbestos removal work.

Asbestos Waste

Asbestos waste means asbestos or ACM removed and disposable items used during asbestos removal work including plastic sheeting and disposable tools.

Building and Site

The main building (or main buildings in the case of a building complex) and all timber structures (such as outbuildings, landscaping, retaining walls, fences, bridges, trees, tree stumps and timber embedded in soil) and the land within the property boundaries up to a distance of 50 metres from the main building(s).



Building element Portion of a building that, by itself or in combination with other such parts, fulfils a characteristic

function. NOTE: For example supporting, enclosing, furnishing or servicing building space.

Clearance Certificate Clearance certificate are issued in accordance with Regulation 474. The licensed asbestos assessor

area does not pose a risk to health and safety from exposure to asbestos.

or competent person must ensure that the asbestos removal area does not pose a risk to health and

safety from exposure to asbestos.

Clearance Clearance Inspections are carried out by a licensed asbestos assessor after asbestos removal has been commissioned at a workplace. The licensed assessor must ensure that the asbestos removal

Client The person or other entity for whom the inspection is being carried out.

Competent Person A competent person means: (WHS Regulations) (f) for a clearance is

(f) for a clearance inspection under regulation 473, a person who has acquired through training or experience the knowledge and skills of relevant asbestos removal industry practice and holds:

- (i) a certification in relation to the specified VET course for asbestos assessor work or
- (ii) a tertiary qualification in occupational health and safety, occupational hygiene, science, building, construction or environmental health
- (g) for any other case, a person who has acquired through training, qualification or experience the knowledge and skills to carry out the task.

Defect Fault or deviation from the intended condition of a material, assembly, or component.

Encapsulation (Asbestos)

Encapsulation of Asbestos Containing Materials is a general term for management strategies which may be advised. Depending on the product and location of it encapsulation will usually involve the application of a sealant product. Encapsulation by the use of partitions is not advised or generally allowable. Refer to your Inspector for more advice, encapsulation should always be undertaken by a trained and experienced and where required licensed technician.

Friable Asbestos Friable asbestos means material that:

- (a) is in a powder form or that can be crumbled, pulverised or reduced to a powder by hand pressure when dry and
 - (b) contains asbestos.

In-Situ Asbestos In situ asbestos means asbestos or ACM fixed or installed in a structure, equipment or plant, but does

not include naturally occurring asbestos.

Inspection Close and careful scrutiny of a building carried out without dismantling, in order to arrive at a

reliable conclusion as to the condition of the building.

Inspector Person or organisation responsible for carrying out the inspection.

Licensed Asbestos Licensed asbestos assessor means a person who holds an asbestos assessor licence. Assessor

Licensed Asbestos Removal Work Licensed asbestos removal work means asbestos removal work for which a Class A asbestos removal licence or Class B asbestos removal licence is required.

Licensed Asbestos Removalist Means a person conducting a business or undertaking who is licensed under these Regulations to carry out Class A asbestos removal work or Class B asbestos removal work.

Limitation

Any factor that prevents full or proper inspection of the building.

Major - Asbestos

A Major Defect in the context of an Asbestos Inspection and Condition Report is any Asbestos or ACM which is present in the building, in a poor condition or in a high risk situation. This may include but is not limited to Asbestos or ACM which has a higher probability of airborne fibre release due to age of materials, material deterioration, damage or probability of damage and degree of human interaction with or access to the element.

Membrane Filter Method Membrane filter method means the membrane filter method described in the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres [NOHSC:3003 (2005)].

Minor - Asbestos

Minor in the context of an Asbestos Inspection relates to Asbestos which is found to be present in the building or on the site but that is in comparatively good condition with a low probability of fibre release. For example the Asbestos or ACM could be in a low traffic area, with little probability of interaction or use and is in good, encapsulated or sealed condition.

NATA

NATA means the National Association of Testing Authorities, Australia.

NATA Accredited Laboratory NATA-accredited laboratory means a testing laboratory accredited by NATA, or recognised by NATA either solely or with someone else.

Naturally Occurring Asbestos

Naturally occurring asbestos means the natural geological occurrence of asbestos minerals found in association with geological deposits including rock, sediment or soil.

Non-Friable Asbestos Non-friable asbestos means material containing asbestos that is not friable asbestos, including material containing asbestos fibres reinforced with a bonding compound.

Note: Non-friable asbestos may become friable asbestos through deterioration (see definition of friable asbestos).

Readily Accessible Areas Areas which can be easily and safely inspected without injury to person or property, are up to 3.6 metres above ground or floor levels, in roof spaces where the minimum area of accessibility is not less than 600 mm high by 600 mm wide and subfloor spaces where the minimum area of accessibility is not less than 400 mm high by 600 mm wide, providing the spaces or areas permit entry. The term 'readily accessible' also includes:

- (a) accessible subfloor areas on a sloping site where the minimum clearance is not less than 150 mm high, provided that the areas is not more than 2 metres from a point with conforming clearance (i.e. 400 mm high by 600 mm wide) and
- (b) areas at the eaves of accessible roof spaces, that are within the consultant's unobstructed line of sight and within arm's length from a point with conforming clearance (i.e. 600 mm high by 600 mm wide).

Reasonably Practicable

In the WHS Act, reasonably practicable, in relation to a duty to ensure health and safety, means that which is, or was at a particular time, reasonably able to be done in relation to ensuring health and safety, taking into account and weighing up all relevant matters including:

- (a) the likelihood of the hazard or the risk concerned occurring and
- (b) the degree of harm that might result from the hazard or the risk and
- (c) what the person concerned knows, or ought reasonably to know, about:
- (i) the hazard or the risk and
- (ii) ways of eliminating or minimising the risk and
- (d) the availability and suitability of ways to eliminate or minimise the risk and
- (e) after assessing the extent of the risk and the available ways of eliminating or minimising the risk, the cost associated with available ways of eliminating or minimising the risk, including whether the cost is grossly disproportionate to the risk.

Respirable Asbestos Fibre Respirable asbestos fibre means an asbestos fibre that:

- (a) is less than 3 micrometres wide and
- (b) more than 5 micrometres long and
- (c) has a length to width ratio of more than 3:1.

Roof space Space between the roof covering and the ceiling immediately below the roof covering.

Safety Hazard -Asbestos Asbestos categorised as a safety hazard within the context of an Asbestos Inspection and Condition Report is Asbestos which due to its degraded condition, damage or any other factor in the opinion of the inspector requires immediate and urgent application of management strategies to minimise risk of further airborne fibre release until a more suitable strategy for its removal or encapsulation is made.

Significant item An item that is to be reported in accordance with the scope of the inspection.

Structural defect Fault or deviation from the intended structural performance of a building element.

Structural element Physically distinguishable part of a structure. NOTE: For example wall, columns, beam, connection.

Subfloor space Space between the underside of a suspended floor and the ground.

Terms on which this report was prepared

SERVICE As requested by the Client, the inspection carried out by the Building Inspection Consultant ("the Consultant") was an Asbestos Clearance Inspection and Certificate. This includes an inspections of the site where Asbestos Containing Materials (ACM) were removed or demolished. A Pre-Inspection Agreement was issued prior to service and forms part of the service agreement.

PURPOSE The purpose of this inspection is to provide a person or entity with advice from a competent person regarding the presence or absence of remnant Asbestos, Asbestos Containing Material (ACM) and Asbestos Containing Dust (ACD).

A report may be conditional on the following:

- (a) Information provided by the person or entity requesting the report.
- (b) Apparent concealment of possible ACM.
- (c) Any other factor limiting the preparation of the report.

SCOPE OF INSPECTION The inspection shall comprise visual assessment of the area where asbestos removal work was performed. Visual inspection of the transit route and property and where requested limited sampling to identify Asbestos, ACM and or ACD to form an opinion regarding the presence or absence of Asbestos at the time of inspection. Air monitoring may or may not be included, refer to your inspector for further advice.

The inspection was limited to Readily Accessible Areas of the Building and Site. The Client shall arrange right of entry, facilitate physical entry and supply necessary information to enable the inspector to undertake the inspection, prepare a report and issue a certificate.

The Inspector is not responsible for arranging entry to property or parts of the property, where reasonable access or entry is denied those areas are excluded from and do not form part of the inspection.

The Client is responsible for provision of permissions to take all samples from all sites as reasonably requested by the Inspector. Where permission to take a sample is withheld the Inspector cannot confirm the presence of Asbestos and therefore its presence must be assumed until disproved.

ACCEPTANCE CRITERIA Unless noted in "Special Conditions or Instructions", the site being inspected was compared with a similar site. To the Consultant's knowledge the similar site used for comparison was demolished or partially demolished in accordance with generally accepted practice.

Unless noted in "Special Conditions or Instructions", this Report assumes that the existing use of the site will continue.

EXTENT OF REPORTING

Significant items to be reported are as follows:

- (a) Record the identification of suspected ACM and ACD on the site
- (b) Where sampling or air monitoring is undertaken, confirm the presence of ACM and ACD, and record the level of ACM fibres/mL of air present at the time of inspection.
- (c) Provide general advice regarding management options including suggested removal, remediation and monitoring.

Terms on which this report was prepared

LIMITATIONS

The Client acknowledges:

- 1. That this Report is only a Clearance Certificate but is not otherwise a Certificate of Compliance of the property or site within the requirements of any Act, regulation, ordinance, local law or by-law and is not a warranty against problems developing in the future.
- 2. This Report does not include the inspection and assessment of matters outside the scope of the requested inspection and report.
- 3. The inspection only covered the Readily Accessible Areas of the Building and Site. The inspection did not include areas which were inaccessible, not readily accessible, and unsafe to access or obstructed at the time of inspection.

Obstructions are defined as any condition or physical limitation which inhibits or prevents inspection and may include - but are not limited to ââ¬â building debris, remnant earth and/or soil, other building materials, stored materials on site, and for partial demolition roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, stored articles/materials, insulation, sarking, pipe/duct work, vegetation, pavements or earth.

4. This Report has been produced for the use of the Client. The Consultant or their firm or company are not liable for any reliance placed on this report by any third party.

SAMPLING

The client provides permission for the removal of samples required to confirm the presence of ACM or ACD. This may be in the form of material samples or air sampling. The inspector is not responsible for:

- (a) Securing permissions to take samples
- (b) Facilitating suitable access, which may include the creation of a 10 metre exclusion area at the site of each sample
- (c) Whilst all care will be taken in the removal of the smallest possible sample, any damage to the sample site or surrounding building material, fittings and fixtures is the responsibility of the client. Repairs and reinstatement of the sample site and any associated costs to make safe are excluded from the inspections service.
- (d) Any incidental, accidental or unplanned contamination of the location or inspection site as a result of sampling is the responsibility of the client to rectify.
- (e) General rectification and reinstatement of the sample sites.

EXCLUSIONS

This Report is not an Asbestos Register or Asbestos Management Plan (as required by WHS Regulations). This is a recommended additional service for all workplaces which is available on request.

Labelling of locations with compliant safety notices (as required by WHS Regulations) is also excluded from this service. This is a recommended additional service for all workplaces which is available on request.

An estimate of the costs of rectification or management costs is not required in an inspection report.

The cost to rectify or repair locations of sample sites and any resultant damage is excluded from this service and is the responsibility of the client.

Terms on which this report was prepared

ADDITIONAL COMMENTS

This Report only records the observations and conclusions of the Consultant about the readily observable state of the property at the time of inspection.

If the Client has any doubt about the purpose, scope and acceptance criteria on which this Report was based please discuss your concerns with the Consultant on receipt of this Report.

The Client acknowledges that, unless stated otherwise, the Client as a matter of urgency should implement any recommendation or advice given in this Report.

Privacy Policy:

We value your personal information, we will ensure it is secure and never share or sell your personal details and contact information. We do however use data collected during inspections for research, commercial, training and educational purposes.

For more information please review our Privacy Policy online at www.jimsbuildinginspections.com.au.

Compliments, Complaints and Concerns

Your feedback, both positive and negative, can assist us to improve our services. We encourage you to please contact us with any compliments or concerns directly and as soon as you are able.

The process for managing customer feedback is documented below:

- 1. Contact your inspector directly to provide feedback or make any complaint as soon as you are able.
- 2. If your inspector cannot resolve it or it involves our insurers they will escalate it to their Regional Franchisor (Manager) and / or insurer as applicable.
- 3. You can also contact their Regional Franchisor (Manager) directly on 131 546 ask to speak to your Inspectors Regional Franchisor (Manager) or email info@jimsbuildinginspections.com.au

Should you have any queries about our terms and conditions, the inclusions and exclusions of this report please contact your Inspector.