

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Henry St 71, Kensington
71 Henry St Kensington
Contract No: P3503

Callouts: 22769

Date of Call: 03-01-2019 15:11:57 Time of Arrival: 03-01-2019 15:25:00 Rectification Time: 03-01-2019 16:25:00 Time of Departure: 03-01-2019 16:45:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 1

For Floor(s): 3

Call Description: left hand side lift is stuck on level3

Order Number: 007191

DESCRIPTION OF WORK

Fault Found (CAUSE): Govenor Idler Switch Tripped

Work Action (CORRECTION): See Work description

Work Description: Adjust govenor idler down to releive the swutch

Part Required: No Parts Required

Service Technician Report Customer

Phil Dodsworth yes