

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Toorak Rd 1155, Camberwell
1155 Toorak Rd Camberwell
Contract No: P3192

## Callouts ID: 21990

Date of Call: 15-10-2018 10:59:37 Time of Arrival: 15-10-2018 11:44:00 Rectification Time: 15-10-2018 11:57:00 Time of Departure: 15-10-2018 13:24:00

## CALLOUTS DETAILS

Reported Fault (COMPLAINT): Button/Indicator Not Working

For Lift(s): 1

For Floor(s): 1

Call Description: lift is out of order, no lights are showing on the floor level display above the lift & the light does not stay on the lift call button

Order Number: .

## **DESCRIPTION OF WORK**

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Lift OOO on arrival. Lift disable relay in incorrect position due to PLC lock up. Reset PLC and tested lift for iperstion. Returned to service

Part Required: No Parts Required

Service Technician Report Customer

James Wallace